

Instrument Control Services Pressure Relief Valve Inspection Report

				✓ In Service ☐ Out	of Service 🔲 Cu	st. Stock/Spare	Archive Unknown			
Facility Operator				Facility						
CRC					VENTURA BASIN (VAB)					
Tag ID Equipment #				Description						
PSV-5789C				TORREY (TORREY COMP SKID					
Manufacturer Model #				Serial Number		Shop #				
Hydroseal		BG7MOV00/D0	621901-		▼ N/A					
Inlet Size/Rating	Outlet Size/R	ating	Code	Туре	Service	Capacity	Cap NB Cert			
Size 1.5"	Size	2"	✓ UV	✓ Spring	Liquid	539				
Rating MNPT	Rating	FNPT	☐ Non-coded	Bellows	✓ Gas ☐ Air	✓ SCFN	No			
	Tailing			☐ Pilot☐ Weight	Steam	GPM				
RF RTJ	☐ RF	RTJ		☐ Weight/Pilot	Steam	☐ PPH				
✓ Thrd ☐ Clamp	✓ Thrd	Clamp		_ 0 ,						
Orifice Size	CDTP		Set Point	Back Pressure	Car Seal Off		Car Seal On			
G503			620	✓ N/A	✓ N/A		✓ N/A			
PSV Location/Condition	n Inspection	Poculte			'					
PSV Condition As Found	ii iiispectioii	i itesuits	Inlet Piping As Found		Outlet Pipin	g As Found				
✓ Mfg Tag Attached □ Plugged			✓ Clean □ Plo	✓ Clean						
✓ Clean			☐ Fouled ☐ Pi		Fouled Pipe strain/poor alignment					
☐ Fouled ☐ Block valve failure			Other (See Comn	Other (Other (See Comments)					
Other (See Comments	s)									
As Found Test Results										
Leak Test Pressure 1st Pop Te		st Pressure	Reset Pressure	Test Result		Test Media				
✓ N/A			625	464	✓ Pass		✓ Nitrogen			
		_			Fail		Liquid			
.,			act Duccessure	Daget Dragging		ous Fail Air il if valve relieves:				
If <90% set pressure on a conventional vapor service or pilot valve, or <80% set			est Pressure	Reset Pressure		pressure for valv				
pressure on conventional liquid service			620	464	set >70 psig					
valve, internal inspection required.					>-2 psig for \	>-2 psig for valves set <= 70 psig				
a	0 1111			laanlinaan Canditian	0.4	ahaniaal Canditi				
	s Condition C D E	Test In		leanliness Condition Internal parts show heavy deposits of		chanical Conditi ternal parts are brok				
E 5 1 1 5 5		As	ssess Root Cause B	bvious plugging of nozzle or seat . Internal parts show some heavy, loo			ement or new valve required) evere corrosion, erosion, pitting or			
Average - Same Interval deposits or rust (possibility of obstructing flow galling (significant repair required) Good Increase Interval parts show corresion erosion or pitting										
							eyond normal wear and tear)			
			. Internal parts show thin oily or sticky	/ ct SligI	ht pitting	d condition, only minor lapping				
			○ E	. Internal parts clean		uired	. ,			
As Left Test Results										
Relief Pressure Reset Pressu			re	ssure	ure					
620			464	✓ Pas	ss 🗌 Fai	il				
Comments										

 Technician
 TAYLOR COOK (123)
 Date
 8/8/2019



Disc Seat Step

Spindle

Disc Back Face To Seat

Instrument Control Services Pressure Relief Valve Inspection Report

eardown Inspection	Result											
Component	N/A	Clean	Dirty	Plugged	Damaged	La	эр	Machine	Comments			
Mfg Tag									Missing	lllegible	□ ок	
Inlet												
Outlet												
Nozzle												
Nozzle Ring												
Disc Insert												
Disc Holder												
Spring/Washer Assy.												
Guide												
Guide Ring												
Spindle												
Bellows												
Bonnet/Body												
Soft Goods												
Comp Screw/Jam Nut												
Cap/Lift Lever												
Spring Identification (Old)	PN	PN		Color Code	Color Code Wir		Wire Size		Range			
Spring Identification (New) N/A	PN	PN			Color Code W		Wire Size		Range			
nspection Measurer	nents											
Component	As Found				As Left			PSV Condition Comment				
Nozzle Ring												
Nozzle Seat Step												
Nozzle Face to Seat							Inle	et Comment				
Nozzle Seat	OD	ID		OD	ID							
Guide Ring												

Outlet Comment

Technician	()	Date