PRESSURE VESSEL INSPECTION REPORT

Rev. 4 ite: October 24, 2008

		104 5	KHIK	××		Fage 1	
Company: Enerplus			Date: MAY 19/10				
Facility: Miry Bay			LSD: 16-24-21-19W3M				
Company Vessel Identification #	: Enerplus 49331	11 12 12 12					
VESSEL DATA							
Description: Horizontal Inlet Separator North			Manufacturer: Platinum				
Mfg. Date: 2005			NB: A 539069				
Serial #: 15148-01			CRN#: R 4923.213				
Diameter: 4'			Length: 10'				
Unit #:			Insp. Method: External 🖂 Internal 🖂				
MAWP Shell: 720		Cc	⊠ F □ F	⊠F MDMT C□ F□ @ MDM □ PC □			
PSV INFORMATION	□ N/A		2 ND P	SV .			
Manufacturer: Taylor	Location: 🖾T 🗀S 🗀 P		Manufacturer:			Location: T S P	
Serial #: 24264-58	CRN #: OG1316.2C		Serial #:			CRN #:	
Madel #: T-8200-2	PSV #: TR 9574		Model #:			PSV #:	
Set Pressure: 720 psi	Capacity: 5486 SCFM		Set Pressure:			Capacity:	
Inlet Size: 2"	Outlet Size: 2"		Inlet Size:			Outlet Size:	
Last Service: 09/15/2009 Service Interval: 3 years		ears	Last Service:			Service Interval:	
Company Ident.#: E 49335			Company Ident.#:				
VESSEL MATERIAL AND THICKN	ESS						
Head Thickness:		Material:			C	.A.:	
Head Thickness:		Material:	F		R	R.T.:	
Shell Thickness:		Material:			н	HT:	
Is Vessel Gounded Is Vessel Secured/Bolted Down Nameplate Secure Nameplate Legible Ladders/Handrail/Walkway Damage Vessel Fit for Service Vessel Requires Repair Future Action Required		See Com	CANADAM SANCTAND SAN	□ N/A □ N/A □ N/A		See Attached Pictures	
PECTION REQUESTED BY: G Zinger		INSPECTION PERFORMED BY: Cory Sasyniuk					

^{*} Cory Sasyniuk PEI Class No. 49 WEx No. 12 NBIC No. 12642 API 510 No. 28371 API 570 No. 32058 ** Neil Pinkney PEI Class No. 47 WEx No. 13 NBIC No. 12641 API 510 No. 38370 API 570 No. 31457

ESSURE VESSEL INSPECTION REPORT

Page | 2

EXTERNAL VISUAL INSPECTION

ACCESS & COVERAGE		SUPPORTS				
Manway/Access Size: 20"		Vessel Has Skirt	Legs	□ N/A		
Coating: Disbonded Blistered		Insulation Good Poor				
□ N/A □ Poor Cleaning □ Adequately Clean □ Peeling		Good Condition Cracked Bolts Missing/Loose/ Damaged Support Ring Damage Skirt Access		☐ Distorted☐ Broken		
SHELL		NOZZLES .				
	Scale	ed – Light ed – Severe	N/A Good Condition Scaled Poor Welding Seal Face Corrosion Internal Corrosion		☐ Cracked ☐ Plugged ☐ Leaking ☐ Bolts Missing/Loose/ Damaged	
HEAD			HEAD			
☐ Top ☐ North ☐ West ☐ N/A		☐ Bottom ☐ South ☐ East ☐ N/A				
□ Good Condition □ Pitted – Light □ Scaled – Light □ External coating	☐ External Corrosion ☐ Pitted – Severe ☐ Scaled - Heavy		□ Good Condition □ Pitted – Light □ Scaled – Light □ External Coating		☐ External Corrosion ☐ Pitted – Severe ☐ Scaled - Heavy	
EXTERNAL PIPING						
External Piping Cladding/Insulation Supports Coating	□ N/A □ N/A □ N/A □ N/A	☐ Good Condition ☐ Good Condition ☐ Good Condition ☐ Good Condition	Leaks Dents/Holes Missing/Stress Chipped/Missing		mments mments	See Comments See Comments

PRESSURE VESSEL INSPECTION REPORT

Rev. 4

Page 3

INTERNAL VISUAL INSPECTION

INTERNAL PROTECTION		ANODES			
N/A Good Condition Blistered – Light Disbonded Mechanical Damage	Coating Holidays Blistered – Severe Chipped/Peeling Mechanically Remove or Sandblasted	⊠N/A □ Dirty □ New/Replaced □ Bonding Cable Attached	Good Condition Consumed% Missing		
DEMISTER SCREEN		MANWAY			
□ N/A □ Dislodged ☑ Missing	Good Condition Broken Fowled%	☐ N/A ☐ Coating Damage ☐ Mechanical Damage ☐ Bolts Missing/Loose			
FIRETUBES		TRAYS			
N/A		N/A Collapsed Loose Wear Poor	Good Distorted Missing Corrosion		
SHELL		VESSEL INTERNALS			
N/A ☐ Internal Corrosion Good Condition ☐ Pitted – Severe ☐ Pitted – Light ☐ Scaled - Heavy ☐ Scaled - Light		□ N/A □ Weir/Baffle/Divider Damage □ Downcomer Corrosion □ Spray Nozzle Damaged/Missing			
☐ Blistered ☐ MPI/UT ☐ To Follow		See Comments			
HEAD		HEAD			
☐ Top ☐ North ☑ West ☐ N/A		☐ Bottom ☐ South ☐ East ☐ N/A			
☐ Good Condition ☐ Pitted – Light ☐ Scaled – Light ☐ Internal Corrosion ☐ Pitted – Severe ☐ Scaled - Heavy ☐ Internal Coating		☐ Good Condition ☐ Pitted – Light ☐ Scaled – Light ☐ Internal Coating	☐ Internal Corrosion ☐ Pitted – Severe ☐ Scaled - Heavy		
INTERNAL PIPING					
ınternal Piping: N/A Good Condition Corrosion Missing/Dents Supports See Comments					

^{*} Cory Sasyniuk

PEI Class No. 49 WEx No. 12 NBIC No. 12642 API 510 No. 28371 API 570 No. 32058

^{**} Neil Pinkney



PRESSURE VESSEL INSPECTION REPORT

Rev. 4 Date: October 24, 2008

Pagel 4

INTERNAL VISUAL INSPECTION DETAILED OBSERVATIONS (Inspection Notes)

Manway entry into vessel is in good condition with no indications of corrosion or pitting visible throughout. Head dish, knuckle and straight flange are in as new condition with indications of mil scale visible throughout base metal surface. No further indications of deterioration visible throughout. Head to shell transitional circ weld is even and uniform with adequate weld reinforcement visible internally.

1st Course - 1st course is in good condition with no indications of pitting or corrosion present. Indications of scaling are visible on shell surfaces in the lower hemisphere of vessel. Inlet nozzle installed in vessel appears to be in good condition with no concerns or issues present. Perforated 1/2 baffle installed in 1st course is bolted in and can be removed for inspection purposes. 3" drain installed in course section is in good condition and there is no indications of deterioration present. Long seam in course shell section is in as new condition as well with adequate weld reinforcement visible throughout. PSV nozzle is in as new condition with adequate weld reinforcement present. No indications of undercut or cold lap are present throughout 1st course of shell. Course 1 to course 2 transitional circ weld is even and uniform. Fit-up between courses are within tolerance of Code. No indications of weld metal deterioration present at this time.

2nd Course - Sample collars installed in south exposure of vessel are in as new condition with adequate weld reinforcement visible internally. Nozzles are adequately clean with no evidence of fowling present at this time. 3" drain installed in course section is in as new condition with no evidence of fowling or pitting visible at this time. Long seam in course section has indications of weld inforcement that is currently at wall thickness. No concerns or issues present at this time with weld detail. Gas demister is rently removed from vessel for service. Discharge nozzle appears to be in good condition with no indications of internal corrosion present. Head to shell transitional circ weld is in as new condition with no evidence of deterioration visible. Dish, knuckle and straight flange of east head is in good condition with evidence of mil scale visible on internal surfaces. No further degredation is present in the form of corrosion or pitting.

RECOMMENDATIONS

Recommend vessel be returned to service and possible replacement of demister pad is required for service.

EXTERNAL VISUAL INSPECTION DETAILED OBSERVATIONS (Inspection Notes)

Vessel is adequately supported on steel skid structure with no indications of listing or leaning and has been secured by bolting. Exterior of vessel is protected with paint, though indications of deterioration from prior are present that have been mitigated with further application of coating. Primary piping for vessel is welded construction, while secondary piping is threaded. All piping joint connections appear tight with no indications of leakage visible at this time. Piping is adequately supported throughout steel skid octure with no concerns or issues present at this time. No evidence of short bolting visible throughout jointed connections. Piping adequately protected with paint with no signs of degredation at this time.

PRESSURE VESSEL INSPECTION REPORT

Rev. 4

	Page 5
RECOMMENDATIONS	
PICTURES	