



4253-97 Street, Edmonton AB, T6E 5Y7 Tel.: (780) 417-0340 Fax: (780) 417-0348 www.integrity-testing.com

## **EQUIPMENT EXTERNAL INSPECTION REPORT**

<b>Customer:</b>	Abbey Resources Corp.		ITS Job	<b>No.:</b> 2-3703	2-3703		
District:	Shackleton			Date:	12-Apr-2017	7	
Facility:	Shackleton Compressor Station LS			LSD:	14-36-020-19W3N	V3M	
Equip. Description:	Inlet Separator			Serial N	<b>v.:</b> WF03.1272	<u>-</u>	
Equip./OIP No.:		Not Stated	PRN:		S05259/A0491789	789	
<b>Equip. Type:</b> Column Cooler I	Exchanger 🗌 Furn	ace Heater Pla	te Exchanger Reboile	er 🗸 Vessel 🔲	Other:		
Remedial Action	Se	rvice	Associated Co	mponents	Shell		
■ No Action Required	✓ Sweet	☐ Sour	▼ Y □ N: Name P	late Secure	✓ Good Condition		
☐ Paint/Coating Repairs	Access ar	nd Coverage	✓ Y □ N: Name P	late Legible	□ External Corrosion		
☐ Insulation Repairs	External Ir	spection	External Groundi	ng	☐ Pitting:	(max depth)	
☐ PSV Service Required	☐ Part. Exter	nal Inspection Direct Indirect N		ect 🗆 N	☐ Scale		
▼ Further Assessment	✓ Internal In	Internal Inspection (VI)		addors/	□ Blistered		
Required	NDE Examina	ation	☐ Y ☐ N ☑ NA: L Handrail/ Walkwa	ay/ Grating	☐ Mechanical Damage		
☐ Condition Damage	<b></b> ✓ UT		in safe condition?		☐ Deformation/Distortion		
☐ Does not comply with	□МТ		✓ See Attached	Pictures	☐ Condensation/Sweatin	ating	
applicable code/safe operating requirement.	☐ PT		☐ Excessive Vibr	ation	☐ No Access		
Repairs Required	□ RT		✓ Y □ N □ NA: Pressure		☐ No Access Insulated	☐ No Access Insulated	
✓ See Comments	□ВН		Gauge within MA	WP	☐ No Access Ice Build Up	l Up	
Status	☐ Other		✓ Y □ N □ NA: Temp.		✓ Weld(s) in Good Condi	ndition	
☐ Operational; ☑ Idle;	✓ See Comments		Gauge within MDMT		☐ Weld(s) Corroded		
☐ Shut In; ☐ New Install;			Y N Attached Piping		☐ Weld(s) Poor Quality		
☐ Surplus/Boneyard;			and Instrumentation in Good Condition		□ Weld(s) Cracked		
☐ Other:			☐ See Comments		☐ See Comments		
			<u> </u>				
Head (1)			Head (2)		Nozzles		
☐ Top ☐ North	<b>✓</b> West	Bottom	South	<b>✓</b> East	✓ RF □ RTJ □ NPT		
☐ Flat ☐ FLG ☑ ELL ☐ EC	CC HEMI	☐ Flat ☐ FLG		☐ HEMI	Good Condition		
Quick Actuating Closure		Quick Actua			Fasteners Engaged		
✓ Good Condition		Good Condition		Repad Weep Holes Clear			
External Corrosion	(may	External Corrosion			Nozzles are Gusseted		
☐ Pitting:	depth)	☐ Pitting:		(max depth)	External Corrosion		
Scale		Scale			Leaking/Weeping		
☐ Blistered		☐ Blistered	D		☐ Damaged/Cracked		
Mechanical Damage		Mechanical Damage		Bolts Missing/Loose			
Deformation/Distortion		Deformation/Distortion			Deflection/Distortion		
Condensation/Sweating		Condensation/Sweating			Partial Internal Inspection		
No Access		□ No Access			No Access Insulated		
No Access Insulated		□ No Access Insulated			Weld(s) in Good Condition		
No Access Ice Build Up		No Access Ice Build Up		Weld(s) Corroded			
External Protection Only		External Protection Only		Weld(s) Poor Quality			
☐ See Comments		☐ See Comme	nts		☐ Weld(s) Cracked		
					✓ See Comments		





4253-97 Street, Edmonton AB, T6E 5Y7
Tel.: (780) 417-0340
Fax: (780) 417-0348
www.integrity-testing.com

<b>External Surface</b>	Supports	<b>Associated Piping</b>	PRD 1	PRD 2				
✓ Good Condition	✓ Good Condition	✓ Good Condition	Location: Piping	Location: Not Applicable				
✓ Painted ✓ Full ☐ Part.	✓ Anchor Bolts	☐ Corrosion	PSV Tag No.: PSV-100	PSV Tag No.:				
Coated Full Part.	Secure	Pitting: (max depth)	✓ Service Date within	☐ Service Date within				
☐ Insulated ☐ Full ☐ Part.	☐ Welded to Skid	☐ Bolts Missing/	Interval	Interval				
☐ Insulation Damaged	☐ Supported by	Loose/ Damaged	✓ Set Pressure within	☐ Set Pressure within				
☐ Penetration Seals	Nozzle(s)	Short Threaded	MAWP	MAWP				
Broken	☐ Piping Supported	☐ Valves leaking	✓ Safety Seal Intact	☐ Safety Seal Intact				
☐ Corrosion Under Insulation (CUI)	Expansion Slots	☐ Connections	✓ Service Seal Intact	Service Seal Intact				
	☐ Bolts Missing/ Loose/ Damaged	Leaking	✓ Current Service Tag Attached	Current Service Tag Attached				
☐ Visible Moisture Contamination	☐ Short Threaded	✓ Piping and Valves	☐ PSV inlet Gusseted	☐ PSV inlet Gusseted				
☐ Paint Deterioration	☐ Deflected/Distorted	Supported	☐ Inlet Block Valve	☐ Inlet Block Valve				
☐ Coating		Piping Deflected/	Locked Open 🔲 Y 🔲 N	Locked Open P Y N				
Deterioration	☐ Poor Insulation	Distorted	Sealed Open Y N	Sealed Open Y N				
☐ Fireproofing Cracked	☐ Fire Proofing	☐ No Access	☐ Outlet Block Valve	Outlet Block Valve				
	Cracked	Insulated	Locked Open 🔲 Y 🔲 N	Locked Open Y N				
☐ External Protection	☐ Vessel is level	See Comments	· .	Sealed Open Y N				
Only	See Comments		See Comments	☐ See Comments				
See Comments								
Observations:								
	od, 🗹 Fair, <u>or</u> 🗌 Poor		on ADI 510 Visual Ext	ornal Inspection this				
Good: No concerns found (may still have recommendations)  Fair: Minor issues found that do not impair the "fitness for service" of the equipment, (paint deterioration, general external surface corrosion - no measurable metal loss, not mounted to skid, etc.)  Poor: Equipment had moderate to major concerns found (equipment is damaged, severe external corrosion noted, cracked or broken component, etc.)  Based on API 510 Visual External Inspection th vessel is fit for service  (This piece of equipment meets the Jurisdictional requirements based on the information available at the time of the inspection.)								
- The vessel is fully painted The outlet 8" flange has some short threaded studs TML#50 was found with a low reading of 6.2mm.								
Recommendations								
- Repair the short threaded studs Monitor TML#50 in 6 months to determine the corrosion rate.								
Non-Conformance Conditions and Corrective Actions:  Note: Reference any and all Non-Conformance Report (NCR) numbers and Corrective Action Report (CAR) numbers.								
- None								
Recommended Inspection Intervals:								
Recommended		PRD 1	PRD	2				
Maximum Inspection Interval:		ccommended 36 vice Interval:		ed Not Applicable Months				

4253-97 Street, Edmonton AB, T6E 5Y7 Tel.: (780) 417-0340 Fax: (780) 417-0348 www.integrity-testing.com



## **Pictures:**



Photo 1: LSD Sign



Photo 2: Short Studs



Photo 3: PSV Overview



Photo 4: PSV Nameplate



Photo 5: PSV Service Tag

Report No.: VE-2-3703-03-JDK



4253-97 Street, Edmonton AB, T6E 5Y7
Tel.: (780) 417-0340
Fax: (780) 417-0348
www.integrity-testing.com

External Inspectio	on Performed By:		ABSA IBPV PESL: 274 NB IS Comm.: 15019 API 510: 28139 API 570: 29975 PEI Class 1: 169	
Print Name:	John David Kobelsky	Certification No.:		
Signature:			Report Reviewed:	Initial
Chief Inspector / Client Representative:	Name (Print)	Signature	Dat	te: