




4253-97 Street, Edmonton AB, T6E 5Y7 Tel.: (780) 417-0340 Fax: (780) 417-0348 www.integrity-testing.com

EQUIPMENT EXTERNAL INSPECTION REPORT

Customer:	TAQA North ITS Jo			ITS Job	No.: 1-2968		
District:	North Area Date:			Date:	18-Oct-2014		
Facility:	Chinchaga Gas Plant LSD:			C-032-H/094-H-08			
Equip. Description:				Serial N	lo.: 393508		
Equip./OIP No.:		603VP005		PRN:	A0601541		
Equip. Type: □Column □Cooler □Exchanger □Furnace □Heater □Plate Exchanger □Reboiler ② Vessel □Other:							
Remedial Action	Se	rvice	Associated Co	mponents	Shell		
■ No Action Required	✓ Sweet	☐ Sour	▼ Y □ N: Name P	late Secure	Good Condition		
□ Paint/Coating Repairs	Access an	d Coverage	▼ Y □ N: Name P	late Legible	External Corrosion		
☐ Insulation Repairs	External In	spection	External Groundi	ng	☐ Pitting: (max depth)	()	
☐ PSV Service Required	☐ Part. Exter	Part. External Inspection 📝 Direct 🗆 Indirect 🗆 N		ect 🗆 N	☐ Scale		
▼ Further Assessment	☐ Internal Inspection (VI)		▼Y□N□NA: Ladders/ Handrail/ Walkway/ Grating		☐ Blistered		
Required	NDE Examination				■ Mechanical Damage		
☐ Condition Damage	 ✓ UT		in safe condition?		■ Deformation/Distortion		
✓ Does not comply with	□МТ		☐ See Attached	Pictures	☐ Condensation/Sweating		
applicable code/safe operating requirement.	□ PT		☐ Excessive Vibr	ation	☐ No Access		
Repairs Required	□ RT		▼Y□N□NA: F	ressure	☐ No Access Insulated		
✓ See Comments	□ВН		Gauge within MA		☐ No Access Ice Build Up		
Status	☐ Other		☐ Y ☐ N ✔ NA: Temp. Gauge within MDMT		✓ Weld(s) in Good Conditio	n	
✓ Operational; ☐ Idle;	☐ See Comments				☐ Weld(s) Corroded		
Shut In;			✓ Y □ N Attached Piping and Instrumentation in Good Condition		☐ Weld(s) Poor Quality		
☐ Surplus/Boneyard;					□ Weld(s) Cracked		
Other:			☐ See Comment	S	☐ See Comments		
Head (1)			Head (2)	- ·	Nozzles		
☐ Top ☐ North	✓ West	Bottom	South	✓ East	RF RTJ NPT		
Flat FLG ELL E	C M HEMI	☐ Flat ☐ FLG		✓ HEMI	Good Condition	_	
Quick Actuating Closure		Quick Actua			Fasteners Engaged	_	
✓ Good Condition		✓ Good Condi			Repad Weep Holes Clear		
External Corrosion	(max	External Co	rosion	(max	Nozzles are Gusseted	_	
☐ Pitting:	depth)	☐ Pitting:		depth)	External Corrosion		
Scale		Scale			Leaking/Weeping		
Blistered		Blistered			□ Damaged/Cracked		
Mechanical Damage		Mechanical Damage			Bolts Missing/Loose		
□ Deformation/Distortion		Deformation/Distortion			Deflection/Distortion	_	
☐ Condensation/Sweating		☐ Condensation/Sweating			Partial Internal Inspection		
□ No Access		□ No Access			No Access Insulated	_	
□ No Access Insulated					Weld(s) in Good Condition	l	
☐ No Access Ice Build Up		No Access Ice Build Up			Weld(s) Corroded	_	
External Protection Only		External Protection Only			☐ Weld(s) Poor Quality		
See Comments		✓ See Comme	nts		☐ Weld(s) Cracked		
					✓ See Comments		





4253-97 Street, Edmonton AB, T6E 5Y7 Tel.: (780) 417-0340 Fax: (780) 417-0348 www.integrity-testing.com

External Surface	Supports	Associated Piping	PRD 1	PRD 2			
✓ Good Condition	✓ Good Condition	✓ Good Condition	Location: top east on vessel	Location: Not Applicable			
✓ Painted ✓ Full ☐ Part.	✓ Anchor Bolts	☐ Corrosion	PSV Tag No.: 603SVVP005	PSV Tag No.: Not Applicable			
☐ Coated ☐ Full ☐ Part.	Secure	Pitting: (max depth)	✓ Service Date within	Service Date within Interval			
☐ Insulated ☐ Full ☐ Part.	☐ Welded to Skid	☐ Bolts Missing/	Interval				
☐ Insulation Damaged ☐ Penetration Seals	☐ Supported by Nozzle(s)	Loose/ Damaged Short Threaded	Set Pressure within MAWP	☐ Set Pressure within MAWP			
Broken	✓ Piping Supported	☐ Valves leaking	✓ Safety Seal Intact	☐ Safety Seal Intact			
Corrosion Under	☐ Expansion Slots		✓ Service Seal Intact	☐ Service Seal Intact			
Insulation (CUI)	☐ Bolts Missing/ Loose/ Damaged	☐ Connections Leaking	✓ Current Service Tag Attached	☐ Current Service Tag Attached			
☐ Visible Moisture Contamination	Short Threaded	✓ Piping and Valves	☐ PSV inlet Gusseted	☐ PSV inlet Gusseted			
☐ Paint Deterioration	☐ Deflected/Distorted	Supported	✓ Inlet Block Valve	☐ Inlet Block Valve			
☐ Coating	Deflected/Distorted	☐ Piping Deflected/	Locked Open 🗌 Y 🗹 N	Locked Open			
Deterioration	☐ Poor Insulation	Distorted	Sealed Open 🕢 Y 🗆 N	Sealed Open Y N			
☐ Fireproofing	☐ Fire Proofing	☐ No Access	Outlet Block Valve	Outlet Block Valve			
Cracked	Cracked	Insulated	Locked Open	Locked Open			
☐ External Protection	✓ Vessel is level	☐ See Comments	Sealed Open Y N	Sealed Open Y N			
Only	☐ See Comments		✓ See Comments	☐ See Comments			
☐ See Comments							
Observations:							
Equipment in Good, Fair, or Poor Condition Good: No concerns found (may still have recommendations) Fair: Minor issues found that do not impair the "fitness for service" of the equipment, (paint deterioration, general external surface corrosion - no measurable metal loss, not mounted to skid, etc.) Poor: Equipment had moderate to major concerns found (equipment is damaged, severe external corrosion noted, cracked or broken component, etc.)							
No access to PSV. PSV information obtained from TAQA records. Limited access to top of vessel. Ladder and grating on West side of vessel only. The vessel and PSV do not have a CRN on the nameplates. According to CSA B51 all vessels and 0G fittings must have the CRN stamped into the nameplate and must be registered in the province they are operating in.							
Recommendations:							
Verify the vessel and PSV designs are registered for use in BC, if they are then have nameplates made up with the CRNs, if they are not than remove the equipment from service.							
Non-Conformance Conditions and Corrective Actions: Note: Reference any and all Non-Conformance Report (NCR) numbers and Corrective Action Report (CAR) numbers.							
None							
Recommended Inspection Intervals:							
Recommended Maximum Inspection	60 Months Re	PRD 1 ecommended 60	PRD Months Recommende	2 Not Applicable _{Months}			

Interval:

Service Interval:

Service Interval:



VE-1-2968-24-MAM

4253-97 Street, Edmonton AB, T6E 5Y7 Tel.: (780) 417-0340 Fax: (780) 417-0348 www.integrity-testing.com



External Inspection	on Performed By:		ABSA IPV PESL: 000622 API 510: 40801	
Print Name:	Murray Angus MacGregor	Certification No.:	API 653: 48515 PEI Class 2: 158 CWB Level 2: 8501	
Signature:	Ilaff)		Report Reviewed:	
Chief Inspector / Client Representative:	Name (Print)	Signature	Date:	