EQUIPMENT EXTERNAL INSPECTION REPORT

Customer:	TAQA North	ITS Job No.:	1-4012
District:	North Area	Date:	09-Jul-2018
Facility:	Chinchaga Gas Plant	LSD:	C-032-H/094-H-08
Equip. Description:	BC #1 Inlet Separator	Serial No.:	7723-03
Equip./OIP No.:	603VS006	PRN:	Not Stated

Equip. Type: Column Cooler Exchanger Furnace Heater Plate Exchanger Reboiler Vessel Other:

Remedial Action	Service	Associated Components	Shell	
No Action Required	🖌 Sweet 🛛 🗌 Sour	🖌 Y 🗌 N: Name Plate Secure	Good Condition	
Paint/Coating Repairs	Access and Coverage	🖌 Y 🗌 N: Name Plate Legible	External Corrosion	
Insulation Repairs	External Inspection	External Grounding	Pitting: (max depth)	
PSV Service Required			Scale	
Further Assessment	Internal Inspection (VI)	🛛 🖌 Y 🔲 N 🔲 NA: Ladders/	Blistered	
Required	NDE Examination	Handrail/ Walkway/ Grating	Mechanical Damage	
Condition Damage	ition Damage 🛛 🕢 UT		Deformation/Distortion	
Does not comply with			Condensation/Sweating	
applicable code/safe operating requirement.	D PT	Excessive Vibration	No Access	
Repairs Required	🗆 RT	🖌 Y 🗌 N 🗌 NA: Pressure	No Access Insulated	
See Comments	BH	Gauge within MAWP	No Access Ice Build Up	
Status	🗆 Other	🗆 Y 🗹 N 🔲 NA: Temp.	Weld(s) in Good Condition	
🗹 Operational; 🗌 Idle;	See Comments	Gauge within MDMT	Weld(s) Corroded	
🗆 Shut In; 🗌 New Install;		Y D N Attached Piping and Instrumentation in Good	Weld(s) Poor Quality	
Surplus/Boneyard;	Surplus/Boneyard;		Weld(s) Cracked	
Other:		See Comments	See Comments	

Head (1)	Head (2)	Nozzles	
🗆 Top 🛛 🗹 North 🖉 West	🗌 Bottom 🔍 South 📃 East	🗹 RF 🗔 RTJ 🗔 NPT	
🔲 Flat 🔲 FLG 🕢 ELL 🗌 ECC 🛄 HEMI 🛄 Other	🔲 Flat 🛄 FLG 🕢 ELL 🛄 ECC 🛄 HEMI 🛄 Other	Good Condition	
Quick Open Closure	🔲 Quick Open Closure	Fasteners Engaged	
Quick Actuating Closure	Quick Actuating Closure	Repad Weep Holes Clear	
Good Condition	Good Condition	Nozzles are Gusseted	
External Corrosion	External Corrosion	External Corrosion	
Pitting: (max depth)	Pitting: (max depth)	Leaking/Weeping	
□ Scale	Scale	Damaged/Cracked	
Blistered	Blistered	Bolts Missing/Loose	
Mechanical Damage	Mechanical Damage	Deflection/Distortion	
Deformation/Distortion	Deformation/Distortion	Partial Internal Inspection	
Condensation/Sweating	Condensation/Sweating	No Access Insulated	
No Access	🗆 No Access	Weld(s) in Good Condition	
☑ No Access Insulated	No Access Insulated	Ueld(s) Corroded	
No Access Ice Build Up	No Access Ice Build Up	U Weld(s) Poor Quality	
External Protection Only	External Protection Only	Uweld(s) Cracked	
See Comments	See Comments	See Comments	

Report No.: VE-1-4012-03-CRE



4340 - 97 Street, Edmonton AB, T6E 5R9 Tel.: (780) 417-0340 Fax: (780) 417-0348 www.integrity-testing.com

External Surface	Supports	Associated Piping	PRD 1	PRD 2	
Good Condition	Good Condition	Good Condition	Location: Shell	Location: Not Applicable	
🗹 Painted 🗹 Full 🗌 Part.		Corrosion	PSV Tag No.: 603SVVS006	PSV Tag No.: Not Applicable	
Coated Full Part.	Secure	Pitting: (max depth)	Service Date within	Service Date within	
🗌 Insulated 🔲 Full 🗌 Part.	Welded to Skid	Bolts Missing/	Interval	Interval	
Insulation Damaged	Supported by	Loose/ Damaged	Set Pressure within	Set Pressure within	
Penetration Seals	Nozzle(s)	Short Bolting	MAWP	MAWP	
Broken	Piping Supported	Valves leaking	🖌 Safety Seal Intact	Safety Seal Intact	
Corrosion Under	Expansion Slots		Service Seal Intact	Service Seal Intact	
Insulation (CUI)	Bolts Missing/ Loose/ Damaged	Connections Leaking	Current Service Tag Attached	Current Service Tag Attached	
Visible Moisture Contamination	Short Bolting	Piping and Valves	PSV inlet Gusseted	PSV inlet Gusseted	
Paint Deterioration		Supported	Inlet Block Valve	Inlet Block Valve	
Coating Deterioration	Deflected/Distorted	Piping Deflected/	Locked Open 🔲 Y 🗌 N	Locked Open 🔲 Y 🗌 N	
	Poor Insulation	Distorted	Sealed Open 🔲 Y 🗌 N	Sealed Open 🔲 Y 🗌 N	
Fireproofing	Fire Proofing	No Access	Outlet Block Valve	Outlet Block Valve	
Cracked	Cracked	Insulated	Locked Open 🔲 Y 🗌 N	Locked Open 🔲 Y 🗌 N	
External Protection	Vessel is level	See Comments	Sealed Open 🔲 Y 🗌 N	Sealed Open 🔲 Y 🗌 N	
Only	See Comments		See Comments	See Comments	
See Comments					

Observations:

Equipment in 🗹 Good, 🗌 Fair, <u>or</u> 🗌 Poor Condition

<u>Good</u>: No concerns found (may still have recommendations) <u>Fair</u>: Minor issues found that do not impair the "fitness for service" of the equipment, (paint deterioration, general external surface corrosion - no measurable metal loss, not mounted to skid, etc.) <u>Poor</u>: Equipment had moderate to major concerns found (equipment is damaged, severe external corrosion noted, cracked or broken component, etc.)

- Vessel is in good condition.

- Paint is in good condition.
- No access to the North head due to external insulation.
- Saran wrap noted on associated flanged connections.
- Weep noted on the South bridle top flanged head. (Appears old)
- Low UT reading found on CML 34 (3" 90 degree drain elbow) nominal thickness 5.5mm / 4.8mm.

Lowest UT reading found 4.1mm. Suspected internal isolated pitting.

- A UT repeat examination was also performed (externally) on the isolated internal pitting found in 2012.
- No change in thickness found. See attached UT report.

Recommendation	ons:
----------------	------

- Monitor the low UT reading found on CML 34 (3" 90 degree drain elbow).
- Remove the saran wrap from the associated flanged connections.

- Remove dried product from the vessel and associated components.

Non-Conformance Conditions and Corrective Actions:

Note: Reference any and all Non-Conformance Report (NCR) numbers and Corrective Action Report (CAR) numbers.

- None.

✓ Based on API 510 Visual External Inspection this vessel is fit for service
(This piece of equipment the lucidictical requirements based on the

(This piece of equipment meets the Jurisdictional requirements based on the information available at the time of the inspection.)



Recommended Inspection Intervals:							
	Recommended Maximum Inspection Interval:	60	Months	PRD 1 Recommended Service Interval:	60	Months	PRD 2 Recommended Not Applicable Months Service Interval:

Pictures:



Associated Flange connection overview

External Inspecti	on Performed By:		ABSA IPV PES	L: 000782	
Print Name:	Christopher Russell Earl	Certification No.:	API 510: 45377		
Signature: 	7. Jun		Report Reviewed:	HO . Initial	
Chief Inspector / Client Representative:	Name (Print)	Signature)ate:	