EQUIPMENT NO: 603FB001 RAMS ID: 433815

Facility: PLT/c-032-H/094-H-08

Equipment Name:Heat Medium Boiler Size:1524 mm IDx3962 mm L Items Inspected:Manway, Nozzles, Shell, Heads, Stack Service Type: Sweet

## Provincial Registration Number: BCSA HP137064 (A0570539) OIP Tag:603FB001 MAWP: 1379kpa @ 343°C Manway: Yes

Fluid:Heat Medium Glycol.

| Scope of Inspection | Type of Inspection |                      |     | Cleaning | Access     |
|---------------------|--------------------|----------------------|-----|----------|------------|
| □ Pre-commission    | AE                 | ШМТ                  | □rt | Good     | □ Full     |
| □ Initial           | ET                 |                      | UΠ  | □Fair    | Partial    |
| Re-inspection       | □lt                | □PT                  | ⊠vt |          | ⊠ External |
|                     | □ve                | UVE Other:Click here |     |          |            |
|                     |                    | to enter text.       |     |          |            |
|                     |                    |                      |     |          |            |
|                     |                    |                      |     |          |            |

## Observations:

-No visible indication of distortion or deformation.

-Paint ~99%; Minor paint loss around top of manway where gasket had previously failed and scorched paint. -No expansion slots; saddles welded directly to piles, no bolts.

-Evidence of glycol leak under PSV's, appears to be old. Operations to retape and tighten when installing new PSV's (To be delivered)

-PSV's < MAWP.

-PSV Inlet Valves car sealed open.

-Stack secure and aligned.

-Pressure Gauge spans MAWP.

-All bolting fully or acceptably engaged.

-ESD function tested at time of inspection and functioned successfully.

## Recommendations

-Tighten weeping PSV piping threads (To be done week of Aug 2 2016)

-Forward Inspection to Will Rettman for Review.

-Return vessel to service.

-Re-inspect at regularly assigned interval.

| Fit For Service: Yes                     | Remedial Action:  |        |                 |  |  |
|--|---|--------|-----------------|--|--|
| Inspected By:Kevin Gawley                | □High   | Medium | Low             |  |  |
| Date of Inspection (Mm-Dd-Yyyy):8/2/2016 |   |        |                 |  |  |
| Follow Up Inspection Required:No         | Required:No By Date: (Mm-Dd-Yyyy):Click here to enter a date. |        | o enter a date. |  |  |



EQUIPMENT NO: 603FB001 RAMS ID: 433815

|                                      | 0) Estemal Querniture                            |
|--------------------------------------|--|
| 1) OIP and Name Plate:               | 2) External Overview:                            |
| 3) Name Plate Detail 1 of 2:         | 4) Name Plate Detail 2 of 2:                     |
| 5) Pressure Gauge (Glycol Piping):   | 6) Shell and Stack Overview:                     |
| 7) Thread Weeping on PSV's:<br>603S1 | 8) Previous Hot Gas fugitive emission on manway: |