




# **EQUIPMENT INTERNAL INSPECTION REPORT**

Customer:	TAQA North	ITS Job N	No.: 1-3626
District:	North Area Date:		03-Nov-2016
Facility:	Sousa Compressor Station	Sousa Compressor Station & Field LSD:	
Equip. Description:	Inlet Separator	Serial No.	B712220
Equip./OIP No.:	520VS013	PRN:	A0516789
<b>Equip. Type:</b> Column Cooler	Exchanger  Furnace  Heater  Plat	te Exchanger 🗌 Reboiler 🗹 Vessel 🔲 C	Other:
Head (1)	Head (2)	Shell	Boot Shell/Head
☐ Top ✓ North ☐ West	☐ Bottom ✓ South ☐ East	✓ Good Condition	✓ Not Applicable
☐ Flat ☐ FLG ☑ ELL ☐ ECC	☐ Flat ☐ FLG ☑ ELL ☐ ECC	☐ No / Limited Access	☐ Good Condition
☐ HEMI	☐ HEMI	☐ Internal Corrosion	☐ Internal Corrosion
✓ Good Condition	☐ Good Condition	Pitting: (max depth)	Pitting: (max depth)
☐ Internal Corrosion	☐ Internal Corrosion	☐ Wear/Erosion	☐ Wear/Erosion
Pitting: (max depth)	Pitting: (max depth)	☐ Cracked	☐ Cracked
☐ Wear/Erosion	☐ Wear/Erosion	☐ Blistered	☐ Blistered
☐ Cracked	☐ Cracked	☐ Scale	☐ Scale
☐ Blistered	☐ Blistered	☐ Coated	☐ Coated
☐ Scale	☐ Scale	☐ Mechanical Damage	☐ Mechanical Damage
☐ Coated	☐ Coated	☐ Bulged/ Distorted/	☐ Bulged/ Distorted/
☐ Mechanical Damage	☐ Mechanical Damage	Deformation	Deformation
☐ Bulged/ Distorted/ Deformation	☐ Bulged/ Distorted/ Deformation	See Comments	☐ See Comments
☐ See Comments	✓ See Comments		
			_
Channel Head	Internal Welds	Internal Nozzles	Drum Steem
Not Applicable	Good Condition	Good Condition	Mud Steam
Good Condition	Poor Quality	☐ Internal Corrosion	Not Applicable
Internal Corrosion	Internal Corrosion	FILLING. depth)	Good Condition
Pitting: (max depth)	Pitting: (max depth)	Wear/Erosion	☐ Internal Corrosion
☐ Wear/Erosion ☐ Cracked	<ul><li>□ Wear/Erosion</li><li>□ Cracked</li></ul>	☐ Cracked☐ Scale	Pitting: (max depth)  Wear/Erosion
Blistered	Scale	Coated	□ Cracked
□ Scale	Coated	Plugged	☐ Blistered
☐ Coated	☐ Mechanical Damage	☐ Poor Welding	☐ Scale
☐ Mechanical Damage	See Comments	☐ Leaking	☐ Coated
	See comments	☐ Mechanical Damage	☐ Mechanical Damage
☐ Bulged/ Distorted/ Deformation		See Comments	☐ Bulged/ Distorted/
☐ See Comments			Deformation
			☐ See Comments





Internal Protection	Vessel Internals	Heating Coil (A)	Heating Coil (B)
■ Not Applicable	Adequate Cleaning	✓ Not Applicable	✓ Not Applicable
✓ Coating    □ Lining	☐ Vortex Breaker(s)/Deflection Plate(s) Damage	☐ Good Condition	☐ Good Condition
☐ Good Condition		☐ Corrosion	☐ Corrosion
☐ Blister(s)		☐ Pitting: (ma. depth	Pitting: (max depth)
✓ Dis-bonded	☐ Weir(s)/ Baffle(s)/ Divider(s) Damage	☐ Cracked	☐ Cracked
☐ Chipped		☐ Scaled	☐ Scaled
☐ Holidays/Cracked	Spray Nozzles Damaged/ Missing	□ Worn	□ Worn
☐ Mechanical Damage		Loose	□ Loose
☐ Missing	Down comes Comment	☐ Poor Installation	☐ Poor Installation
✓ See Comments	□ Down-comer Corrosion	☐ See Comments	☐ See Comments
	☐ See Comments		
			<u>-</u>
Demister Screen	Refractory	Manway	Trays
Not Applicable	▼ Not Applicable	Not Applicable	✓ Not Applicable
Good Condition	Good Condition	Good Condition	Good Condition
Dislodged	Cracked (minor)	Coating Damage	Collapsed
Broken	Spalling	☐ Internal Corrosion	Distorted
Missing	Missing	☐ Mechanical Damage	Loose
☐ Tie-downs Missing	☐ Damaged	Seal Face Corrosion	Missing
Fouling	Cracked (severe)	Pitting: (max depth	
Corrosion	☐ See Comments	☐ See Comments	Corrosion
☐ See Comments	-		Poor
			☐ Valve Caps Missing
			☐ See Comments
Tube Sheet	Firetube(s)	Tube Bundle	Tubes
✓ Not Applicable	✓ Not Applicable	✓ Not Applicable	✓ Not Applicable
Good Condition	Good Condition	Good Condition	Good Condition
☐ Corrosion	☐ Corrosion	☐ Corrosion	☐ External Corrrosion
☐ Pitting: (max depth)	☐ Pitting: (max depth)	☐ Pitting: (ma. depth	Internal Correction
☐ Wear/Erosion	☐ Wear/Erosion	☐ Wear/Erosion	Pitting: (max depth)
☐ Cracked	☐ Cracked	☐ Cracked	☐ Wear/Erosion
☐ Damaged	☐ Scaled	☐ Damaged	☐ Cracked
☐ See Comments	☐ Coated	☐ Plugged	☐ Thinning
	☐ Heat Impinged	☐ Scaled	☐ Heat Impinged
	☐ Burner Misalignment	☐ See Comments	☐ Bulged/Distorted
	☐ Damaged Supports		☐ Leaking
		-	☐ See Comments
	☐ Damaged Guides/ Tracks		
	☐ See Comments		

Report No.: VI-1-3626-03-CRE

Integrity Testing

4253-97 Street, Edmonton AB, T6E 5Y7
Tel.: (780) 417-0340
Fax: (780) 417-0348
www.integrity-testing.com

#### **Observations:**

# Equipment in **Good**, **Fair**, **or Poor** Condition

<u>Good</u>: No concerns found (may still have recommendations) <u>Fair</u>: Minor issues found that do not impair the "fitness for service" of the equipment, (paint deterioration, general external surface corrosion - no measurable metal loss, not mounted to skid, etc.)

<u>Poor</u>: Equipment had moderate to major concerns found (equipment is damaged, severe external corrosion noted, cracked or broken component, etc.)

### Based on API 510 Visual Internal Inspection this vessel is fit for service

(This piece of equipment meets the Jurisdictional requirements based on the information available at the time of the inspection.)

### Internal inspection performed.

- The coating patch on the South Head has disbonded from the substrate exposing the previously ground area from the 2013 VI findings. No corrosion / erosion noted in the area of coating failure. It is determined that the cause of coating failure was due to improper surface preparation.
- No pitting / corrosion noted in the vessel.
- Nozzles are in good condition.
- The demister was pulled and cleaned for inspection. The demister is in good condition. The demister box is in good condition.
- The manway and seal face are in good condition.
- Internal welds are in good condition.
- Vortex breaker is in good condition.

#### November 08, 2016:

- The area of failed coating was repaired by IPAC. The vessel was heated to a temperature of 18 degrees prior to coating. The area was sandblasted then coated using Enviroline 240S. Coating thickness applied averaged 24mils. See attached coating forms for further information.

### **Recommendations:**

- Recoat the coating patch on the South head.

### November 08, 2016:

- None

### **Non-Conformance Conditions and Corrective Actions:**

Note: Reference any and all Non-Conformance Report (NCR) numbers and Corrective Action Report (CAR) numbers.

- None

### **Recommended Inspection Interval:**

Recommended Maximum Inspection Interval:

60

Months



Photo 1: Internal Overview



Photo 2: Internal Overview (2)





Photo 3: Shell Overview



Photo 4: Shell Overview (2)



Photo 5: Shell Overview (3)



Photo 6: Shell Overview (4)



Photo 7: Failed Coating



Photo 8: Failed Coating (2)



Photo 9: Coating Failure



Photo 10: Previous Repair



Photo 11: Previous Repair (2)



Photo 12: Previous Repair (3)



Photo 13: Flange Face



Photo 14: Manway Flange






Photo 15: Manway Flange (2)



Photo 16: Internal Weld



Photo 17: Internal Weld (2)



Photo 18: Internal Nozzle



Photo 19: Internal Nozzle (2)



Photo 20: Internal Nozzle (3)



Photo 21: Inlet Deflector




Photo 22: Inlet Deflector (2)



Photo 23: Demister Box



Photo 24: Demister Pad




Photo 25: Vortex Breaker



Photo 26: Vortex Breaker (2)

Report No.: VI-1-3626-03-CRE



4253-97 Street, Edmonton AB, T6E 5Y7 Tel.: (780) 417-0340 Fax: (780) 417-0348 www.integrity-testing.com



Photo 27: Thermowell

Internal Inspectio	n Performed By:		ABSA IPV PESL: 000782
Print Name:	Christopher Russell Earl	Certification No.:	API 510: 45377
Signature:	7. 3 cm		Report Reviewed: Initial
Chief Inspector / Client Representative:	Name (Print)	Signature	Date: