

Report No.: VE-2341-11-CHO

4253-97 Street, Edmonton AB, T6E 5Y7
Tel.: (780) 417-0340
Fax: (780) 417-0348
www.integrity-testing.com

EQUIPMENT EXTERNAL INSPECTION REPORT

	-~	/\ \			• • • •			
Customer:	TAQA North ITS Job					No.: 2341		
District:	South Area Date:					_	24-Jul-2013	
Facility:	Swalwell Field LSD:					01-07-030-24W4		
Equip. Description:	3 Pha	se Glycol Cont	actor	Seria	al No	0.:	2005740301B	
Equip./OIP No.:		158VT001		PRN:		_	A0539303	
Equip. Type: Column Cooler	Exchanger □Furr	nace Heater Pl	late Exchanger □Reboile	r V ess	sel 🗌	Other:		
Remedial Action	Access and	d Coverage	Associated Comp	poner	nts		Shell	
✓ No Action Required	✓ External Inspection		✓ Name Plate Secu	re	□ N	□ Тор	☐ Bottom	
☐ Paint/Coating Repairs	☐ Part. External Inspection		✓ Name Plate Legib	ole [\square N	 Goo	d Condition	
☐ Insulation Repairs	NDE Examination		External Grounding			□ Exte	rnal Corrosion	
☐ PSV Service Required	□МТ		☐ Direct ☑ Indirect ☐ N			☐ Pitti	ng: (max depth)	
☐ Further Assessment	 UT		Ladders/ Handrail/			□ Scal	e	
Required	□RT		Walkway/ Grating in saf			□ Blist	ered	
☐ Condition Damage	□ ВН		condition?			☐ Mechanical Damage		
☐ Does not comply with applicable code/safe operating requirement.	□ PT		☐ See Attached Pictures			□ Defo	ormation/Distortion	
	□ Other		☐ Excessive Vibration			☐ Condensation/Sweating		
Repairs Required	See Comme	ents	☑ Gauge within MAWP			☐ No Access Insulated		
See Comments			☐ Gauge within MDMT			☐ No Access Ice Build Up		
Status	□ Idle;		✓ Y □ N Attached Piping		and	☑ Weld	d(s) in Good Condition	
✓ Operational; □ Idle;			Instrumentation in			☐ Weld(s) Corroded		
Shut In;			Condition			☐ Weld(s) Poor Quality		
☐ Surplus/Boneyard; ☐ Other:			✓ See Comments	ıts		☐ Weld(s) Cracked		
- Other.					☐ See Comments			
111/1			111 (2)				N I	
Head (1)	□ West	Z Dettem	Head (2)	East		Z DE 🗆	Nozzles	
✓ Top☐ North☐ Flat☐ FLG✓ ELL☐	West	☑ Bottom			_		RTJ NPT Condition	
	ECC HEMI			— п	_			
Good Condition		✓ Good Condition				▼ Fasteners Engaged		
External Corrosion	(may	External Corrosion			/may F	Repad Weep Holes Clear		
☐ Pitting:	(max depth)	☐ Pitting: (ma depth			-	□ Nozzles are Gusseted		
□ Scale		□ Scale			-	☐ External Corrosion		
☐ Blistered		□ Blistered			L	☐ Leaking/Weeping		
□ Mechanical Damage		☐ Mechanical Damage				☐ Damaged/Cracked		
□ Deformation/Distortion		 Deformation/Distortion 				☐ Bolts Missing/Loose		
\square Condensation/Sweating		Condensation/Sweating				☐ Deflection/Distortion		
☐ No Access Insulated		\square No Access Insulated				☐ Partial Internal Inspection		
□ No Access Ice Build Up		\square No Access Ice Build Up				☐ No Access Insulated		
☐ External Protection Only		☐ External Protection Only				✓ Weld(s) in Good Condition		
✓ See Comments		See Comme	ents			Weld	(s) Corroded	
						Weld	(s) Poor Quality	
						Weld	(s) Cracked	
						See C	Comments	





4253-97 Street, Edmonton AB, T6E 5Y7
Tel.: (780) 417-0340
Fax: (780) 417-0348
www.integrity-testing.com

External Surface	Supports	Associated Piping	PRD 1	PRD 2
✓ Good Condition	✓ Good Condition	✓ Good Condition	Location: On Vessel	Location: Not Applicable
Painted Full Part.		☐ Corrosion	PSV Tag No.: 158SVVT001	PSV Tag No.:
Coated Full Part.	Secure	Pitting: (max depth)	✓ Service Date within	nin Service Date within
☐ Insulated ☐ Full ☐ Part.	☐ Welded to Skid	☐ Bolts Missing/	Interval	Interval
☐ Insulation Damaged☐ Penetration Seals	☐ Supported by Nozzle(s)	Loose/ Damaged Short Threaded	✓ Set Pressure within MAWP	☐ Set Pressure within MAWP
Broken	✓ Piping Supported	☐ Valves leaking	✓ Safety Seal Intact	☐ Safety Seal Intact
☐ Corrosion Under	☐ Expansion Slots	,	✓ Service Seal Intact	☐ Service Seal Intact
Insulation (CUI)	□ Bolts Missing/ Loose/ Damaged	Connections Leaking	✓ Current Service Tag Attached	☐ Current Service Tag Attached
☐ Visible Moisture Contamination	☐ Short Threaded	✓ Piping and Valves	☐ PSV inlet Gusseted	☐ PSV inlet Gusseted
☐ Paint Deterioration	☐ Deflected/Distorted	Supported	☐ Inlet Block Valve	☐ Inlet Block Valve
☐ Coating		☐ Piping Deflected/	Locked Open ☐ Y ☐ N	Locked Open PYN
Deterioration	☐ Poor Insulation	Distorted	Sealed Open 🔲 Y 🗆 N	Sealed Open PYN
☐ Fireproofing Cracked	☐ Fire Proofing	□ No Access	☐ Outlet Block Valve	☐ Outlet Block Valve
	Cracked	Insulated	Locked Open	Locked Open ☐ Y ☐ N
☐ External Protection	✓ Vessel is level	☐ See Comments	Sealed Open 🔲 Y 🗆 N	Sealed Open Y N
Only	See Comments		☐ See Comments	☐ See Comments
☐ See Comments				
Observations:				
 Vesse	l in Good Condition	□ Based (on API 510 Visual Ext • vessel is fit for	ernal Inspection this service
- Temp gauge is not w - No access to top hea - PSV service date 03/2 - Liquid level is in good - Roof seal is in good of	d 2010 set at 9756 kPa d condition			
Recommendations	:			
- Recommend to repla	ce temp gauge with on	e that is within MAWP o	f vessel29C	
_				
	Conditions and Corrend all Non-Conformance R	ective Actions: eport (NCR) numbers and	Corrective Action Report	(CAR) numbers.
- None				
Recommended Ins	pection Intervals:			
Recommended Maximum Inspection Interval:		PRD 1 Recommended 60 ervice Interval:	Months Recommend Service Inter	O 2 Not Applicable Months val:
External Inspection Per Print Name:	rformed By: Chad Harol	d Qakes	Certification No.:	
Signature:	W Out			Report Reviewed:
				initial