

District: West central		Area: Granada		nk Information Location (LSD): 2-18-52-11w5				
Tank ID # 920		Serial Number: J-04-087-4		Function / Description: Production.				
Year Built: 2004 Year Installe 2004		alled:	Manufacturer: GLM					
	X Aboveground (AST)			Underground (UST)			☐ Double Wall	X Single Wall
Tank Type:	☐ Flat Bottom	☐ Flat Bottom ☐ Slope I		ottom		C 4		
Material	X Steel	☐ Fiberglas	s	Poly	☐ Other	Description	on:	
Tank Category:	☐ Flare KO	☐ Storage		X Process	□ Po	p Tank		
Service:	X Oil	☐ Leachate		☐ Brine Water ☐ Fr		esh H2O	☐ Condensate	☐ Glycol
Service:	☐ Chemical	☐ Slop / S	olids	☐ Drilling M	ud		X Sweet	Sour
		Water State Committee Comm	Exter	nal Inspe	ction	And the second s		
External Condition				Painted / External Coating		y Foam Insul		
	(Check All That Apply)	☐ Bare St				stic, fibreglass, etc.	
	Condition: Comments: Nee bottom ring pai		☐ Excelle	nt X Good	∏ Fair	<u> </u>	′oor □ N//	A (No Protection)
	Inspection Meth	nod:	X Visual	☐ UT'e	d ☐ Othe	r Desc	cription:	
	Corrosion / Pitt Cracking:	ing /	☐ Yes	X No	Descrip	tion:		
•	Comments:							
Shell Fixtures & Fittings (heating coils, sample collection points, mixers,	Manways / Nozzles	X Good	☐ Fair	☐ Poor	Description:			·
etc).	Tank Piping	X Good	☐ Fair	☐ Poor	Description:		-	
	Comments:							
Roof Condition	Thief Hatch	X Good	☐ Fair	☐ Poor	Description:			
	Roof Deck	X Good	☐ Fair	☐ Poor	Description:			
	Ice Rake	☐ Good	I ☐ Fair	☐ Poor	Description: I	N/A		
Roof Fixtures & Fittings		X Good	☐ Fair	☐ Poor	Description:			
	Comments: Vented to atmosphere.			·				



Ladders, Stairs, Platforms.	Х С	ood 🔲 Fair 🔲 Poor Description:			
5.4484					
Floor Condition	Internal Protection: (Check All That Apply)	Internal Inspection X Coated X Bare Steel Poly, Fiberglass Other Description:			
	Floor Condition:	X Excellent Good Fair Poor N/A (No Protection) Corrosion Pitting Wear Delamination Scrapes / Dents Other Description:			
	Soil Side (Floor Scan) (Floor Scan is discretionary.)	☐ Excellent ☐ Good ☐ Fair ☐ Poor X NA Description:			
	Inspection Method:	X Visual X Jeeped MFI. Floor Scan UT – Spot Check Other Description:			
	Comments:	No signs of cracking or pitting.			
Shell Condition	Internal Protection:	☐ Coated X Partial ☐ Complete ☐ Bare Steel ☐ Poly, Fibreglass, etc. ☐ Other Description:			
	Condition:	X Excellent ☐ Good ☐ Fair ☐ Poor ☐ N/A (No Protection) ☐ Corrosion ☐ Pitting ☐ Wear X Delamination ☐ Scrapes / Dents ☐ Other Description:			
	Inspection Method:	X Visual			
	Comments:	Coated 4ft up wail.			
Roof Condition	Condition:	☐ Excellent X Good ☐ Fair ☐ Poor ☐ N/A (No Protection) ☐ Corrosion ☐ Pitting ☐ Wear X Delamination ☐ Scrapes / Dents ☐ Other Description:			



	Inspection Method:	X Visual	
	Comments:	Rust	
		·	
The second secon		Internal Inspection	The second secon
Fixtures and Fittings (tank associated pipe, fittings, nozzles, etc)	Condition:	Nozzles / Flanges X Excellent	
Internal Equipment	Condition:	Agitators, augers, float assemblies, etc:	
Anodes	Condition (% Spent)	Anode #1 Anode #2 Anode 3 Anode #4 Anode #5 Anode #6 Anode #7 Anode #8 Anode Replacement: Description: N/A	, , , , , , , , , , , , , , , , , , , ,
Tank Cleaning		X Yes No Volume (m3): Description:	
		Additional Comments	A company of the comp
Ensure all pertinent documentation	n / photos are attached to this rep	ort =i.e. NDE (UT, Jeep, etc.) test results, repairs and alterations, cathodic protection, third party inspections	, elc.
Tank is in good to ex	cellent condition.		
Sign-Off:			
Date Inspection Complete	d: January-06-2015	January-10-	
Individual Performing the Inspection	Lynes Hani	na. 2015	
	Name Christan Lawre	nce Date Jan 10 2015	
Facility Manager	Name	Signature Date	-



*** Upon completion of the Tank Inspection Form, Sign and Forward to the Facility Manager. ***							
Last Date of Inspection:	June 24 2014	Insp. Interval Yearly	Next Inspection Due Date:	January-06-2016			