

155741-MD-21 Report #: Inspect Date: 02/16/2012 Page: 1 of 13

Insp. Co. Job #: 155741

Criticality D	Designation:			Kellon	<b>%</b> /				
Insp. Comp:	Matrix_Insp	pection Distric	t: Gran	de Prairie - No	rth		Fiel	ld: South F	lamburg
Location:	12-29-096-	-11W6 Unit / Skid	<b>#</b> :	7714			LS	D: 12-29-09	96-11W6
Jurisdiction #:	A30749					5	Serial	#: 95-1	207
CRN #:	M8509	9.2 Nat'l Bd	<i>‡</i> :	N/A		Ye	ar Bui	ilt: 19	95
Manufacturer:	<b>EXCHANGER</b>	INDUSTRIES	Equipme	ent Description	: Ot	her: Propane C	hiller		
Status:	In Service -	Ed	uip. Typ	e: Exch.: Chill	er			Service:	Sweet
MAWP Shell:	285 Psi	@ 100 °F	Volu	ume:			=" 	Code Stamp:	⊠Y □N
MAWP Tube:	1037 Psi	@ 100 °F H	eight/Ler	ngth: 576		in.		Insulated:	$\boxtimes$ Y $\square$ N
MDMT:	-20 °F	RT: RT-3 Siz	ze/Diame	eter.: 18	in.	O.D.		PWHT:	$\square$ Y $\boxtimes$ N
Support	Saddle	Vessel on Or	ginal CN	IRL Inventory L	_ist:	$\boxtimes$ Y $\square$ N		Manway:	$\square$ Y $\boxtimes$ N
C.A.:	0.063 in.	Coated: No	Clad: 1	No J	.E.:	0.90 Remo	te Acc	cess: 🗌	
Comp	onent	Material		Nominal Thk	I	Diameter O	D/ID	Tube Side	Shell Side
1 Main - She	ell	SA- 516-70		0.500 in.	1	8.000 in.	OD		$\boxtimes$
2 West - Hea	ad	SA- 516-70		3.750 in.	1	8.000 in.	OD		$\boxtimes$
3 East - Hea	ıd	SA- 516-70		3.750 in.	1	8.000 in.	OD		$\boxtimes$
4 - S	hell	SA- 516-70		0.750 in.	1	8.000 in.	OD		$\boxtimes$
5 -									
Static Data: C	onfirmed 🗌	Changed (See Commen	ts) 🛚						
Comments:									
Static data upd									
Shell CA = 0.12	26" Channel CA	· = 0.063"							
D0// 0/ /: D /									
PSV Static Data									
PSV –1 Tag				90042 01			_	02176.52	
	el #: JBS 15J	Capacit	/: 2113 <sup>2</sup>	4 SCFM		Set Pressu	_	•	
	rer: Crosby	<del></del>				Service Compa		•	
	& Type: 3.00 i			_		Last Service Da	_		
	& Type: 6.00 i	in Flanged		E	Block	Valve: Upstre		•	en
	al Intact: Yes			<b>5</b>		Code Star	_		
Shell Side	/ Tube Side: S	nell Side Out for	Service	During Insp.:	N	Location of Page 1	SV: <u>(</u>	Jpstream	
PSV –2 Tag	g #:	Serial a	<b>#</b> :			CF	RN: _		
Mode	el #:	Capacit	/:			Set Pressu	ıre:		
Manufactu						Service Compa	ıny:		
	rer:								
	rer: & Type:	-				Last Service Da	ate:		
	& Type:	-		E		Last Service Da k Valve: -			
Inlet Size Outlet Size	& Type:	-		E			-		
Inlet Size Outlet Size Carsea	& Type: & Type:	-	Service	EDuring Insp.:		k Valve:	- mp: _		
Inlet Size Outlet Size Carsea Shell Side	& Type: & Type: al Intact:	-	Service			k Valve: Code Star	- mp: _		
Inlet Size Outlet Size Carsea Shell Side PSV Comments	& Type: & Type: al Intact: / Tube Side:	-	Service			k Valve: Code Star	- mp: _		
Inlet Size Outlet Size Carsea Shell Side	& Type: & Type: al Intact: / Tube Side:	-	Service			k Valve: Code Star	- mp: _		
Inlet Size Outlet Size Carsea Shell Side PSV Comments	& Type: & Type: al Intact: / Tube Side:	-	Service			k Valve: Code Star	- mp: _		
Inlet Size Outlet Size Carsea Shell Side PSV Comments	& Type: & Type: al Intact: / Tube Side:	-	Service			k Valve: Code Star	- mp: _		
Inlet Size Outlet Size Carsea Shell Side PSV Comments	& Type: & Type: al Intact: / Tube Side:	-	Service			k Valve: Code Star	- mp: _		
Inlet Size Outlet Size Carsea Shell Side PSV Comments	& Type: & Type: al Intact: / Tube Side:	-	Service			k Valve: Code Star	- mp: _		
Inlet Size Outlet Size Carsea Shell Side PSV Comments	& Type: & Type: al Intact: / Tube Side:	-	Service			k Valve: Code Star	- mp: _		



Report #: 155741-MD-21 Inspect Date: 02/16/2012 Page: 2 of 13 Insp. Co. Job #: 155741

Insp. Company:	Matrix_Ir	spection	LSD:	12-29-096-11W6	Jurisdic	tion #:	A30	74903	
External Inspection Resu	ults – VE	External In	spection Per	formed					
Item	N/A	Condition	(0	Comment Check Status Bar or Press F1 for Help	))	NCR	Action Item Integrity	Action Item Maintenance	
Nameplate		Accept	Firmly affixed and legible						
Foundation and Suppo	rts 🗌	Accept	Acceptable	Acceptable condition					
Anchor Bolts		Accept	Secure & tig	ght					
Grounding		Accept	Grounded b	y skid					
Insulation Condition		Reject	Cladding da	amage allowing for moss grov	vth			$\boxtimes$	
PSV		Reject	Due for serv	vice				$\boxtimes$	
Shell Heads & Nozzles		Accept	Minor surfa	ce corrosion on exposed noz	zles				
Metal Surfaces (Paint)	$\boxtimes$		Exchanger	is insulated with no access					
Aux Equipment		Accept	Secure and	intact					
Cathodic Protection	$\boxtimes$		No external	anode					
Alignment		Accept	Acceptable	condition					
Flange Connections		Accept	Adequate th	nread engagement					
Pressure Gauge		Accept	0-2100 kPa	: acceptable range					
Temperature Gauge	$\boxtimes$		No tempera	ature gauge					
Sight Glass		Accept	Clear and v	risible sight glass					
Ladder / Platform		Accept	Ladder and	platform are acceptable					
Leaks		No	No evidence	e of leaks					
Piping from Vessel		Accept	Adequately	supported					
Previous UT Survey		No	No ports, no	o history provided	UT C	ompan	y: N/A		
External Visual Observat	iono								
The Chiller is complete	ly insulat	ed with ice I	build-up on n	nany of the exposed flanges.					
The cladding is punctu nameplate. This may le				moss growth noted in the pur rrosion.	nctured clad	dding a	s well as arou	nd the	
There is loose banding	on the c	ladding that	has allowed	for the cladding the split and	expose the	foam	glass.		
The insulation on the b the corrosion due to Cl		the sight gla	ass is deterio	rated and weathered which m	nay have er	ntrappe	d moisture an	d accelerate	
The PSV is due for service									
				ne of inspection due to no port cture if chipped in this condition		ed acce	ss (no scaffold	d or platforms)	)
TA 2012 - UT corrosion	n survey	was comple	ted with the	chiller off-line with no significa	ant recordat	ole wall	losses		

### Recommendations:

Service the PSV

Consider removing the moss and treating with a biocide (multiple applications may be required) Repair the insulation, banding and caulking seals

TA Recommendations:

Using a travel restraint device perform UT corrosion survey on the exchanger - COMPLETED TA 2012



Report #: 155741-MD-21
Inspect Date: 02/16/2012
Page: 3 of 13
Insp. Co. Job #: 155741

				ļ	1			
Insp. Company:	Matrix_In	spection	LSD:	12-29-096-11W6	Jurisdiction #:	A30	74903	
Internal Inspection R	esults – VI 1	N/A (Not App	olicable)					_
Item	N/A	Condition	(Che	Comment eck Status Bar or Press F1 for Help	nCR	Action Item Integrity	Action Item Maintenance	
Shell				spection Carried Out		Ŭ,		-
Heads				spection Carried Out				1
Manway				spection Carried Out				-
Gasket Surfaces				spection Carried Out				1
Welds				spection Carried Out				1
Refractory				spection Carried Out				-
Heating Coils				spection Carried Out				1
Demister Pad				spection Carried Out				1
Vane Pack				spection Carried Out				-
Baffles				spection Carried Out				1
Trays				spection Carried Out				1
Filter				spection Carried Out				-
Internal Coating				spection Carried Out				1
Tubesheet				spection Carried Out				1
Tube Bundle				spection Carried Out				1
								_
Internal Visual Obser	vations							_
Recommendations:								
	ion Corried (	)t						
No Internal Inspect	ion Carried C	Jut						



Report #: 155741-MD-21
Inspect Date: 02/16/2012
Page: 4 of 13
Insp. Co. Job #: 155741

Insp. Company: Mat	rix_In	spection	LSD:	12-29	-096-11W6		Jurisdiction #:	A30	74903	
Firetube Static Data N/A (N	lot An	pplicable)								
Diameter: Not Applicate		- 110abio)	Nom	Thickness:	Not Applicat	hle		Rend: Not	Applicable	
Length: Not Applicat					Not Applicat			Dona. 1400	, ippiioanie	_
Lengin. Not Applicat	UT	□ Penor	t#: Not Applic	·-			Report#: Not	Applicable		
Firetube NDE		· ·								
Performed:		-	t#: Not Applic		RT		Report#: Not			
	PT	Repor	t#: Not Applic	able	Other	. П	Report#: Not	Applicable		
Firetube Inspection Results										
Item	N/A	Condition			mment		NCR	Action Item	Action Item	
		00110111011			or Press F1 for F	Help)		Integrity	Maintenance	·
Burner			No Firetube II	-				<u> </u>		
Stack			No Firetube II							$\dashv$
Flange (Throat) Tube Sheet			No Firetube II							
Hot Side			No Firetube II							-
Miter			No Firetube II							
Return Bend			No Firetube II	•					<u> </u>	
Supports			No Firetube II	•				<u> </u>		$\dashv$
Butt Welds			No Firetube II					<u> </u>		$\dashv$
Fillet Welds			No Firetube II							
			No i lietabe li	ispection C	zamed Out			Ш		
Firetube Visual Observations	3									
No Firetube Inspection Ca	rried	Out								
Recommendations:										
No Firetube Inspection Ca	rried	Out								



Report #: 155741-MD-21
Inspect Date: 02/16/2012
Page: 5 of 13
Insp. Co. Job #: 155741

		<del> </del>				
Insp. Company:	Matrix_Inspection	LSD:	12-29-096-11W6	Ju	ırisdiction #:	A3074903
Vessel NDE and Final	Summary:					
	UT ⊠ Report#:		ET	□R	eport#:	
NDE Performed	· · · · · · · · · · · · · · · · · · ·		RT		leport#:	
	PT Report#	-	Other		leport#:	
Maxi-Trak Observations	<u> </u>	-			<u> </u>	
PSV is due for service	<u> </u>	<u> </u>		,		
	osing the foam glass and	d moss growth.	Loose banding on cla	addina		
	n on sight glass with wea	-		-		
	ice may risk brittle fract			•		
Maxi-Trak Recommenda			ndations Max 255 Ch	aracters	)·	
Service the PSV	tions cummary (cumm	41120 1100011111101	Tadiono Max 200 On	araotoro	<del>//·</del>	
	e moss and treating with	n a biocide (mult	iple applications may	be requ	uired)	
Repair the insulation,	banding and caulking se	als				
Perform UT at TA - CO	OMPLETED AT TA					
Actions Corrected at Ti	me of Inspection: (If action	as were corrected at	the time of Inspection – not	te the corre	ected actions here )	
	cted at the time of inspe		and time of moposition floor		octor actions here.	
No actions were corre	sted at the time of mape	Clion				
Additional Visual Observ						
No additional visual ol	bservations were made	at the time of ins	spection			
Any other safety concern				associat	ted piping, buildings, p	umps etc)
Proper tie off required	when outside of the pla	tforms, use a sp	otter as well			



Report #:
Inspect Date:
Page:

Insp. Co. Job #:

155741-MD-21 02/16/2012 6 of 13 155741

Insp. Company: Matrix\_Inspection LSD: 12-29-096-11W6 Jurisdiction #: A3074903

#### Thickness and Remaining Life Evaluation

#### " Must be Completed"

### MUST BE COMPLETED AND RESOLVED WITH CNRL IMMEDIATELY UPON DISCOVERY OF LOW WALL THICKNESS AREAS

Step 1: Was any thickness measurement location found to be less than (Nominal WT - Corrosion Allowance)?: No

If YES, proceed to Step 2; if NO, proceed to "Crack Evaluation" and "CNRL Criticality Designation".

Step 2: Which component(s) were found below (Nominal WT - Corrosion Allowance)?

Components found below Nom - CA:

Components					
N/A - N/A					
N/A - N/A					
N/A - N/A					
N/A - N/A					
N/A - N/A					

Perform Steps 3 – 8 for each component with actual thickness less than (Nominal WT – Corrosion Allowance).

Step 3: Describe Location and Extent of Corrosion:

Components

**Location and Extent of Corrosion** 

N/A - N/A	t Applicable for this Inspection			
N/A - N/A	Not Applicable for this Inspection			
N/A - N/A	Not Applicable for this Inspection			
N/A - N/A	Not Applicable for this Inspection			
N/A - N/A	Not Applicable for this Inspection			

#### Notes:

Not Applicable for this Inspection

#### Step 4:

- For shells and nozzles, calculate minimum required thickness (T-min) as per ASME Section VIII UG-27.
- For heads, calculate minimum required thickness (T-min) as per ASME Section VIII UG-32.

Components	T-Min
N/A - N/A	N/A



Report #: 1
Inspect Date:
Page:

Insp. Co. Job #:

155741-MD-21 02/16/2012 7 of 13 155741

Insp. Company: Matrix\_Inspection LSD: 12-29-096-11W6 Jurisdiction #: A3074903

#### Thickness and Remaining Life Evaluation (Continued)

Step 5: Is any measured thickness less than calculated minimum required thickness (T-min)? N/A

If YES, complete Step 6
If NO, proceed to Step 7..

Step 6: Is nature and extent of pitting acceptable as per API 510? N/A

Step 7: Calculate Remaining Life as per API 510. How? (Find last reading; use nominal thickness if nothing available). Short Term Corrosion Rates and Long Term Corrosion Rates.

Components	Remaining Life (Yrs)
N/A - N/A	N/A

Step 8: Contact CNRL Integrity Coordinator to discuss above results.

- Name of CNRL contact: Not Applicable for this Inspection
- Date and time of conversation: Not Applicable for this Inspection

Summary/results of conversation:

Not Applicable for this Inspection

#### Crack Evaluation by Magnetic Particle or Alternative Inspection "Must be Completed"

#### MUST BE COMPLETED AND RESOLVED WITH CNRL IMMEDIATELY UPON DISCOVERY OF CRACK-LIKE INDICATIONS

Were any indications found to suggest the vessel contained cracks? N/A

If NO, proceed to "CNRL Criticality Designation".

If YES, Contact CNRL Integrity Coordinator to discuss results.

- Name of CNRL contact: Not Applicable for this Inspection
- Date and time of conversation: Not Applicable for this Inspection

Summary/results of conversation:

Not Applicable for this Inspection



Report #: 155741-MD-21
Inspect Date: 02/16/2012
Page: 8 of 13
Insp. Co. Job #: 155741

Insp. Company: Matrix\_Inspection LSD: 12-29-096-11W6 Jurisdiction #: A3074903

#### CNRL Criticality Evaluation – "MUST BE COMPLETED"

The CNRL In-Service Pressure Vessel Inspector MUST answer all the following questions

- 1. Is the vessel fit-for-service?: Yes
- 2. Was the measured thickness less than the calculated minimum required thickness (T-min) for any component?: No
- 3. Were MT indications found?: **N/A**
- 4. Was the remaining life less than 6 years for sour service vessels or less than 10 years for sweet service vessels?: **No**
- 5. Were NCR's or Action Items generated as a result of the inspection? : Yes
- 6. Were UT readings below (Nominal WT Corrosion Allowance) found? : No

#### Information on CNRL Owner User Program - Criticality Designation and Required Review

RED – Vessel Inspection Results are deemed RED if one of the following occurred:

- The measured thickness was less than the calculated minimum required thickness (T-min) for any component.
- MT indications were found.
- The remaining life was calculated to be less than 6 years for sour-service vessels or less than 10 years for sweet-service vessels.

RED inspection reports must be signed off by the CNRL Chief Inspector.

YELLOW – Vessel Inspection Results are deemed YELLOW if one or more of the following occurred:

- The vessel was declared NOT fit-for-service by the 3<sup>rd</sup> Party In-Service PV Inspector.
- NCR's or Action Items were generated as a result of the inspection.
- UT readings below (Nominal WT Corrosion Allowance) were found.

YELLOW inspection reports must be signed off by the CNRL Pressure Equipment Integrity Coordinator.

GREEN - Vessel Inspection Results are deemed GREEN if all of the following are true:

- The vessel was declared fit-for-service by the 3<sup>rd</sup> Party In-Service PV Inspector.
- UT readings below (Nominal WT Corrosion Allowance) were NOT found.
- MT indications were NOT found.
- NCR's or Action Items were NOT generated as a result of the VE inspection.

GREEN inspection reports must be signed off by the 3<sup>rd</sup> Party In-Service Pressure Vessel Inspector.

Critica	ality Designation	Yellow
Vehicle #:	501 Kms:	Inspector (Name): Matthew B Dickinson PESL: 601
Time In:	00:00 Time Out: 00:00 Hrs	Inspector (Signature): API: 39483
Time In:	00:00 Time Out: 00:00 Hrs	CNRL Coordinator (Name):
Personnel:	BI, LP	CNRL Coordinator (Signature):
Billing Info:	AFE:	(I am in full agreement with report contents) CNRL Chief Inspector (Signature):
	-	(I am in full agreement with report contents)



Report #: 155741-MD-21
Inspect Date: 02/16/2012
Page: 9 of 13
Insp. Co. Job #: 155741

#### **Equipment Photographs:**



01 nameplate



02 East overview



Report #: 155741-MD-21
Inspect Date: 02/16/2012
Page: 10 of 13
Insp. Co. Job #: 155741



03 West overview



04 overview

Report #: 155741-MD-21
Inspect Date: 02/16/2012
Page: 11 of 13
Insp. Co. Job #: 155741



05 punctured cladding with moss



06 deteriorated insulation

Report #: 155741-MD-21
Inspect Date: 02/16/2012
Page: 12 of 13
Insp. Co. Job #: 155741



07 loose banding



08 moss growth around nameplate



Report #: 155741-MD-21
Inspect Date: 02/16/2012
Page: 13 of 13
Insp. Co. Job #: 155741



09 PSV overview