

Page 1 of 2

		🗆 Ins	tallatior	n 🗹 Extern	al 🔲 Pip	ing												
Date:		Aug. 25,		Descri	ption:	C Ves	Vessel 🗹 Exchanger 🗔 Furnace Boiler											
Inspector:		Brad Wh	ite		Unit #:			Equip #:										
Agent Co:		Foothills	Integrity	<sup>,</sup> Managemen	Equip.	Name:	Water Ir	Water Injection Filter										
					Jurisdi	iction #:	N/A											
Province:		Manitoba	а			acturer:		ESS Corp.										
Area:					Year B			2014 S/N: 4550B										
Subarea:		_					Location/LSD: 09-32-001-2				8W1 E	V1 Battery						
Service		Sweet Sour Other:						PS	SV Locatio					<b>MDMT</b> -29C			-29C	
Zones:		MAWP Design T		T Set P	Set P CPE# M		/lanufacturer		S/N		ln. Sz		Serv. Co.	Serv Date	e IV		Capacity	
Shell Side		1034kPa 38 C												_	Y/N	Y/N		
Tube Side															Y/N	Y/N		
Other											<u> </u>			Y/N Y/N				
s		Mate	rial	Nominal t	CA		Retire t		owest t		OK?	1	Calc. t-min		Com	nent		
Components	Shell								I		<u>Y                                    </u>							
noc	Head										<u>Y _ </u>							
Ē	Channel										Y							
ŭ	Tube Other										<u>Y _ r</u> Y <u>_</u> r			Specify				
			<b>W</b> 1/	E	Concret		o					N	0					
	rientation	Hor.		_		e 🖳					Other:	O a se all'it' a se	Cor	ndition G	000			
Support		Saddl	le		Seal-welded Free to Move Free of debris Comment:							Condition:						
			oro	Secure (		ment						Condition:						
		Hang C Other									Condition: Condition: Good							
Overall		Cher Specify: Legs General Condition: Good										Electrical grounding  Direct  Indirect  None						
Ext. Surface		Painted Insulated Fire-proofed Cladded Other:     Ladder Platform(s) Other:     Condition:										Condition: Good						
Ext. Fixtures		Ladde		Platform(s)		Condition:												
		🗖 Manw		Port Size	Reinforcement Pads us						used Weep Holes Present							
		Commer	_					1										
Da	avit Arm	Pres	ent	Greased		uble	nutted	Condit	ion									
				Supported	orted 🛛 🗖 Joined pe			🔲 Dra	ins Properl	у		Well Coated	Com	ment:				
		🗹 Inlet	~	Supported	ported 🛛 🗹 Joined pe			<b>F</b> ree	from leak	5	<u>ا</u>	Well Coated	Com	ment:	ent:			
		🗹 Outle		Supported					e from leak			Vell Coated	Com	nment:				
	ping	Drain		1	upported I I Joined per				e from leak			Well Coated	Corr	nment:				
			mentatio		ported	loi	ned per d					_	omment:					
		Process Fluid Identified Flow direction marked Comment: See comment below										intern.						
		Manua			Free f													
Valves Gauges		=		ontrol Valve	E Free f													
				ain plugged														
		Pressure						Condition: New										
		Temperature			Reading:			Condition:										
Sight Glass		E Fluid Level		Reading	Ũ			Condition:										
	spection ummary	Vessel legs are welded to the foundation.																
Recommended Actions:											NCR/IDR							
RN WO~Mark process fluid and flow direction on piping.																		
L																		
L-						-	_	SSEL S					_			<u> </u>		
	tegrity Statu			Continued Se					diate Repa					airs Requ	iired 🖳	Repla	ce	
In	ventory Stat	us 🔛 🗹	n Servic	e 🗖 Idle 🗖	Out of Se	rvice	🗖 Su	rplus 👢	Scrap	⊟ Ao	ction It	tems Comple	eted					

INDEL       411-4-1-50-0-636         Text       102-507-000         Text       102-507-000 <b>JOURT CANADA INC</b> Internet inte

Additional Notes on continuation page: (Report:\_\_\_\_) Inspection Interval: 5 yrs OR Changed to: \_\_\_\_\_ yrs. IPV/IBPV Certificate #: 113 PSV Interval: \_\_\_\_\_ yrs OR Changed to: \_\_\_\_\_ yrs. IPV/IBPV Certificate #: \_\_\_\_\_

Signature of In-Service Inspector: Brad White