

## Crescent Point visual inspection report – pressure vessel

Page 1 of 2

										_								- 5 -				
		□Ins	tallatio	n 🗹 Ex	cterna	al 🗆 Pip	oing															
Date:		Aug. 25, 2015							Description:			Vessel Exchanger Furnace Boiler										
Inspector:		Brad White						Unit #:			Equip #:											
Agent Co:		Foothills Integrity Management Inc.						Equip. Name:			Water Injection Filter											
		- · · · · ·							diction #	: N/	N/A <b>CRN #</b> : T4805.4											
Province:		Manitoba						Manufacturer:			ESS Corp.											
Area:									Year Built:			2014 <b>S/N</b> : 4551A										
Subarea:								Locat	ion/LSD	09	09-32-001-28W1 Battery											
Service		Swee	PS			ocatio			-	MDMT -29C												
Zones: Shell Side		MAWP Design		Sour Othe T Set P				anufactu			S/N		ln.	Out.	Serv.	Serv.	IV	cso				
		1034kPa 38 C		1 361	Г	01 211		anuiaciu	1161		D/IN	Sz		Sz	Co.	Date	Y/N	Y/N	Сараспу			
		1034KFA 36 C		-		<del></del>																
Tube Side Other																	Y/N Y/N	Y/N Y/N				
Н	Other	Mata	ui a l	Namin	-14	C A		Datina			4.4		01/0	0-1- 4					1			
ţ	Ole - II	Material		Nomin	ıaı t	CA		Retire	) I	Lowest t	ττ		OK?	Calc. t	-min		Comn	ient				
Components	Shell												Y 🗆 N	<u> </u>								
oc	Head												Y 🗆 N									
m	Channel										ļ		Y 🗆 N									
ၓ	Tube					1							Y 🗆 N			Cnooif.						
Ų	Other					_							Y□N			Specify:						
Orientation				_	Foundation				Gravel 🗖 Timbers						Cor	Condition Good						
Support		□ Saddle □		Seal-			□F	ove	Condition:													
		Skirt		Free of debris Comment: Condition:																		
		Hang	Secure Comment: Condition:																			
		Other		Specify:	5																	
Overall		General	Conditio	n: Good									Ele	ctrical gro	unding	🖵 Direct 🖸	Indire	ct 🖳 l	None			
Ext. Surface		Painte	ed 垣 In	sulated [	☐ Fire	e-proofed	$\Box$ C	ladded	Other				Cor	ndition: G	ood							
Ext. Fixtures		☐ Ladde	er 🔲	Platform	(s) 🛚	Other:				Cor	nditior	n:										
														ep Holes F	Present							
		Commer														тор ттолоо т						
Davit Arm		Present Greased Double nutted Condition																				
		Treeding Greater Board Harrisa										Com	mont:									
Piping				Supported    Joined per						ns Properly					nment:							
		Inlet	I Suppor	Supported  Joined per			r code	e fron				l Coated	Com	nment:								
		☑ Outle	Support	pported								Coated	Com	nment:								
		☑ Drain		upported 🛮 🗹 Joined per				r code 🛮 🗹 Free			ks	☑ <sub>Wel</sub>	l Coated	Com	nment:							
						oorted	☑ Joi	ined per code			Free from leaks/kinks			Comment:								
		Process Fluid Identifie					direc	tion mar	ked	Comm	mment: See comment below											
Valves		☑Manual Isolation Value				Free	from	leaks	eaks Comment:													
		☐ Auton	ontrol Va	lve	☐ Free			eaks Comment:														
			ain plugg		Commer	nt	1															
Gauges Sight Glass		☑ Pressure			Reading:			Condition: New														
		☐ Temperature		Reading:			Condition:															
		☐ Fluid Level		Reading:			Condition															
Inspection Summary		Vessel legs are welded to the foundation. Drain valve is a tripping hazard.																				
					F	Recomm	ende	ed Acti	ons:								NCR/	IDR				
R۱	N WO∼Drair	ı valve ne	eds to he	e dealt w						lv wel	I.							-				
	Dian		10 51		40		י פייייו			.,												
								_	ESSEL S	STATU	JS											
Int	egrity Statu	us Suitable for Continued Service    ✓ Yes    No    Immediate Repairs Required    Future Repair												irs Require	d 🛚	Repla	се					
Inv	entory Stat	us 🔽 I	n Servic		ьΓ	Out of Se	rvice	_ □ ∘	urnlus		ran	$\square$ $\wedge$	rtion Itom	s Comple	ted							



Additional Notes on continuation page: (Report:						
Inspection Interval: 5 yrs OR Changed to: yrs.						
IPV/IBPV Certificate #: 113						
PSV Interval: yrs OR Changed to: yrs.						
IPV/IBPV Certificate #:						

Signature of In-Service Inspector: Brad White