



Client >	FUELLED	A# >	243000	Head Mat. >	SA-516-70	OD >	36"
Report# >	4830-2	Ser. # >	8723-102	Head Th. >	1.316"	Year >	1987
Work Order# >	-	CRN# >	H1399.2	Shell Mat. >	SA-516-70	PWHT >	YES
Equipment >	HORIZONTAL SEPARATOR	MAWP >	1300 PSI	Shell Th. >	1.375"	RT >	RT-1
Manufacturer >	ENERFLEX	Temp >	300 F	Cor. Allow. >	.0620"	Cap. >	-



VESSEL EXTERIOR

Component	Condition	Comments
Shell	Good	Some random corrosion throughout the vessel prior to latest paint coating. Minor. Deepest - 1/64"
Heads	Good	
Coating	Good	A few random areas had the paint rubbed off. Minor
Insulation	N/A	
Manway	N/A	
Nozzles	Good	

VESSEL INTERIOR

Component	Condition	Comments
Shell	N/A	No manway for internal inspection
Heads	N/A	
Coating	N/A	
Scale	N/A	
Attachments	N/A	
Nozzles	N/A	

EXTERNAL INSPECTION

Component	Condition	Comments
Grounding	N/A	Vessel is not installed, all below items are not applicable
Ladders	N/A	
Foundation	N/A	
Supports/Bolting	N/A	
Leaks/Seeps	N/A	
Press. Gauge	N/A	Range: Operating Pressure:
Temp. Gauge	N/A	Range: Operating Temp:

PIPING

Component	Condition	Comments
Bolting	N/A	No piping is attached to the vessel
External Cond.	N/A	
Insulation	N/A	
Valves	N/A	
Supports	N/A	
Auto Shutoffs	N/A	



Alpine NDT Services Inc.

Client >	FUELLED	A# >	243000	Head Mat. >	SA-516-70	OD >	36"
Report# >	4830-2	Ser. # >	8723-102	Head Th. >	1.316"	Year >	1987
Work Order# >	-	CRN# >	H1399.2	Shell Mat. >	SA-516-70	PWHT >	YES
Equipment >	HORIZONTAL SEPARATOR	MAWP >	1300 PSI	Shell Th. >	1.375"	RT >	RT-1
Manufacturer >	ENERFLEX	Temp >	300 F	Cor. Allow. >	.0620"	NB# >	-

SAFETY DEVICES

Component	Condition	Comments
Fusible Links	N/A	Vessel is not installed, all below items are not applicable
Emergency Shutoff	N/A	
Excess Flow	N/A	
PRV Location	N/A	Threaded or Flanged
Barriers	N/A	

PRESSURE RELIEF DEVICES

		Comments
Quantity	N/A	No PRV's are installed on the vessel
Serial #'s	N/A	
Model #'s	N/A	
Manufacturer	N/A	
Set Pressure	N/A	
Capacity	N/A	
Size	N/A	
Service Date	N/A	
Service Company	N/A	
Service Tag#	N/A	

API Inspector: Tim Rosenkranz
 Certification # 35312

Signature: 
 Company: Alpine NDT Services

Date: Sept. 24, 2024



Alpine NDT Services Inc.

Client >	FUELLED	A# >	243000	Head Mat. >	SA-516-70	OD >	36"
Report# >	4830-2	Ser. # >	8723-102	Head Th. >	1.316"	Year >	1987
Work Order# >	-	CRN# >	H1399.2	Shell Mat. >	SA-516-70	PWHT >	YES
Equipment >	HORIZONTAL SEPARATOR	MAWP >	1300 PSI	Shell Th. >	1.375"	RT >	RT-1
Manufacturer >	ENERFLEX	Temp >	300 F	Cor. Allow. >	.0620"	Cap. >	-

Empty rectangular area for notes or additional data.

Empty rectangular area for notes or additional data.

Empty rectangular area for notes or additional data.



Alpine NDT Services Inc.

Client >	FUELLED	A# >	243000	Head Mat. >	SA-516-70	OD >	36"
Report# >	4830-2	Ser. # >	8723-102	Head Th. >	1.316"	Year >	1987
Work Order# >	-	CRN# >	H1399.2	Shell Mat. >	SA-516-70	PWHT >	YES
Equipment >	HORIZONTAL SEPARATOR	MAWP >		Shell Th. >	1.375"	RT >	RT-1
Manufacturer >	ENERFLEX	Temp >		Cor. Allow. >	.0620"	Cap. >	-

Empty section for notes or additional data.

Empty section for notes or additional data.

Empty section for notes or additional data.