

Fueled Pump Package Inspection Report

Provided by Surepoint

October 30, 2024

1. Power End Inspection


- 1.1 – Lube oil is clean
- 1.2 - Crankshaft condition is good
- 1.3 - End play is good
- 1.4 - Connrod bearings are good

2. Fluid End


- 2.1 – Carbon Steel Fluid End- not sleeved in good condition
- 2.2 – Packing Leak Detection
- 2.3 – Abrasion Resistant valves in good condition
- 2.4 – Plunger lubrication system

3. Building and Skid

- 3.1 - Building is in good condition
- 3.2 – Sump has fluid and crystalized salt



Power End





Fluid End





