

Existing Equipment Integrity Assessment Report

Date July 27, 2023

Page 1 of 1

Inspec	ct Date: Ju	ıly 27, 2023	Client:	Yoho	Resources	6		District: I	nga, E			SD: 10-19-087-23	sW6
Facility	y:				C	lient Ref #				IF	RM Ref #	P004	
Equipr	ment #:				Description	Glyco (Botto		al Coole	r	Jur#	N/A	CRN: N/A	
MFR:	Air-X-C	hangers			Mfr S/N:	0558	572.2	Mfr I	Date:	2005	Stat	tus: Operating	
	or Service	e: Yes nspection has					PSV m N/A	eets Co	de:	N/A	PSV set	t at or below MAW	P: N/A
		/ Verified:	N/A	•	u.	•	1 1 7 7						
		ation / PSV C			red	I	No						
					Curre	nt Insp	ection	Result	ts				
VE UT PSV	2023-07 VE UT completed by RJC Integrity VE The caulking at the piping to building interfaces have failed. UT DUE 2025 PSV NA Assessment completed by Aaron Bischoff VE reviewed; no major concerns noted. AJB												
					Past P	SV Ser	vicing	Resul	lts				
					Past Ins	pection	Histo	ory Res	ults				
No h	istorical ins	pections				-							
					NEXT ND	E & Ins	specti	on Metl	hods				
\boxtimes	VE] VI			\boxtimes	UT	2025			BW	
	WF] LF				ET				HIC	
	CREEP			BHN				CDR				MFL	
Othe	er:												
No h	istorical ITI	D			Previ	ious Ins	specti	on Plar	n				
	iotorioai i i												
						xt Insp							
Prima NDE UT o	ary Areas o examination n 20 #-yea	ge mechanisms of degradation: I ons (type & exte r DUE 2025 next inspection:	Bottom he ent): VE or	ad and p	iping elbows			alized pitti	ing pos	ssible.			
Qualifie Inspec		on Bischoff Qu	ıal: IBP	V#644	Signatu	re:				Report	date: 17-N	Report ov-2023 status: I	Final

R036b REVIEWED 2020



Report No.:

Client	Yo	ho R	Resources Inspec								or Ryan Cadieux							Date	Ju	ly 27, 2	2023
District Inga, BC Surface LSD 10-19-087-2								3W6	W6 Downhole LSD												
Vessel Data																					
Vessel D	esc	riptio	on	Glycol	Aeria	l Cool	er (Bot	tom)		R	Т	No	PW	PWHT □ Yes ☒ No Partial □							
A# / NB	#	N/A	1			Seri	al#	0555	72.2				CRN# N/A								
Manufa	Manufacturer Air-X-Changers											Manway□ Yes						⊠No Size:			
Owner Tag N/S Skid Comp Skid #0509									0903		OD					Length					
MAWP 1 ⊠Shell □ Tube 14			14	psi		kPa	MAV	VT		С	300	F	ſ	МD	MT		С	-20	F		
MAWP 2 □Shell□Tube				psi		kPa	MAV	VT		С		F	ſ	MD	MT		С		F		
Operatir	ng P	ressı	ıre		psi			kPa	Opei	rating	Temp)	C F F					ange Rating # N/A			
Process	Con	ditio	ns: 🛭	⊠ Swe	et 🗆	Sour						Inte	rnal (Coatii	ng:		N/S				
Product	: [Gas		Water	☐ Air		ffluent	: ⊠ C	Other: G	lycol /	Oil										
PSV #1 Data																					
Owner ID/Tag									PSV	Loca	tion										
Manufa	ctur	er								Mod	lel#										
Serial #								Mfg	Date	!											
CRN# Code																					
Set Pressure ⊠psi □kPa								□kPa	Service Company												
Capacity scfm					gpı	_		Other	Serv	ervice Date			·				ce Tag #				
Inlet Size NPS Type □THD□FLG #								_	et Siz		NPS Type □THD□ FLG #										
Inlet Block Valve ☐Yes ☐No Locked/Sealed ☐ Yes ☐ No											ck Val		Yes 🗆	Nc)	Locke	d/Seale				
Seal Intact:									Prop	erly :	Suppo	orted						Yes		No	
Drainage																					
Discharg							O, atmo	sphere	<u>:</u>												
PSV Ger	nera	I Cor	nditio	on/Com	ments	·															
									PSV #2	Data	<u> </u>										
Owner I	D/T	ασ							1 3 ν π 2		Locat	tion									
Manufa										Mod											
Serial #		-								_	Date										
CRN#											Code										
Set Pressure					□psi		□kPa	Serv	rvice Compan			ny									
Capacity scfm gpm				n		Other	Serv	Service Date			r					ce Tag #					
Inlet Size	e			NPS	Туре	e 🗆 Th	ID 🗆 FL	G #		Outl	et Siz	e.		NF	Pς	Ī	Гуре [□THD	☐ FL	G #	
Inlet Bloc	ck Va	lve	□Y	es 🗆 No	Lo	cked/S	ealed [Yes	□ No	Outlet Block Valve Yes No Locked/Sealed Yes No								□No			
Seal Intact: ☐ Yes ☐ No									Properly Supported												
Drainage (i.e. pocketed, missing tailpipe):																					
	Discharge Piped to (i.e. flare line, pop tank, FKO, atmosphere):																				
PSV General Condition/Comments:																					

QTI-VIN-001 Rev.1 Page 1 of 6



Report No.:

External Inspection	Good	Fair*	Poor*	N/A	External Inspection	Good	Fair*	Poor*	N/A
Skid Foundation/Supports	X				Ladder(s)/Platforms				X
Insulation/Cladding		X			Gauges				X
Vessel Nameplate	X				Valves				X
Vessel Saddle/Skirt/Supports/Bolts	X				Piping	X			
Vessel Paint/Coating	X				Flanges/Bolting (per Code)				X
Vessel Shell				X	Piping Support	X			
Vessel Head	X				Catadyne Heaters (zip ties)				X
Nozzles	X				Surface Staining of Ground	X			
Pig Traps (ie evidence of hammering)				X	Signage (i.e. stand alone)				X
Regulators Vented	⊠ Yes	· □	No		Vessel/Skid Grounded	⊠ Yes		No	

^{*} Fair and Poor selections require comments

Comments:											
1. The caulking at the piping to building interfaces have failed.											
☑In Service ☐Idle ☐Blinded/Disconnected	Signature	Ryan Cadisux	Date	July 27, 2023							

QTI-VIN-001 Rev.1 Page 2 of 6



Vessel External Inspection PHOTOS

Report No.:





QTI-VIN-001 Rev.1 Page **3** of **6**



Report No.:





QTI-VIN-001 Rev.1 Page **4** of **6**



Report No.:





QTI-VIN-001 Rev.1 Page **5** of **6**



Report No.:



QTI-VIN-001 Rev.1 Page **6** of **6**