

Existing Equipment Integrity Assessment Report

Date July 2023

Page 1 of 1

Inspect Date: July 27, 2023 Clie	ent: Yono Resources	District: Inga, BC	LSD: 10-19-087-23006									
Facility:	Client Ref #	IF	RM Ref # P004									
Equipment #:	Description: Glycol	Aerial Cooler (Top) Jur#	N/A CRN: N/A									
MFR: Air-X-Changers	Mfr S/N: 055572	2.1 Mfr Date: 2005	Status: Operating									
Online PSV Inspection has been	n completed: N//	V meets Code: N/A	PSV set at or below MAWP: N/A									
'	N/A											
Repair / Alteration / PSV Calibra	ation Required No											
	Current Inspec	tion Results										
2023-07 VE UT completed by RJC Int VE The caulking at the piping to build UT DUE 2025 PSV NA Assessment completed by Aaron Bisc	ding interfaces have failed.	rne noted A IR										
Assessment completed by Adron bisc	mon ve reviewed, no major conce	ms noted. AJB										
	Past PSV Servi	cing Results										
rasi rov servicing nesults												
	Past Inspection F	listory Results										
No historical inspections												
	NEXT NDE & Insp	ection Methods										
	□ VI	☑ UT 2025	□ BW									
☐ WF	☐ LF	☐ ET	☐ HIC									
☐ CREEP	□ BHN	CDR	☐ MFL									
Other:			<u> </u>									
	Previous Insp	ection Plan										
No historical ITP												
	Next Inspec	tion Plan										
Expected damage mechanisms and lot Primary Areas of degradation: Bottom NDE examinations (type & extent): VE UT on 20-year DUE 2025 Preparation for next inspection: None PSV: NA	n head and piping elbows. E on 5-year Interval – due July 2028	. Localized pitting possible.										
Qualified	IBPV#644 Signature:	Report	Report date: 17-Nov-2023 status: Final									



Report No.:

Client	Yo	ho R	esou	irces	Inspector Ryan Cadieux							Date	Ju	ly 27, 2	2023					
District	Ir	nga,	ВС		Su	ırface	LSD	10-1	.9-087-2	3W6	Downhole LSD					LSD				
Vessel Data																				
Vessel Description Glycol Aerial Cooler (Top) RT No PWHT ☐ Yes									'es [⊠ No	Pa	rtial 🗆								
A# / NB# N/A Serial # 055572.1 CRN # N/A																				
Manufacturer Air-X-Changers												Manway□ Yes ⊠No Size:								
Owner T	ag	g N/S Skid Comp Skid #0509								0903			OD	DD			Length			
MAWP 1	L	⊠Sh	ell□	Tube	14	psi		kPa	MAV	VT		С	300	F	М	IDMT	C -20 F			F
MAWP 2	2	□Sh	ell□	Tube		psi		kPa	MAV	VT		С	F MDMT C					F		
Operatir	ng Pi	essu	ıre		psi			kPa	kPa Operating Temp C F Flange Rating # N							# N	I/A			
Process	Con	ditio	ns: 🛭	⊠ Swe	et 🗆	Sour						Inte	rnal (rnal Coating: N/S						
Product: □Gas □ Water □ Air □ Effluent ⊠ Other: Glycol / Oil																				
PSV #1 Data																				
Owner ID/Tag									PS۱	/ Loca	tion									
Manufa	anufacturer								Мо	del #										
Serial #			Mfg Date																	
CRN#																				
Set Pres	sure		⊠psi □kPa Service Company																	
Capacity				scfm		gpı			Other	Service Date Service Tag #										
Inlet Size			NPS Type □THD□FLG# Outlet Size NPS Type □THD□ FLG#																	
	Inlet Block Valve ☐ Yes ☐ No Locked/Sealed ☐ Yes ☐ No Outlet Block Valve ☐ Yes ☐ No Locked/Sealed ☐ Yes ☐ N																			
Seal Intact:									No											
Drainage																				
Discharg							O, atmo	sphere	<u>e):</u>											
PSV General Condition/Comments:																				
									PSV #2	Dat	<u> </u>									
Owner I	D/Ta	οσ							1 3 ν π2	1	/ Locat	tion								
Manufa											del #	LIOII								
Serial #	- Cur										g Date									
CRN#								Cod	_											
Set Pres	Set Pressure □psi □kPa							Ser	vice Company											
Capacity	,			scfm		gpr	n		Other	Ser	vice D	ate				Servic	e Tag #	‡		
Inlet Size	e			NPS	Туре	e 🗆 TH	ID 🗆 FL	G #		Out	tlet Siz	e.		NP	S	Туре	□THD	☐ FL	G#	
Inlet Block Valve ☐ Yes ☐ No Locked/Sealed ☐ Yes ☐ No Outlet Block Valve ☐ Yes ☐ No Locked/Sealed ☐ Yes ☐ No									No											
Seal Intact: ☐ Yes ☐ No Properly Supported ☐ Yes ☐ No								No												
Drainage	e (i.e	. pock	eted,	missing	ailpipe)	:														
Discharg	ge Pi	ped	to (i.e	e. flare lir	ie, pop t	ank, FK	O, atmo	sphere	e):											
PSV General Condition/Comments:																				

QTI-VIN-001 Rev.1 Page 1 of 6



Report No.:

External Inspection	Good	Fair*	Poor*	N/A	External Inspection	Good	Fair*	Poor*	N/A
Skid Foundation/Supports	X				Ladder(s)/Platforms				X
Insulation/Cladding		X			Gauges				X
Vessel Nameplate	X				Valves				X
Vessel Saddle/Skirt/Supports/Bolts	X				Piping	X			
Vessel Paint/Coating	X				Flanges/Bolting (per Code)				X
Vessel Shell				X	Piping Support	X			
Vessel Head	X				Catadyne Heaters (zip ties)				X
Nozzles	X				Surface Staining of Ground	X			
Pig Traps (ie evidence of hammering)				X	Signage (i.e. stand alone)				X
Regulators Vented	⊠ Yes	s 🗆	No		Vessel/Skid Grounded	⊠ Yes		No	

^{*} Fair and Poor selections require comments

Comments:												
1. The caulking at the piping to building interfaces have failed.												
☑In Service ☐Idle ☐Blinded/Disconnected	Signature	Ryan Cadisux	Date	July 27, 2023								


QTI-VIN-001 Rev.1 Page 2 of 6



Vessel External Inspection PHOTOS

Report No.:





QTI-VIN-001 Rev.1 Page **3** of **6**



Report No.:





QTI-VIN-001 Rev.1 Page 4 of 6



Report No.:





QTI-VIN-001 Rev.1 Page **5** of **6**



Report No.:



QTI-VIN-001 Rev.1 Page **6** of **6**