

Client	Yoho Resources Insp					Inspec	tor Bob Stanhope					Date	De	ec 20 ,	2018				
District	Inga Surface LS				e LSD	10-1	10-19-087-23W6			Downhole LSD									
Vessel Data																			
Vessel Description Fuel Gas Separator RT 2 PWHT ☐ Yes ☒ No Partial																			
A# / NB# A0577529 S					Sei	Serial # 149-35-07					Manway				Yes	⊠No	Siz	e:	
Owner Tag					Skid					OD 1			10"			Length 52"			
MAWP 1 ⊠Shell□Tube 1			1480	psi	osi		MA	MAWT		С	100	F	MD	MT		С	-20	F	
MAWP 2 □Shell□Tube				Psi		kPa	kPa MAV		С			F	MDMT			С		F	
				psi	kPa Oper				rating	ating Temp 15 C F F				Fla	ange Rating # 600				
Process Conditions: $oximes$ Sweet $oximes$ So					Sour	•	Internal Coating: No						None	ie					
Product: ⊠Gas □ Water □ Air □ Effluent □ Other:																			
PSV Data																			
Owner ID/Tag							PSV Location Shell												
Manufac	Manufacturer Taylor									Model # 82E5351311									
Serial # 070671-3									Mfg	Date	ate								
CRN # 0G1316.2C									Cod	ode NB/UV									
Set Pressure 250					⊠psi □kPa					Service Company Kings Energy									
Capacity 838 scfm					gr							Servic	e Tag ‡	‡					
Inlet Size 1" NPS				Туре	e 🗵 T	HD□F	LG#		Out	Outlet Size 1" NPS				s .	Туре	$\boxtimes THD$	☐ Fl	.G #	
Inlet Block Valve □Yes ⊠No				Lo	Locked/Sealed ☐ Yes ☒ No				Outl	Outlet Block Valve Yes No Locked/Sealed Yes No							⊠ No		
Seal Intact:						⊠ Yes □ No				Properly Supported						⊠ Yes □ No			
Drainage (i.e. pocketed, missing tailpipe):																			
Discharge Piped to (i.e. flare line, pop tank, FKO, atmosphere): Atmosphere																			
PSV General Condition/Comments: PSV is located on vessel shell and is in the vertical plane. PSV verified set at or below the MAWP of vessel. PSV does not require calibration as per API 510 and a 5-year service interval has been given. PSV nameplate complete, legible, and secure. Seal wires intact and secure, valve well supported with no body damage noted. Service report has not been reviewed. No valves in the critical path. No internal inspection of the valve was completed. PSV condition satisfactory and is considered fit for continued service under present conditions. PSV capacity verified and deemed adequate																			
																			г
External I	nspection	on		Go	od	Fair*	Poor	* N/	4	Exter	nal Ins	pectio	n	Go	od	Fair*	Po	or*	N/A
Skid Found	Skid Foundation/Supports			X					La	Ladder(s)/Platforms									X
Insulation/Cladding							X	Ga	Gauges			X							
Vessel Nameplate			Х					Va	Valves			Χ							
Vessel Saddle/Skirt/Supports/Bolts			, X					Pip	oing				Χ						
Vessel Paint/Coating			Х					Fla	inges/l	Bolting	(per Co	de)	Χ						
Vessel Shell				X				Pip	oing Su	ipport			X						
Vessel Head			Х					Ca	Catadyne Heaters (zip ties)		ies)	Χ							
Nozzles			Х					Su	Surface Staining of Ground		und	X							
Pig Traps (ie evidence of hammering)									Sig	nage (i.e. star	nd alon	e)	X					
Regulators Vented				\boxtimes	⊠ Yes □ No					Vessel/Skid Grounded ⊠ Yes					N	lo			

* Fair and Poor selections require comments

Comments:

The vessel is located inside a building. The nameplate is legible and secure. The vessel is identified by an A-number and a serial number stamped on the nameplate. The heads, shell, nozzles, and bolting appear in good condition. There



supported by a full skirt and is welded. The vessel is fully painted, and the particle does not have structural attachments. connections. The vessel is considered Piping: The associated piping appears in general supported adequately by clamps. The	The associated piping appears in generally good condition. There is no damage or distortion on piping. The piping is supported adequately by clamps. The primary piping is mainly welded and flanged, and the secondary piping is mainly threaded. The piping is fully painted and the paint is in good condition. There is no external corrosion or									
MIn Service Uldle Ullinded/Disconnected	Cignaturo	9	Date	Doc 20, 2019						

PHOTOS

"Your success is our goal" Rev 1.0 www.integrityrisk.ca















