

	STATIC E	QUIPMEN	IT INSPEC	TION REPO	ORT - Exhibit	# 300a	
COMPANY: 1	Tourmaline				E-TEGRIT	Y JOB #:	
	gan / Earring nlet Separator	_Facility: <u>5</u>	-14	Lsd	05-14-082-08V	/6M Skid:	Inlet building 2
VESSEL DATA							
Equip#:		Serial #:	P8078.0	1 ABSA#:	0642464	CRN #:	K6964.1
	ss Manufacturino	Code/Div.:	8 div 1	Para:		Code Stamp:	
Yr. Built: 2008		Size:			Actual Est	Insulated:	No
Service: Sour		PWHT:	HT	R.T.:	1	Repairs:	No
Nominal Thickr	ness & Material	_					
Top Head:).5" Ma	terial: SA 5	16-70 c	.A. 0.125"		Reasons:	
Bottom Head:					_		
Shell:).5"	SA 5	16-70	0.125"	_	Status: 🗸	IN SERVICE
Shell:					_		OUT OF SERVICE
Tube:	_		_		_	Manway	S
_	_		_		_	Reason for I	
						✓ PLANNED	- IN SERVICE
Operating Pres: 7	70 psi	C	perating Tem	_{p:} 20 f	_	PROBLEM	INVESTIGATION
MAWP Shell: 2	285 ✓	Psi kPa	Temp:	100	F C	PROCESS	CHANGE
MAWP Tube:		Psi kPa	Temp:		F C	COMMISS	SIONING
Comments:							
PSV INFORMA	TION						
Location:		V	 ✓ s		S S =	SHELL SIDE	
Manufacturer:	Taylor		т			TUBE SIDE	
Serial #:	013284-35		P		P P=	PIPING	
PSV #:	UVL 19966F				<u> </u>		
CRN:	0G01316.2C				 Inlet Isol	ation valves se	ealed open:
Model:	83K7721341				<u></u>	YES	NO 📝 N/A
Set Press:	285 psi				Outlet Is	olation valves	sealed open:
Capacity:	9528 scfm				<u></u>	YES	NO N/A
Code Stamp:	UV						
Inlet Size (mm):	3"						
Outlet Size (mm):	3"						
Conn Type (F/T):	F/F						
Serviced By:	Unified valve						
Last Service Date	2/28/2012				<u></u>		
	tion Requested By:	Colin Sh	aver		Inspection Date:	Nov 4, 201	15
Inspection Performed By: Josh Wierenga				Certification # 000854			
Chief I	nspector: Terry Mo	Connell			Certification #: 00	0049	

EXTERNAL VISUAL INSPECTION

Remedial Action	Access & Coverage	<u>Other</u>	Shell TOP BOTTOM
No Action Required Paint Repairs Repair Weld - S.R. Repair Weld - No S.R. Grind Out See Comments	Poor Cleaning Partial Int. Inspection External Inspection NDE Inspection UT RT BH PT Other	Ladders/Handrail/ Walkway Damage Nameplate Secure	Good Condition N External Corr. Pitted - Light Pitted - Severe Scaled - Light Scaled - Heavy Blistered N/A Insulated
Nozzles	External Protection	<u>Welds</u>	<u>Supports</u>
Good Condition Cracked Scaled Plugged Poor Welding Leaking Seal Face Corrosion Bolts Missing/Loose/ Damage Partial Int. Inspection	Good Condition Fireproofing Cracked Insulation Damaged Paint Deteriorated Corrosion Under Insulation (CUI) Asbestos YES NO Insulated YES NO	Good Condition Corroded Cracked Broken Poor Quality	Good Condition Distorted Cracked Broken Poor Installation Bolts Missing/ Loose/Damaged Support Ring Damaged N/A
Heads TOP	Heads BTM	Pressure Gauge	Vessel Repad
MORTH WEST Good Condition External Corrosion Pitted - Light Pitted - Severe Scaled - Light Scaled - Heavy Blistered	Good Condition External Corrosion Pitted - Light Pitted - Severe Scaled - Light Scaled - Heavy Blistered	Glass Intact YES NO Within Operating Limits YES NO Obvious Leaks YES NO	N/A ✓ Vent Holes 1 2 ✓ Plugged YES ✓ NO
PIPING - PSV	PIPING - INLET	PIPING - OUTLET/DRAIN	
Good Condition External Corrosion Pitted Supported Welded Threaded Fittings Deadlegs	Good Condition External Corrosion Pitted Supported Welded Threaded Fittings Deadlegs	Good Condition External Corrosion Pitted Supported Welded Threaded Fittings Deadlegs	

EXTERNAL VISUAL INSPECTION

OBSERVATIONS:				
✓ Vessel is in Good Condition				
 ✓ API 510 External Inspection confirmed the equipment is fit for continued servic NOT FIT FOR SERVICE, DETAILS BELOW 				
Vessel is in good condition Vessel was stamped by ABSA earlier this year. Inspection comments:				
Service PSV. No other concerns noted.				
Inspection interval Grade 1 set at 3 years JA 02/04/2016				
RECOMMENDATIONS:				
Service PSV				

PICTURES:









