123 - 8805 Resources Road Grande Prairie, AB T8V 3A6

phone: 780-933-9700 Ismith@lanceinspections.com



Informational Visual Inspection Report

Informational Visual Inspection_ SN-KOTK-GB-T75-12241 oct2025

Page 1 of 10

INNISFAIL, ALBERTA

Client: Fuelled	Facility: CNRL Wapiti Field	Date: Oct. 1, 2025
LSD: 03-26-66-07W6M (CNRL)	Equipment Inspected: FKOD SN: KOTK-GB-T75-12241	LII Job #: 13788

<u>Job Scope</u>: To perform external and internal informational visual inspections on a horizontal Flare Knockout Drum, SN: KOTK-GB-T75-12241. This FKOD is out of service and currently located at the CNRL 03-26-66-07W6M location.

MADE IN CANADA Welding & Manufacturing Ltd SERIAL NUMBER YEAR BUILT NOMINAL DIAMETER NOMINAL LENGTH NOMINAL CAPACITY INTERIOR THICKNESS EXTERIOR THICKNESS EXTERIOR THICKNESS EXTERIOR THICKNESS SHELL 36 DESIGN PRESSURE COATING INT. CELE 65

FKOD Skid Overview and Data Pate

Informational Results Summary:

- VE: An informational external visual inspection was performed on all accessible external components. There
 were no external concerns identified during inspection. See the attached pages of this report for more
 detailed results and inspection photos.
- VI: An informational internal visual inspection was not performed as the manway was not opened at the time
 of inspection.
- UT: A UT baseline survey was conducted on the FKOD shell, heads, nozzles and external piping. No concerns identified during UT inspection. See Lance Inspections UTS report (UT_SN KOTK-GB-T75-12241 oct2025) for CML locations and thickness results.

Technician: Dave Ellis (API 510 #118975) (CGSB UT-2, MT-2, PT-2 #21762) (SNT-TC-1A UT-II, MT-II, PT-II)

Assistant: Karsyn Utz

Client Representative: Will Van Weelden (Fuelled)

An Ale

123 - 8805 Resources Road Grande Prairie, AB T8V 3A6 phone: 780-933-9700

Ismith@lanceinspections.com



Informational Visual Inspection Report

Informational Visual Inspection_ SN-KOTK-GB-T75-12241 oct2025

Page 2 of 10

<u>Visual Inspection Information – Flare Knockout Drum SN: KOTK-GB-T75-12241)</u>

Note: This FKOD was out of service at the time of inspection.


- Nameplate: Sticker nameplate is firmly fastened and legible.
- o **Foundation/Support:** This FKOD is supported by two saddle supports welded to the skid floor. No visible signs of damage. According to the nameplate data this FKOD is a double walled tank.
- o External Surface: This FKOD is carbon steel, painted, and uninsulated. No visible signs of damage.
- o **Insulation:** This FKOD is uninsulated and inside of a utilidor building. There are gaps in the silicone seals where the piping protrudes through the ceiling.
- Ladder/Platform: Thers is no ladder or platform associated with this FKOD.
- External Piping: All visible external piping is uninsulated and painted. All piping appears to be properly supported with no visible signs of damage.
- Nozzles: No visible signs of damage or deflection. All nozzles have a 150# flange rating.
- Manway: This FKOD has a 20" manway with no notable external deficiencies.
- Overpressure Protection: There is no PSV associated with this FKOD.
- External Components: This FKOD has two Catadyne heaters, one sight glass, one air quality monitoring system, and a truck out box installed. The bottom of the truck out box is corroded. There is also an attachment on the top 4" nozzle that extends approximately 8' above the roof.
- o Internal Components: The manway of this FKOD was not open at the time of inspection.
- Comments: According to the data plate, this FKOD has an interior shell with a nominal thickness of 9.5mm and an exterior shell with a nominal thickness of 4.8mm. With the UT performed from the exterior shell and the manway not opened for internal visual access, this informational assessment was only performed externally on the secondary containment.



Informational Visual Inspection Report

Report Informational Visual Inspection_ SN-KOTK-GB-T75-12241_oct2025

Page 3 of 10








Informational Visual Inspection Report

Report Informational Visual Inspection_ SN-KOTK-GB-T75-12241_oct2025

Page 4 of 10













Informational Visual Inspection Report

Report Informational Visual Inspection_ SN-KOTK-GB-T75-12241_oct2025

Page 5 of 10









Informational Visual Inspection Report

Report
Informational Visual Inspection_
SN-KOTK-GB-T75-12241_oct2025

Page 6 of 10











Informational Visual Inspection Report

Informational Visual Inspection_ SN-KOTK-GB-T75-12241_oct2025

Page 7 of 10

<u>Visual Inspection Photos (Site/Building/Dimensions) – Flare Knockout Drum SN: KOTK-GB-T75-12241</u>











Informational Visual Inspection Report

Report
Informational Visual Inspection_
SN-KOTK-GB-T75-12241_oct2025

Page 8 of 10

<u>Visual Inspection Photos (Site/Building/Dimensions) – Flare Knockout Drum SN: KOTK-GB-T75-12241</u>



123 - 8805 Resources Road Grande Prairie, AB T8V 3A6 phone: 780-933-9700

. Ismith@lanceinspections.com



Informational Visual Inspection Report

Report
Informational Visual Inspection_
SN-KOTK-GB-T75-12241_oct2025

Page 9 of 10

<u>Visual Inspection Photos (Site/Building/Dimensions) – Flare Knockout Drum SN: KOTK-GB-T75-12241</u>



123 - 8805 Resources Road Grande Prairie, AB T8V 3A6 phone: 780-933-9700

Ismith@lanceinspections.com



Informational Visual Inspection Report

Informational Visual Inspection_ SN-KOTK-GB-T75-12241_oct2025

Page 10 of 10

Flare Knockout Drum SN: KOTK-GB-T75-12241 Nameplate

