



101, 56 Cuendet Industrial Way, Sylvan Lake, AB T4S 0B6

Field Inspection Report - Long_Run 172957_08/22/2007_UT_External

Vessel Number	172957	Vessel Name	NGL BULLET	Province	Alberta
District	TREVOR J'S FIELD	LSD	05-10-033-26W4	Location	WIMBORNE
Method	UT	Access	External	Cleaning	
Inspection Date (mm/dd/yyyy)	08/22/2007	Inspection Interval (months)	72	Next Inspection (mm/dd/yyyy)	08/22/2013
CRN	9156.3214	Skid Number	NO	Service	Sweet
Internal Access	YES	Internal Coating	No	Status	IN SERVICE
MAWP (PSI)	250	MAWP (kPa)	1723.7	Outstanding NCRs	0
MAWT (°C)	66	MAWT (°F)	150.8		

General

Safety Valves

PSV P95925 Shell side. Set pressure: 250 PSI / 1723.7 KPa. MAWP: 250 PSI / 1723.7 KPa. Capacity: 10203 SCFM / 288.92 m3/min.

PSV P95926 Shell side. Set pressure: 250 PSI / 1723.7 KPa. MAWP: 250 PSI / 1723.7 KPa. Capacity: 10203 SCFM / 288.92 m3/min.

PSV P95927 Shell side. Set pressure: 250 PSI / 1723.7 KPa. MAWP: 250 PSI / 1723.7 KPa. Capacity: 10203 SCFM / 288.92 m3/min.

PSV P95928 Shell side. Set pressure: 250 PSI / 1723.7 KPa. MAWP: 250 PSI / 1723.7 KPa. Capacity: 10203 SCFM / 288.92 m3/min.

External Condition

Refer to the VT external inspection reported in this database as part of the through inspection.

Internal Condition

The vessel was UT inspected for wall loss.

Hunt Inspections's Ultrasonic Corrosion Survey Project #C30082, as reported on Drawing # 138, noted vessel thickness readings to be above ASME Section VIII, Div. 1 code requirements at time of inspection. The calculated retirement date is 2027 at the MAWP of the vessel.

The associated piping was also inspected with no notable wall loss recorded



101, 56 Cuendet Industrial Way, Sylvan Lake, AB T4S 0B6

Field Inspection Report - Long_Run

172957_08/22/2007_UT_External

Recommendations

Next inspection is 6 years or 1/2 remaining life, whichever is less.

Suitable to be returned to Service	Yes	Suggested Inspection interval (Months)	72
Repairs are still required	No		
John Bourne Cert 000193 Inspector		Signature	11/15/2007 Date (mm/dd/yyyy)

Pictures

-No pictures for this inspection-