

## Field Inspection Report - Long\_Run 172957\_04/01/2003\_UT\_External

<b>Vessel Number</b>	172957	<b>Vessel Name</b>	NGL BULLET	<b>Province</b>	Alberta
<b>District</b>	CENTRAL ALBERTA	<b>LSD</b>	05-10-033-26W4	<b>Location</b>	WIMBORNE
<b>Method</b>	UT	<b>Access</b>	External	<b>Cleaning</b>	
<b>Inspection Date (mm/dd/yyyy)</b>	04/01/2003	<b>Inspection Interval (months)</b>	48	<b>Next Inspection (mm/dd/yyyy)</b>	04/01/2007
<b>CRN</b>	9156.3214	<b>Skid Number</b>	NO	<b>Service</b>	Sweet
<b>Internal Access</b>	YES	<b>Internal Coating</b>	No	<b>Status</b>	In Service
<b>MAWP (PSI)</b>	250	<b>MAWP (kPa)</b>	1723.7	<b>Outstanding NCRs</b>	0
<b>MAWT (°C)</b>	66	<b>MAWT (°F)</b>	150.8		

### General

### Safety Valves

Insert PSV Protection Here

### External Condition

### Internal Condition

MTL TESTING INC. UT SURVEY AS NOTED ON DWG# 021 SHOWED ALL READINGS TO BE ABOVE CODE REQUIREMENTS AT THE TIME OF INSPECTION.

### Recommendations

<b>Suitable to be returned to Service</b>	Yes	<b>Suggested Inspection interval (Months)</b>	48
<b>Repairs are still required</b>	No		



101, 56 Cuendet Industrial Way, Sylvan Lake, AB T4S 0B6

## Field Inspection Report - Long\_Run 172957\_04/01/2003\_UT\_External

John Bourne Cert 000193 <b>Inspector</b>	<b>Signature</b>	08/30/2004 <b>Date (mm/dd/yyyy)</b>
---	------------------	--

### Pictures

-No pictures for this inspection-	
-----------------------------------	--