

FORM: IMS001 – Devon Standard Inspection Form

Equipment:			
District:	Fairview	Equipment Name:	Inelt Sep
Plant / Area:	Puskwaskau	Equipment Number:	PUS-4021A
LSD:	3-26-74-1W6	Manufacturer:	Petro
Functional Block (Process Unit):	Inlet Separator Unit	Manufacture Serial Number:	5828-20
Equipment Type:	Horizontal Sep	Provincial Registration Number:	A-3174858
CRN:	N1538.2		
Inspection Personnel:			
Inspection Company:	Devon	Extent of Inspection:	Full Internal
Name of Inspector:	Jason McGovern	Date of Inspection:	June 17, 2009
Inspection Summary:			
<ul style="list-style-type: none"> - Full internal inspection was completed. Pitting noted as described below. - External inspection revealed no relevant findings. 			
Inspection Details:			
<ul style="list-style-type: none"> - Internal pitting was noted from 5 to 7 o'clock - Deepest pit was 0.045" in depth, 1/4" in dia. Located just west of manway, seen in the attached photo - Baffle plate has no indications - Inlet deflector plate has no indications - Demister pad was very clean. It was not removed for inspection. - Boot had scattered pitting to the same depth as the shell. - All welds were free of corrosion and cracking - All nozzles were free of corrosion. 			
Repairs:			
<ul style="list-style-type: none"> - None 			
NDE Reports:			
<ul style="list-style-type: none"> - None - 			
Recommendations:			
<ul style="list-style-type: none"> - None. - 			
Certification:			
Inspector Signature:		Provincial Certification Number:	
Date:	June 18, 2009		

Pictures:**Picture 1 (Desc.):****Picture 2 (Desc.)****Picture 3 (Desc.):****Picture 4 (Desc.)****Picture 5 (Desc.):****Picture 6 (Desc.)****Note:**

1. Contractor inspector to submit complete inspection form in PDF or word with pictures attached as JPG.
2. Individual pictures must be in a format that is less than 2 MB.