

Field Inspection Report - Long_Run 568797_11/19/2019_UT_External

Vessel	568797	Vessel	BULLET	Province	Alberta
Number		Name			
District	NORTHERN - AB	LSD	07-04-071-18W5	Location	SNIPE LAKE
Method	UT	Access	External	Cleaning	Good
Inspection	11/19/2019	Inspection	60	Next	11/19/2024
Date		Interval		Inspection	
(mm/dd/yyyy)		(months)		(mm/dd/yyyy)	
CRN	A223.4.5.3.2.8.0	Skid	N/A	Service	SWEET
		Number			
Internal	Yes	Internal	No	Status	In Service
Access		Coating			
MAWP (PSI)	250	MAWP	1723.7	Outstanding	0
, ,		(kPa)		NCRs	
MAWT (°C)	53.33	MAWT (°F)	128		

General

2019 Ultrasonic Corrosion Survey.

Safety Valves

PSV P110884 Shell side. Set pressure: 250 PSI / 1723.7 KPa. MAWP: 250 PSI / 1723.7 KPa. Capacity: 6515 SCFM / 184.48 m3/min.

External Condition

Refer to the latest VT External inspection report as part of this thorough inspection.

Internal Condition

The vessel was UT inspected for wall loss.

Mountain West Services Ultrasonic Corrosion Survey Project #C52617, noted all vessel thickness readings to be above ASME Section VIII, Div. 1 code requirements at time of inspection. See attached report.

The associated piping was also inspected with no notable wall loss recorded.

Next inspection is 5 years or 1/2 remaining life, whichever is less.

Recommendations

Recommend 5 year interval for next UT inspection. Ultrasonic Corrosion Survey due again in 2024.

101, 56 Cuendet Industrial Way, Sylvan Lake, AB T4S 0B6

Field Inspection Report - Long_Run 568797_11/19/2019_UT_External

Suitable to be returned to Service	Yes	Suggested Inspection interval (Months)	60
Repairs are still required	No		
Duane Paetkau ABSA ISBPV:000087, API 570:24422, NB Cert. 222			02/24/2020 Date
Inspector		Signature	(mm/dd/yyyy)

Pictures

-No pictures for this inspection-	