	STATIC EQUIPMENT	INSPECTION	ON REF	PORT	- Exhibi	t # 300	
COMPANY:	TRYDENT		SIGMA JOB #:				
District:	CORBETT Facility:		Lsd	15-	10-62-6	5 6 5 Skid:	TGC 2187
	REFRIDERAMI S						
VESSEL DATA					14051		
Equip#:	Serial #:		_ABSA#:	53	7287	CRN#:	
			Para:			Code Stamp	o:
	Size:			Actual	Est.	Insulated:	
Service:			_R.T.:			Repairs:	
Nominal Thick	ness & Material						
Head:	Material:	C.A				Reasons:	
Head:				_			
Shell:						Status: Z	IN SERVICE
Shell:							OUT OF SERVICE
Channel HD:				_		Manway:	YES NO
Channel SH:				_		Reason for	Inspection
Boot HD:				_		PLANNED	- IN SERVICE
Boot SH:	/			_ /		PROBLEM	INVESTIGATION
MAWP Shell:		Temp:	150°	_ ☑ F	С	PROCESS	CHANGE
MAWP Tube:	Psi kPa	Temp:		F	С	COMMISS	IONING
Comments							
PSV INFORMA	TION						
Location:	TOP OF COOLER S	T P				S 🗌 T 🗌 P	S = SHELL SIDE
Manufacturer:	COSSOLIDATED	20					T = TUBE SIDE
Serial #:	TP 12155						P = PIPING
PSV #:							4
CRN:	065530.52	· ·					
Model:	190566						
Set Press:	250 PSi						
Capacity:	24245 2n3/1R						
Status:	in SERVICE						
Inlet Size (mm):	3.5"	12					
Outlet Size (mm)	4.5"	,					
Conn Type (F/T):	T	\d					
Serviced By:	VAISGAL						
Last Service Date	e: 0cr/07						
I/L Isolation valve	es sealed open: YES NO		YES	NO			
O/L Isolation valv	ves sealed open: YES NO		YES	NO			
Comments							

EXTERNAL VISUAL INSPECTION

7	ABSA#: 53/27 SIGMA JOB #:					
Remedial Action	Access & Coverage	Other	Shell TOP			
 No Action Required Paint Repairs Repair Weld - S.R. Repair Weld - No S.R. Grind Out See Comments 	Poor Cleaning Partial Int. Inspection External Inspection NDE Inspection MT UT RT BH PT Other	Ground Cable ☐ Y ☐ N Ladders/Handrail/ Walkway Damage Nameplate Secure ☐ N Nameplate Legible ☐ N See Attached Pictures	Good Condition External Corr. Pitted - Light Pitted - Severe Scaled - Light Scaled - Heavy Blistered N/A Insulated			
Nozzles	External Protection	Welds	Supports			
Good Condition Cracked Scaled Plugged Poor Welding Leaking Seal Face Corrosion Bolts Missing/Loose/ Damage Partial Int. Inspection	Good Condition Fireproofing Cracked Insulation Damaged Paint Deteriorated Corrosion Under Insulation (CUI) Asbestos YES NO Insulated YES	Good Condition Corroded Cracked Broken Poor Quality	☐ Good Condition ☐ Distorted ☐ Cracked ☐ Broken ☐ Poor Installation ☐ Bolts Missing/ Loose/Damaged ☐ Support Ring Damaged ☐ N/A			
Heads TOP	<u>Heads</u> ☐ втм	Pressure Gauge	Vessel Repad			
MORTH WEST Good Condition External Corrosion Pitted - Light Pitted - Severe Scaled - Light Scaled - Heavy Blistered	Good Condition External Corrosion Pitted - Light Pitted - Severe Scaled - Light Scaled - Heavy Blistered	Glass Intact YES NO Within Operating Limits YES NO Obvious Leaks YES NO	N/A Vent Holes 1 2 Plugged YES NO			
PIPING - PSV	PIPING - INLET	PIPING - OUTLET/DRAIN				
Good Condition External Corrosion Pitted Supported Welded Threaded Fittings Deadlegs	Good Condition External Corrosion Pitted Supported Welded Threaded Fittings Deadlegs	Good Condition External Corrosion Pitted Supported Welded Threaded Fittings Deadlegs				
Inspection Requested By:						
Inspection Performed By: Chief Inspector:		Certification #: Certification #:				

EXTERNAL VISUAL INSPECTION ABSA #: 537287 SIGMA JOB#:						
SUMMARY OBSERVATIONS (128 Character max.):						
VESSEL IN GOOD CONDITION.						
SUMMARY RECOMMENDATIONS (128 Character max.):						
API 510 External Inspection confirmed the equipment is fit for continued service NOT FIT FOR SERVICE, DETAILS BELOW						
NOT FIT FOR SERVICE, DETAILS BELOW						
DETAILED OBSERVATIONS (Memo Field):						
5.						
DETAILED RECOMMENDATIONS (Memo Field):						