STATIC EQUIPMENT INSPECTION REPORT - Exhibit # 300								
COMPANY:	TR: DENT			SIG	GMA JOB#:			
District:	CORBETT Facility:		Lsd	15-10-6:	2-6~5Skid: 7	EC 2187		
	GAS-GAS							
VESSEL DA	TA				)			
Equip#:	Serial #:		ABSA#:	537286	CRN#:			
Manuf:	Code/Div.:		Para:		Code Stamp	:		
Yr. Built:	Size:			Actual Es	t. Insulated:			
Service:	PWHT:		R.T.:		Repairs:			
Nominal Thi	ckness & Material							
Head:	Material:	C.A		_	Reasons:			
Head:				_				
Shell:				_	Status:	IN SERVICE		
Shell:				_		OUT OF SERVICE		
Channel HD: _					Manway: $\Box$	YES NO		
Channel SH: _					Reason for	Inspection		
Boot HD:				-	PLANNED	- IN SERVICE		
Boot SH:				_ /	PROBLEM	INVESTIGATION		
MAWP Shell:_		Temp: _	150'	_ □ F □ C	PROCESS	CHANGE		
MAWP Tube:_	Psi kPa	Temp: _		FC	COMMISSI	ONING		
Comments _								
PSV INFORM					25 20 20 20 20			
Location:	TOP of SOUTH SHELL S	_ T			STP	S = SHELL SIDE		
Manufacturer:	CONSOLIDATED	_				T = TUBE SIDE		
Serial #:	TN90060	_				P = PIPING		
PSV#:		_						
CRN:	06 55 30 . 52	_						
Model:	1912GC-3	_						
Set Press:	8963 KPA	_						
Capacity:	2/3/6 nm3	_						
Status:	in SERVICE	_						
Inlet Size (mm)		_						
Outlet Size (mr		_						
Conn Type (F/	n:							
Serviced By:		_						
Last Service Date: 3 / 06								
I/L Isolation valves sealed open: YES NO YES NO								
O/L Isolation valves sealed open: YES NO YES NO								
Comments								

## **EXTERNAL VISUAL INSPECTION** SIGMA JOB #: ABSA#: Shell TOP **Remedial Action** Access & Coverage **Other** ВОТТОМ ☐ Good Condition See Comments No Action Required Poor Cleaning Ground Cable Y N External Corr. Paint Repairs Partial Int. Inspection ☐ Pitted - Light Repair Weld - S.R. External Inspection Ladders/Handrail/ NDE Inspection ☐ Pitted - Severe Repair Weld - No S.R. Walkway Damage Nameplate Secure N Scaled - Light Grind Out □ мт 🗹 от Scaled - Heavy Nameplate Legible N N See Comments RT BH See Attached Pictures Blistered PT Other N/A Insulated Wolde Sunnorte Mozzloc External Protection

NOZZIES	External Protection	weigs	Supports
Good Condition Cracked Scaled Plugged Poor Welding Leaking Seal Face Corrosion Bolts Missing/Loose/ Damage Partial Int. Inspection	Good Condition Fireproofing Cracked Insulation Damaged Paint Deteriorated Corrosion Under Insulation (CUI) Asbestos YES NO Insulated YES	Good Condition Corroded Cracked Broken Poor Quality	Good Condition Distorted Cracked Broken Poor Installation Bolts Missing/ Loose/Damaged Support Ring Damaged N/A
Heade Tren	Heads BIM	Pressure Gauge	Vessel Repad
Heads TOP NORTH WEST  Good Condition External Corrosion Pitted - Light Pitted - Severe Scaled - Light Scaled - Heavy Blistered	Good Condition External Corrosion Pitted - Light Pitted - Severe Scaled - Light Scaled - Heavy Blistered	Glass Intact YES NO Within Operating Limits YES NO Obvious Leaks NO	N/A Vent Holes  1 2 Plugged YES NO
PIPING - PSV	PIPING - INLET	<b>PIPING - OUTLET/DRAIN</b>	
Good Condition External Corrosion Pitted Supported Welded Threaded Fittings Deadlegs	Good Condition External Corrosion Pitted Supported Welded Threaded Fittings Deadlegs	Good Condition External Corrosion Pitted Supported Welded Threaded Fittings Deadlegs	
Inspection Requested By: Inspection Performed By: Chief Inspector:		Inspection Date Certification #: Certification #:	:

## **EXTERNAL VISUAL INSPECTION** ABSA #: 537286 SIGMA JOB#:\_\_\_ SUMMARY OBSERVATIONS (128 Character max.): VESSEL IN GOOD CONDITION. SUMMARY RECOMMENDATIONS (128 Character max.): API 510 External Inspection confirmed the equipment is fit for continued service NOT FIT FOR SERVICE, DETAILS BELOW **DETAILED OBSERVATIONS (Memo Field):** DETAILED RECOMMENDATIONS (Memo Field):