

STATIC EQUIPMENT INSPECTION REPORT - Exhibit # 300				
COMPANY: Trident	SIGMA JOB #:			
District: Ft. Assiniboine Facility: Corbbett Comp Lsd 15-10 Item Insp.: Low Temp Separator	0-62-6WS Skid: TEL 2187			
Item Insp.: Low Temp Separator				
VESSEL DATA				
Equip#:	7290 CRN#:			
Manuf: Code/Div.: Para:	Code Stamp:			
Yr. Built: Size: 36" × 180" Actual	Est. Insulated: Yes			
Service: Sweet PWHT: ^0 R.T.:	Repairs:			
Nominal Thickness & Material				
Head: Material: C.A	Reasons:			
Head:				
Shell:	Status: IN SERVICE			
Shell:	OUT OF SERVICE			
Channel HD:	Manway: ☐ YES ☐ NO			
Channel SH:	Reason for Inspection			
Boot HD:	PLANNED - IN SERVICE			
Boot SH:	PROBLEM INVESTIGATION			
MAWP Shell: 1300 Psi kPa Temp: 150 F	F C PROCESS CHANGE			
MAWP Tube: Psi kPa Temp: F	C COMMISSIONING			
Comments				
PSV INFORMATION				
Location: STTP	STTP S=SHELL SIDE			
Manufacturer:	T = TUBE SIDE			
Serial #:	P = PIPING			
PSV #:				
CRN:				
Model:				
Set Press:				
Capacity:				
Status:				
Inlet Size (mm):				
Outlet Size (mm):				
Conn Type (F/T):				
Serviced By:				
Last Service Date:				
I/L Isolation valves sealed open: YES NO YES NO				
O/L Isolation valves sealed open: YES NO YES NO				
Comments PSV Removed due to turn arou	nd			

EXTERNAL VISUAL INSPECTION

ABSA#: 537290 SIGMA JOB #:			
Remedial Action	Access & Coverage	Other	Shell TOP BOTTOM
No Action Required Paint Repairs Repair Weld - S.R. Repair Weld - No S.R. Grind Out See Comments	Poor Cleaning Partial Int. Inspection External Inspection NDE Inspection MT UT RT BH PT Other	See Comments Ground Cable Y N Ladders/Handrail/ Walkway Damage Nameplate Secure N Nameplate Legible N See Attached Pictures	Good Condition External Corr. Pitted Light Pitted - Severe Scaled - Light Scaled - Heavy Blistered N/A Insulated
Nozzles	External Protection	Welds	Supports
Good Condition Cracked Scaled Plugged Poor Welding Leaking Seal Face Corrosion Bolts Missing/Loose/ Damage Partial Int. Inspection	Good Condition Fireproofing Cracked Insulation Damaged Paint Deteriorated Corrosion Under Insulation (CUI) Asbestos YES NO Insulated YES	Good Condition Corroded Pracked Broken Poor Quality	Good Condition Distorted Cracked Broken Poor Installation Bolts Missing/ Loose/Damaged Support Ring Damaged N/A
Heads TOP	Heads BTM	Pressure Gauge	Vessel Repad
□ NORTH □ Good Condition □ External Corrosion □ Pitted - Light □ Pitted - Severe □ Scaled - Light □ Scaled - Heavy □ Blistered	Good Condition External Corrosion Pitted - Light Scaled - Light Scaled - Heavy Blistered	Glass Intact YES NO Within Operating Limits YES NO Obvious Leaks YES NO	N/A Vent Holes 1 2 Plugged YES NO
PIPING - PSV	PIPING - INLET	PIPING - OUTLET/DRAIN	
Good Condition External Corrosion Pitted Supported Welded Threaded Fittings Deadlegs	Good Condition External Corrosion Pitted Supported Welded Threaded Fittings Deadlegs	Good Condition External Corrosion Pitted Supported Welded Threaded Fittings Deadlegs	
Inspection Requested By: Inspection Performed By: Chief Inspector:	ECHO	Inspection Date: Certification #: Certification #:	Aug 31 2010

ABSA #: SIGMA JOB#:
SUMMARY OBSERVATIONS (128 Character max.):
VESSEL IN GOOD CONDITION.
Vessel is fully insulated
SUMMARY RECOMMENDATIONS (128 Character max.):
API 510 External Inspection confirmed the equipment is fit for continued service NOT FIT FOR SERVICE, DETAILS BELOW
NOTH TOR SERVICE, SETALO SELOW
DETAILED OBSERVATIONS (Memo Field):
DETAILED RECOMMENDATIONS (Memo Field):