STATIC EQUIPMENT INSPECTION REPORT - Exhibit # 300								
COMPANY:	TRIDENT		SIGMA JOB #:					
District:	CORBETT Facility:		Lso	15-	10-62	6 Skid:	TEC 2187	
Item Insp.:	DEETHAN	IZER						
VESSEL DA								
Equip#:	Serial #:		ABSA#:	5	31124	CRN #:		
			Para:			Code Stam	p:	
	Size:			Actual	Est.	Insulated:		
Service:	PWHT:		R.T.:			_Repairs:	No.	
Nominal Thi	ckness & Material							
Head:	Material:	C.A		_		Reasons:		
Head:				_				
Shell:				_		Status:	IN SERVICE	
Shell:				_			OUT OF SERVICE	
Channel HD:				-0		Manway:	YES NO	
Channel SH:				_			Inspection	
Boot HD:						PLANNED	- IN SERVICE	
Boot SH:				/		PROBLEM	INVESTIGATION	
MAWP Shell:		Temp: _	400"		С	PROCESS		
MAWP Tube:	Psi kPa	Temp: _		_ ∐ F	∐ c	COMMISS	SIONING	
Comments								
PSV INFORI								
Location:	South SIDE of VESSE S]T∅P _				S 🗌 T 🗌 P	S = SHELL SIDE	
Manufacturer:		_					T = TUBE SIDE	
Serial #:	TP05862	_					P = PIPING	
PSV#:	22							
CRN:	06 5530.52	_						
Model:	19567mc-2-F1-GS							
Set Press:	550 PSi	_						
Capacity:	9/02 m3/AR	_						
Status:	in SERVICE	_						
Inlet Size (mm): 2.375	_						
Outlet Size (m	m): 2.875'	_						
Conn Type (F/		_						
Serviced By:	VAL SEAL	_						
Last Service D		-		Unio				
I/L Isolation va	lives sealed open: YES NO		H 4380500 D N	NO				
O/L Isolation v	alves sealed open: YES NO		YES _	NO				
Comments								

EXTERNAL VISUAL INSPECTION ABSA#: 53/124 SIGMA JOB #:____ Shell Remedial Action Access & Coverage **Other**

 No Action Required □ Paint Repairs □ Repair Weld - S.R. □ Repair Weld - No S.R. □ Grind Out □ See Comments 	Poor Cleaning Partial Int. Inspection External Inspection NDE Inspection MT	See Comments Ground Cable Y N Ladders/Handrail/ Walkway Damage Nameplate Secure N Nameplate Legible N See Attached Pictures	Good Condition External Corr. Pitted - Light Pitted - Severe Scaled - Light Scaled - Heavy Blistered N/A Insulated
Nozzles Good Condition Cracked Scaled Plugged Poor Welding Leaking Seal Face Corrosion Bolts Missing/Loose/	Good Condition Fireproofing Cracked Insulation Damaged Paint Deteriorated Corrosion Under Insulation (CUI) Asbestos YES	Welds Good Condition Corroded Cracked Broken Poor Quality	Supports Good Condition Distorted Cracked Broken Poor Installation Bolts Missing/ Loose/Damaged Support Ring
Damage Partial Int Inspection Heads TOP NORTH WEST Good Condition	Insulated YES NO Heads BTM SOUTH EAST Good Condition	Pressure Gauge Glass Intact YES NO	Damaged N/A Vessel Repad N/A Vent Holes
External Corrosion Pitted - Light Pitted - Severe Scaled - Light Scaled - Heavy Blistered	External Corrosion Pitted - Light Pitted - Severe Scaled - Light Scaled - Heavy Blistered	Within Operating Limits YES NO Obvious Leaks YES NO	2 Plugged YES NO
Good Condition External Corrosion Pitted Supported Welded Threaded Fittings Deadlegs Inspection Requested By:	Good Condition External Corrosion Pitted Supported Welded Threaded Fittings Deadlegs	PIPING - OUTLET/DRAIN Good Condition External Corrosion Pitted Supported Welded Threaded Fittings Deadlegs Inspection Date:	
Inspection Performed By:		Certification #:	
Chief Inspector:		Certification #:	

EXTERNAL VISUAL INSPECTION ABSA #: 53/124 SIGMA JOB#:_____ **SUMMARY OBSERVATIONS (128 Character max.):** VESSEL IN GOOD CONDITION. **SUMMARY RECOMMENDATIONS (128 Character max.):** API 510 External Inspection confirmed the equipment is fit for continued service NOT FIT FOR SERVICE, DETAILS BELOW DETAILED OBSERVATIONS (Memo Field): DETAILED RECOMMENDATIONS (Memo Field):