

PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD: b-49-C/93-P-2 Date: June 16th 2014 SAP Equipment ID: 66156026

205. 5 10 6/60 1 2 Batc. Galle 10 32511 6/11 240pHottle.									
VESSEL STATIC DATA									
Plant	Plant Wolverine De-Hy			Op Unit FH-NB-001			System		
Prov. Insp. # 595438			CRN U8368.213			Equip Tag #			
Equipment Description L/P Flar			re KO Drum				Serial # 007095-01		
Manufacturer Tornado Technologies						Vessel Class			
Internal Access: NO Description:					Year Built 2009				
MAWP 50		PSI		@ 212		°F	MDMT -4	9 °F	
CODE: U			RT:	1			PWHT: YES		
Diameter Length OAL mm / in									
Shell Mat	I	Thickr			ness			Corr Allowance	
Head Mat	ı		Thickness			Corr Allowance			
Nozzle Mat	I		Thickness			Corr Allowance			
Internal Coating: NO			Internal Clad:			Capacity			
Manway: NO			Inspection Port :						
Nozzle Rating ANSI		ANSI	Painted: YES			Insulated: YES			
				PROCESS I	DATA				
Product Desc	ription								
Operating Pre	essure								
PSV STATIC DATA									
Serial No.	Location	Se Press		Capacity SCFM / Lbs/Hr / GPN		ıfacturer	Model / Type	Service Date	
INSPECTION SUMMARY									

This vessel sits elevated on steel pilings along the elevated flare line before the flare stack. The external surfaces are painted and the coating was in good visible condition. The vessel is normally insulated but the insulation was stripped so that a full UT inspection of the lower shell could be performed. Prior to this T/A, corrosion was identified on the inlet and outlet piping associated with this vessel. This piping was replaced and internally coated. This vessel is not internally coated and does not have a manway. The vessel was secured to its foundation and grounded as required. The data plate was legible and intact. The shell, heads, saddles and accessible nozzles were in good condition, with no signs of leaks, deformation or damage present at time of inspection. The vessel was isolated from service as part of the 2014 turn around. The vessel was opened and cleaned for inspection (UT and camera). Pictures were taken through the 4" inlet and outlet nozzles. Visible and active corrosion along the lower shell and inlet nozzle was visible. A 5" UT grid was done on the lower shell and thickness readings were also taken on the inlet nozzle. The lowest thickness reading taken in the scanned areas of the lower shell was 0.338" (Shell nominal 0.375"). L/T corrosion rate is 0.009"/year. Vessel was put into service in 2010.

RECOMMENDATIONS

All of the inlet and outlet piping has been internally coated, so there is a concern that corrosion may be amplified in this vessel since it is not. This vessel shall be removed from service, cleaned thoroughly and re-inspected in two years. A corrosion rate for its new service can be determined then.

NONCONFORMANCES / INSPECTION DEFICIENCIES							
	INSPECTION PLAN	INING					
Inspection Strategy	Availability	Inspection Interval					
Inspection Date	Date of Last Inspect	Date of Next Inspect					
							
	REPORT CERTIFIC	ATION					
The signatures below certify that inspections/tests have been completed in accordance with the identified inspection strategy and that the specified equipment is considered fit for service until the date of next inspection.							
Inspected by	Warren Fast Husky Integrity Inspector Grande Prairie District	Date June 27, 14					



PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD: b-49-C/93-P-2 Date: June 16th,2014 SAP Equipment ID: 66156026

DETAILED INSPECTION VISUAL EXTERNAL

ID	Description	Condition	Location	NCR	Comments
V1	General Other (Please Explain)				
V2	General Corrosion				
V3	General Leaks				
V4	Vibration				
V5	Dissimilar Flange Rating				
V6	Ladder/Stairway				
V7	Heads	GOOD			
V8	Guy Wires				
V9	Electrical Ground	GOOD			
V10	Painted Inactive Corrosion				
V11	Coating/Painting	GOOD			
V12	Expansion Joint or Bellows				
V13	Gauge/Site Glass				
V14	Shell	GOOD			
V15	Jacket				
V21	Support Other (Please explain)				
V22	Foundation	GOOD			
V23	Anchor Bolts	GOOD			
V24	Saddle/Skirt	GOOD			
V25	Davit				
V26	Fireproofing				
V31	Connections Other (Please explain)				
V32	Small Branches				
V33	Nozzles	GOOD			
V34	Manways	GOOD			
V35	Reinforcing Pads	GOOD			
V36	Inadequate Thread Engagement				
V37	Bolting				
V38	Flanges	GOOD			
V39	Leak Clamps				
V41	Insulation Other (Please explain)				
V42	Damage				
V43	Penetrations				
V44	Insulation Jacket				
V45	Banding				
V46	Seals/Joints				
V51	Relief Devices Other (Please explain)				
V52	Corrosion				
V53	Leaks				
V54	Restricted Inlet/Outlet				
V55	Manual Operation Lever				




PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD: b-49-C/93-P-2 Date: June 16th,2014 SAP Equipment ID: 66156026

DETAILED INSPECTION UT THICKNESS

UT THICKNESS READINGS TAKEN ON LOWER SHELL, LOWER HEADS AND INLET NOZZLE ALL READINGS ARE THE LOWEST IN THE AREA SCANNED

AREA	NOM.	1	2	3
LOWER SHELL				
Α	0.375"	0.370"	0.353"	0.355"
В	0.375"	0.356"	0.342"	0.348"
С	0.375"	0.355"	0.338"	0.360"
D	0.375"	0.362"	0.365"	0.361"
E	0.375"	0.371"	0.363"	0.361"
F	0.375"	0.372"	0.362"	0.359"
INLET HEAD				
4	0.313	0.344"		
5	0.313	0.335"		
6	6 0.375" 0.336"		Shell side of Shell-Head butt weld	
OUTLET HEAD				
7	0.375"	0.359"	Shell side of Shell-Head butt weld	
8	0.313	0.300"		
9	0.313	0.360"		
INLET NOZZLE				
4" XH	0.337"	0.311"		





PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD: b-49-C/93-P-2 Date: June 16th,2014 SAP Equipment ID: 66156026

PHOTOS





PRESSURE VESSEL & COLUMN INSPECTION REPORT





PRESSURE VESSEL & COLUMN INSPECTION REPORT





PRESSURE VESSEL & COLUMN INSPECTION REPORT





PRESSURE VESSEL & COLUMN INSPECTION REPORT C/93-P-2 Date: June 16th,2014 SAP Equipment ID: 66156

LSD: b-49-C/93-P-2 SAP Equipment ID: 66156026



Inlet Nozzle Side



PRESSURE VESSEL & COLUMN INSPECTION REPORT



Inlet Nozzle



PRESSURE VESSEL & COLUMN INSPECTION REPORT



Outlet Nozzle Side



PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD: b-49-C/93-P-2 Date: June 16th,2014 SAP Equipment ID: 66156026

Looking down from Inlet Nozzle





PRESSURE VESSEL & COLUMN INSPECTION REPORT C/93-P-2 Date: June 16th,2014 SAP Equipment ID: 66156026

LSD: b-49-C/93-P-2

Picture taken with camera held inside of outlet nozzle

