Husky Energy


Tank Inspection Report

Location: BSM Tank	Yard Lloydminster AB.	Tank Type: Sto	orage	Date: Jul.27.2020
Mfg: Foremost Ind.	Year b	_{lt:} 2013	_{S/N:} 29203-2	cap: 1000 _{bы}
Floor Thk: 1/4"	Shell Thk: 1/4	-3/16"	Roof Thk: 3/16	6"
Requisitioned by: Christ	ina Dueck	Approver: Jamie	Carte	Approver Code: 2Z-10011081
wo #. 605009	PO#. 8401456382	CC:	SAP#	1000175849

ID	Item	Yes	Good	N/A	See Notes	
	GENERAL					
T1	Other (Please Explain)					
T2	Corrosion	Х			1	
T3	Leaks			Х		
T4	Vibration			Х		
T5	Dissimilar Flange Rating			х		
T6	Ladder/Stairway	Х	х			
T7	Platform			х		
T8	Electrical Ground			Х	2	
T9	Cathodic Protection			Х		
T10	Painted Inactive Corrosion			Х		
T11	Coating/Painting			Х		
T12	Level Gauge	X	х			
T13	Bottom			Х	2	
T14	Secondary Containment	1		Х	2	
T15	Shell	X	х			
T16	Roof	×	×			
T17	Agitator/ Mixer	1		Х	1	
	SUPPORTS					
T31	Other (Please Explain)			7.00		
T32	Foundation	<u> </u>		X	2	
T33	Anchor Bolts	 		х		
T34	Windgirders	-		Х		
104	CONNECTIONS					
T41	Other (Please explain)					
T42	Small Branches	×	×			
T43	Nozzles	X	×			
T44	Pipe Manifolds	+	-	×		
T45	Swing Lines	-		X		
T46	Manways/Hatches	×	X			
T47	Reinforcing Pads	X	X			
		<u> </u>	 	X		
				^		
	Inadequate Thread Engagement	- v	V			
T49	Bolting	X	X			
T48 T49 T50	Bolting Flanges	X	×			
T49 T50	Bolting Flanges Leak Clamps			х		
T49 T50 T51	Bolting Flanges Leak Clamps INSULATION			X		
T49 T50 T51	Bolting Flanges Leak Clamps INSULATION Other (Please explain)	X		X	2	
T49 T50 T51 T61 T62	Bolting Flanges Leak Clamps INSULATION Other (Please explain) Damage	x	×	x	3	
T49 T50 T51 T61 T62 T63	Bolting Flanges Leak Clamps INSULATION Other (Please explain) Damage Penetrations	X			3	
T49 T50 T51 T61 T62 T63 T64	Bolting Flanges Leak Clamps INSULATION Other (Please explain) Damage Penetrations Jacket	x	×	X	3	
T49 T50 T51 T61 T62 T63 T64 T65	Bolting Flanges Leak Clamps INSULATION Other (Please explain) Damage Penetrations Jacket Banding	X X X	x		3	
T49 T50 T51 T61 T62 T63 T64 T65	Bolting Flanges Leak Clamps INSULATION Other (Please explain) Damage Penetrations Jacket Banding Seals/Joints	x	×	X	3	
T49 T50 T51 T61 T62 T63 T64 T65	Bolting Flanges Leak Clamps INSULATION Other (Please explain) Damage Penetrations Jacket Banding Seals/Joints RELIEF DEVICE	X X X	x	X	3	
T49 T50 T51 T61 T62 T63 T64 T65 T66	Bolting Flanges Leak Clamps INSULATION Other (Please explain) Damage Penetrations Jacket Banding Seals/Joints RELIEF DEVICE Other (Please explain)	X X X	x	X	3	
T49 T50 T51 T61 T62 T63 T64 T65 T66 T7t T72	Bolting Flanges Leak Clamps INSULATION Other (Please explain) Damage Penetrations Jacket Banding Seals/Joints RELIEF DEVICE Other (Please explain) Corrosion	X X X	x	X X	3	
T49 T50 T51 T61 T62 T63 T64	Bolting Flanges Leak Clamps INSULATION Other (Please explain) Damage Penetrations Jacket Banding Seals/Joints RELIEF DEVICE Other (Please explain)	X X X	x	X	3	

ID	Item	Yes	Good	N/A	See Notes
	GENERAL				
T1	Other (Please Explain)				
T2	Corrosion			Х	
T3	Erosion			Х	
T4	Distortion	Х			
T5	Blisters			х	
T6	Deposits			Х	
T7	Welds	Х	х		
T8	Nozzles	X	х		
T9	Shell	Х	х		
T10	Roof	Х	х		
T11	Floor	Х	х		
	GENERAL				
T21	Other - Firetube	Х	х		
T21	Other - Anodes			х	
T22	Annular Ring			Х	
T23	Sump			Х	
T24	Roof Supports			Х	
T25	Thermowells	Х	х		
T26	Metallic Linings			Х	
T27	Non Metallic Linings			х	
T28	Internal Steam Coil / other Piping	Х	х		
T29	Level Gauge	х	х		
	Other Welded Attachements			Х	
Bac	kwelding Req'd			Х	

Notes
"Rusty Seepage" Evident at roof level - Possible Corrosion Under Insulation. Monitor are
Tank is Unhooked and in Boneyard
-Slight "Bulging" of insulation at roof level
Tank is in "As New" condition and has no sign of ever being in service.



Page 2 of 2



NONDESTRUCTIVE INSPECTION REPORT

CA1101-NDT-498

Page 1 of 4

Type of Inspection: VT/UT/MFL Rev:

Test Technique: Visual / UT / thickness inspection | IRISNDT #: LYN2000687 Equipment: DMS GO+, Generator, Grinder, MFE MK IV 72616

Code/Standard: Client Spec.

Client: HUSKY OIL OPERATIONS LIMITED

Location: BSM Tank Yard Lloydminster AB.

Item Inspected: 1000BBL Tank

Date: 2020-Jul-27 WO #: 60723117

PO#: 8401456382

A MFL / Visual / UT inspection was carried out as requested on (1) - 1000BBL Tank


@ BSM Tank Yard Lloydminster AB.

Tank sn# 29203-2

Recommendations / Notes of inspection :

-Slight "Bulging" of insulation at roof level. Rusty seepage evident, possible sign of Corrosion Under Insulation in area - monitor roof level. There were no areas requiring immediate attention at this time - Tank is fit to return to service on a 5yr. inspection interval. -There was no sign of any underside corrosion evident with MFL floor scan inspection.

Tank in in "As New" condition - No sign of being in service





For additional inspection results see attached inspection sheets.

REQ: Christina Dueck

APP:Jamie Carte

2Z-10011081

Inspection Limitation(s):

Unit#:1000	Ki	ometers:	Consumables:	Interpretation by:			
In:	Out:	Hrs:	 MIN	Sheldon (Print)	Trachuk	SNT-TC-1A: _ C.G.S.B. #:	2 UT-2
In:	Out:	Hrs:		a		U.G.S.D. #	(Level)
Personnel:				(Sign)		C.G.S.B #: _	11405
Sheldon Trachuk				Client Representative:	(Print)		
Marshall Lundell				I am in full agreement with report contents	(Fills)		
				report contents	(Sign)		

5311 - 86 Street NW, Edmonton, Alberta T6E 5T8 Phone (780) 437-4747 Fax (780) 436-4873 Calgary (403) 279-6121 Cold Lake

(780) 875-6455 Lloydminster Barrhead (780) 674-3018 (780) 955-7616 Nisku

Fort McMurray Red Deer

(780) 826-6105 (780) 743-1536 (403) 347-1742 www.irisndt.com

Engineering, Calgary Engineering, Edmonton Rope Access Services

(403) 217-9684 (780) 437-2022 (780) 437-2022


Offices also located in USA and UK



NONDESTRUCTIVE INSPECTION REPORT

CA1101-NDT-498

Page 2 of 4



Slight "Bulging" of insulation at roof level

Rusty seepage evident, possible sign of Corrosion Under Insulation in area - monitor roof level.

IRISNDT #: LYN2000687

Client: HUSKY OIL OPERATIONS LIMITED

Date: 2020-Jul-27 Sheldon Tract

(Sign)

5311 - 86 Street NW, Edmonton, Alberta T6E 5T8 Phone (780) 437-4747 Fax (780) 436-4873

 Calgary
 (403) 279-6121

 Lloydminster
 (780) 875-6455

 Barrhead
 (780) 674-3018

 Nisku
 (780) 955-7616

Cold Lake Fort McMurray Red Deer (780) 826-6105 (780) 743-1536 (403) 347-1742 www.irisndt.com Engineering, Calgary Engineering, Edmonton Rope Access Services Offices also located in USA and UK (403) 217-9684 (780) 437-2022 (780) 437-2022