

Date: Oct. 09, 2014 Report # : IR141009GENi

Plant (	Celtic Co	ompressor	Op Unit	НО	G		System / LSD:	10-08-	-052-23w3	
Equipment #							Asset Type	Scrubber		
Description			Sas Scrubber	Prov. Insp. #		S 09	9268	Serial #	901128-06	j
Manufacturer	En	erflex Systems	s Ltd.	CRN	=	F80	07.213	Year Built	1990	)
MAWP			KPag	- @	149	°C		MDMT	-29	°C
Code			Fluid Service		ıral Gas	_	Sweet	PWHT	No	-
Internal Acce			Insulated	No			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Internal Coat		No
	_		iiisulateu				Descripe Tome	•	g	°C
Operating Pre	essure		-	KPag			Operating Temp	)	-	C
				PSV	DATA					
Serial Number:		69436								
Manufacturer:		Mercer								
Model: Set Pressure	Van	8112421037 1138								
Capacity	Kpa SCFM	608								
Inlet Size	mm	25								
Outlet Size	mm	25								
Service Date:	mm/yyyy	10/2014					,			
Location:	,,,,	Side of FGS								
External:  A visual external inspection performed to the applicable standards did not identify any concerns with the pressure boundary of this equipment, there were no significant deficiencies noted.  This equipment was in service at the time of inspection.  A thorough inspection to verify the equipment's integrity was done by VE and UT.  The nameplate is intact and legible.  No NCR's were issued at this time.  Internal: There was no internal inspection or NDE performed at this time, the scope of work was for an external inspection only.  NDE: The UT readings are within acceptable limits: see the UT readings below.  RECOMMENDATIONS  The Serial # in SAP should be changed to 901128-06.  NONCONFORMANCES / INSPECTION DEFICIENCIES										
Inspection Stra	iteav		Availability	ISPECTIO	N PLAI	INING	Inspection	Interval	<del>5 yrs</del>	4 years
Inspection Date		10/2014	Date of Last I	nspection				xt Inspection	10/2019	,
mapeodon Date	_	10/2014		opeolion				At mapecuon	10/2019	2018
REPORT CERTIFICATION  The signatures below certify that inspections/tests have been completed in accordance with the identified inspection strategy and that the specified equipment is considered fit for service until the date of next inspection.										
VE Inspected	by / Cert	ification #	Guy Normand	API 51	0# 23041	0	0	Date	Oct. 9, 2014	
VI Inspected b								Date		
Reviewed and			Remi Lacasse			1		Date		
Criticality Ass						Ins	pection Planning	Rerun		
Assessed Nex										



Date: Oct. 09, 2014 Report # : IR141009GENi

# DETAILED INSPECTION VISUAL EXTERNAL

	VISUAL EXTERNAL							
l				NCR /				
ID	Description	Condition	Location	IDR	Comments			
		T	T	1				
V1	General Other (Explain)	Good			This equipment was found to be acceptable for continued service.			
					Any deficiencies are noted below.			
1/0		0 1			The nameplate is intact and legible.			
V2	General Corrosion	Good			There is no corrosion present in the areas that were visibly			
1/0		0 1			accessible.			
V3	General Leaks	Good			No leaks were noted.			
V4	Vibration	N/A						
V5	Dissimilar Flange Rating	N/A						
V6	Ladder/Stairway	N/A						
V7	Heads	Good			The heads are in good mechanical condition.			
V8	Guy Wires	N/A						
V9	Electrical Ground	Good			The equipment is grounded through the skid package.			
V10	Painted Inactive Corrosion	N/A						
V11	Coating/Painting	Good			The paint is in fair condition.			
V12	Expansion Joint or Bellows	N/A						
V13	Gauge/Site Glass	N/A						
V14	Shell	Good			The shell is in good mechanical condition.			
V15	Jacket	N/A						
V21	Support Other (Explain)	N/A						
V22	Foundation	N/A						
V23	Anchor Bolts	Good			The anchor bolts are tight and secure.			
V24	Saddle/Skirt	N/A						
V25	Davit	N/A						
V26	Fireproofing	N/A						
V31	Connections Other (Explain)	Good			All piping connections to the vessel are secure.			
V32	Small Branches	Good			The instrumentation tubing is acceptable, no signs of leakage noted.			
V33	Nozzles	Good			All nozzles are thread-o-lets.			
V34	Manways	N/A						
V35	Reinforcing Pads	N/A						
V36	Inadequate Thread	Good			The thread engagement is adequate.			
	Engagement							
V37	Bolting	Good			The studs / nuts are secure.			
V38	Flanges	Good			All flanges are intact with no defects noted.			
V39	Leak Clamps	N/A						
V41	Insulation Other (Explain)	N/A						
V42	Damage	N/A						
V43	Penetrations	N/A						
V44	Insulation Jacket	N/A						
V45	Banding	N/A						
V46	Seals/Joints	N/A						
V51	Relief Devices Other (Explain)	Good			The PSV is set to the proper pop pressure and has been serviced within an acceptable time frame.			
V52	Relief Devices Corrosion	N/A			a dooptable time name.			
V53	Relief Devices Leaks	N/A						
V54	Restricted Inlet/Outlet	N/A		1				
V55	Manual Operation Lever	N/A						
¥ 0 0	Marida Operation Lever	14/7	I .	_1				



Date: Oct. 09, 2014 Report # : IR141009GENi

# DETAILED INSPECTION VISUAL INTERNAL

				NCR /	
ID	Description	Condition	Location	IDR	Comments
V1	General Other (Explain)				
V2	Corrosion				
	(depth, length, width)				
V3	Erosion				
V4	Distortion				
V5	Blisters				
V6	Deposits				
V7	Heads				
V8	Welds				
V9	Nozzles				
V10	Shell				
V11	Gasket Surfaces				
V21	Internals Other(Explain)				
V22	Demister				
V23	Baffle/Weir				
V24	Sparger				
V25	Thermowells				
V26	Metallic Linings				
V27	Nonmetallic Linings				
V28	Trays				
V29	Tray Rings				
V30	Other:				
	Welded Attachments				

# DETAILED INSPECTION OTHER TECHNIQUES

ID	Location	Observation/Measurement	Acceptance Criteria	NCR / IDR	Comments
1					
2					
3					
4					
5					

#### DETAILED INSPECTION UT THICKNESS

CML	Nom. Thk	Current Reading	Short Term Corr Rate	Long Term Corr Rate	Remaining Life	Comments
005	25.4	27.3				Top Head
010	7.1	7.7				Upper Shell
015	7.1	7.6				Lower shell @ the liquid level
020						
025						
030						
035						
040						
045						



Date: Oct. 09, 2014 Report # : IR141009GENi

# **PHOTOS** CERTIFIED BY YEAR Enerflex Systems Ltd. CRN FROOT SN 901128-CALGARY ALBERTA MODEL MAWP PSI@ quote this number on all inquit MDMT 09268 SHTHK REG. NO. Nameplate Sask.# Overall View