

Inspection Report

Print Date: 11/9/2007 2:30:14 PM

Hanlan Robb
Petro-Canada



Equipment Detail

Plant/Area: Hanlan - Minehead **Type:** VS **Number:** ..W-MIN-01-13-A-V-801
Equipment Name: PRODUCED WATER FLASH VESSEL

Report Information

Memo No.: 7833
Report Number: **Job File No.:**
Date Created: 11/7/2007 **Work Order No.:**
Due Date: **Date Inspected:** 11/7/2007 **Completed:** ☒ **Date Completed:** 11/7/2007

Stream

Internal

Extent

Full

Title: Routine Inspection VI, VE, US

Summary

A.I. Name: **Inspector:** R. Murtha & B. Paulson
Reason for Inspection: Routine
Regulatory Comment: Suitable for further service
Chief Inspector: **Chief Inspec. Date:**

Inspection Summary

VI
- Done through 4" 300 Flange. Couldn't see much
- Original anode 2" high silicon cast iron. Needs to be changed out to an aluminum treater style anode (may require machining down and a new blind flange)

VE
- No apparent defects

US
- Survey showed no signs of corrosion

Details (Whole Equipment)

Inspection Details

Repairs

☐ Repairs Completed

Action Taken

Activity Codes

US
VE
VI

Prob/Failure Code:

Process/Continuous History

Attachments**Attach. No.: 1****Attachment Type:** Linked**Description:****File Name:** \\PCREDSN\WORKGRP\OIP\Pressure Equipment Integrity\Pictures & Electronic Data
\\Unit #50\50-0113-A-V-801 Nov 2007\IMG_0105.JPG **File Size:** 60,578 bytes

-- attachment not printable --

Attach. No.: 2**Attachment Type:** Linked**Description:****File Name:** \\PCREDSN\WORKGRP\OIP\Pressure Equipment Integrity\Pictures & Electronic Data
\\Unit #50\50-0113-A-V-801 Nov 2007\IMG_0106.JPG **File Size:** 51,851 bytes

-- attachment not printable --

Attach. No.: 3**Attachment Type:** Linked**Description:****File Name:** \\PCREDSN\WORKGRP\OIP\Pressure Equipment Integrity\Pictures & Electronic Data
\\Unit #50\50-0113-A-V-801 Nov 2007\IMG_0107.JPG **File Size:** 70,396 bytes


-- attachment not printable --

Attach. No.: 4**Attachment Type:** Linked**Description:****File Name:** \\PCREDSN\WORKGRP\OIP\Pressure Equipment Integrity\Pictures & Electronic Data
\\Unit #50\50-0113-A-V-801 Nov 2007\IMG_0108.JPG **File Size:** 49,836 bytes

-- attachment not printable --

Attach. No.: 5**Attachment Type:** Linked**Description:****File Name:** \\PCREDSN\WORKGRP\OIP\Pressure Equipment Integrity\Pictures & Electronic Data
\\Unit #50\50-0113-A-V-801 Nov 2007\IMG_0109.JPG **File Size:** 39,535 bytes

-- attachment not printable --

Nov 9/07
Date
Inspector_____
Date_____
Chief Inspector