Blackfoot/Lloyd

CA1101-NDT-105 P5/6

Tank Inspection Report

Location: D4 104/1-3-49-2w	4 sfc:16-3-49-2w4	Tank Type: S	ales / Water TK#2	_{Date:} Jun. 29.18
Mfg: Universal Industries	Year bl	_{t:} 2012	s/N: 027499-6	CAP: 1000 bbl
Floor Thk: 1/4"	Shell Thk: 1/4	-3/16"	Roof Thk:	3/16"
Requisitioned by: Randy Chi	ırka	Approver: Shane	e Gustavson	Approver Code: <u>2Z-2001456</u>
wo #: 81298259 P	o#: 8401273576	cc:	SA	P#:_66232321

WO#	:01290239 PO#: 044	01270			_ 0
EXTE	RNAL INSPECTION:				
ID	Item	Yes	Good	N/A	See Notes
	GENERAL				
T1	Other (Please Explain)				1
T2	Corrosion			\	
T3	Leaks			1	
T4	Vibration			\	
T5	Dissimilar Flange Rating			/	
T6	Ladder/Stairway	1			
T7	Platform	1	1		
T8	Electrical Ground	_	1		
T9	Cathodic Protection			1	
T10	Painted Inactive Corrosion			1	
T11	Coating/Painting			-	
T12	Level Gauge			-	
T13	Bottom				
T14	Secondary Containment	_			
T15	Shell		- /		
T16	Roof				
T17	Agitator/ Mixer			/	
	SUPPORTS				
T31	Other (Please Explain)				
T32	Foundation			_	
T33	Anchor Bolts			-	
T34	Windgirders			-	
	CONNECTIONS		No.		
T41	Other (Please explain)				
T42	Small Branches		/		
T43	Nozzles			_	
T44	Pipe Manifolds			_	
T45	Swing Lines				_
T46	Manways/Hatches		-		
T47	Reinforcing Pads				
T48	Inadequate Thread Engagement				_
T49	Bolting		_	-	
T50	Flanges	7		_	
T51	Leak Clamps	-		-	
	INSULATION			had	
T61	Other (Please explain)				
T62	Damage				
T63	Penetrations			-	
T64	Jacket				_
T65	Banding				
T66	Seals/Joints		/		
	RELIEF DEVICE				
T7t	Other (Please explain)				
T72	Corrosion				
T73	Leaks			_	
T74	Restricted InleUOutlet				
	Manual Operation Lever				

Husky Energy

INTERNAL INSPECTION:


ID	Item	Yes	Good	N/A	See Notes
	GENERAL				
T1	Other (Please Explain)				
T2	Corrosion	-		-	1
T3	Erosion			6	
T4	Distortion			1	
T5	Blisters			/	
T6	Deposits				K
T7	Welds		1		
T8	Nozzles	_			
T9	Shell	_	-		
T10	Roof		-		
T11	Floor	-			
	GENERAL				
T21	Other - Firetube	*		1	
T21	Other - Anodes			/	
T22	Annular Ring				
T23	Sump			1	
T24	Roof Supports			1	
T25	Thermowells	/			
T26	Metallic Linings			/	_
T27	Non Metallic Linings		-		
T28	Internal Steam Coil / other Piping				
T29	Level Gauge				
T30	Other Welded Attachements				
Bac	kwelding Req'd			1	

ID	Notes 1
1	* AMAS of Moderate to
	severe corrasion on internal
	TIPLI STO, LIDAST ALPRIS
	UT mspected - see next page
	- Pitting appears confined to
	Bottom 3-4 fee
A	Scale on shell
	7 - 3
_, L	111
*	Note: Recommend tank be
1.	Alaced on lyr inspection
	interval to re-assess
	Progression of skell comosion
	- Further assessment by
	HUSKY QATQL reconviouded

CA1101-NOT-105 PG/6

With MFE


	Hus	ky	Energy
--	-----	----	---------------



s/N: 027499-6

Location: D4 104/1-3-

	.140150	5 yr	
	.130139	4 yr	
-49-2w4 sfc:16-3-49-2w4	.120129	3 yr	
01, 071	.110119	2 yr	
240 256	.100109	1 yr	
21		Patch	
240	under .100	Replace	
#1	under . 100	Floor	
21/4		Shell	
X 741			



Comments:

#1=.190	Areas #1 to #5 areas of worst
#2 = .213	Corrosion UT inspected.
#3 = .203	
#4 = .207	
#5 = .213	

101	
Inspected by: Skellen	Trachuk

Jun. 29.18 Date:

Husky Inspector:

Date:



NONDESTRUCTIVE INSPECTION REPORT

CA1101-NDT-105

Page 1 of 6

Type of Inspection: VT / UT

Code / Standard: Client Spec.

Test Technique: Visual / UT / thickness inspection

Equipment: DMS GO+, Generator, Grinder

Client: HUSKY OIL OPERATIONS LIMITED

IRISNDT #: LYN1800958

Location: (D4) 104/1-3-49-2w4 sfc:16-3-49-2w4

Item Inspected: 1000BBL Tank

Date: 29-Jun-18 WO #: 81298259

PO#: 8401273576

A Visual / UT inspection was carried out as requested on (1) - 1000BBL Tank


@ (D4) 104/1-3-49-2w4 sfc: 16-3-49-2w4

Tank#2 sn# 027499-6

Recommendations / Notes of inspection:

-MODERATE - SEVERE Corrosion evident throughout internal shell surface worst areas seen visually were UT inspected -(5) areas total UT inspected = #1= 0.190" #2= 0.213" #3= 0.203" #4= 0.207" #5= 0.213"

-Due to severity of corrosion found coupled with age of set up - Recommend tank be placed on a 1yr. inspection interval to further assess progression of corrosion found - Further Assessment required by Husky QA/QC





For additional inspection results see attached inspection sheets.

REQ:Randy Chiurka APP: Shane Gustavson 2Z-2001456

Inspection Limitation(s):

Unit#:1000	8	Kilometers:	Consumables:	Interpretation by:		
In:	Out:	Hrs:	MIN	Sheldon Trachuk	SNT-TC-1A:	1
· · · · · · · · · · · · · · · · · · ·	Out.	= 1115		(Print)	C.G.S.B.:	UT-2
In:	Out:	Hrs:				(Level)
				(Sign)	C.G.S.B #:	11405
Personnel:				Client Representative:		
Sheldon Trachuk Brayden McGinnis				(Print) Karer	n Hawryluk	
Brayden wcGinnis				I am in full		
				agreement with	.1 . /	
				report contents (Sign)	- Candrel	
				(Sign)		

5311 - 86 Street NW, Edmonton, Alberta T6E 5T8 Phone (780) 437-4747 Fax (780) 436-4873

(403) 279-6121 Calgary Lloydminster Barrhead

(780) 875-6455 (780) 674-3018 (780) 955-7616 Cold Lake Fort McMurray Red Deer

(780) 826-6105 (780) 743-1536 (403) 347-1742 www.irisndt.com

Engineering, Calgary Engineering, Edmonton Rope Access Services Offices also located in USA and UK

(403) 217-9684 (780) 437-2022 (780) 437-2022

Nisku



NONDESTRUCTIVE INSPECTION REPORT

CA1101-NDT-105
Page 2 of 6





Corrosion UT locations #1 - #3

Corrosion UT locations #4 - #5

IRISNDT #: LYN1800958

Date: 29-Jun-18

Sheldon Trachuk

Client: HUSKY OIL OPERATIONS LIMITED

(Print)

(Sign)

5311 - 86 Street NW, Edmonton, Alberta T6E 5T8 Phone (780) 437-4747 Fax (780) 436-4873

Calgary Lloydminster

Barrhead

Nisku

(403) 279-6121

(780) 875-6455 (780) 674-3018 (780) 955-7616 Cold Lake Fort McMurray Red Deer (780) 826-6105 (780) 743-1536 (403) 347-1742 www.irisndt.com Engineering, Calgary
Engineering, Edmonton
Rope Access Services
Offices also located in USA and UK

(403) 217-9684 (780) 437-2022 (780) 437-2022



NONDESTRUCTIVE INSPECTION REPORT

CA1101-NDT-105

Page 3 of 6





UT Location#1

UT Location#2





UT Location#3

UT Location#4

IRISNDT #: LYN1800958

Date: 29-Jun-18

Sheldon Trachuk

Client: HUSKY OIL OPERATIONS LIMITED

(Sign)

(Print)

Barrhead

Nisku

(780) 674-3018 (780) 955-7616

5311 - 86 Street NW, Edmonton, Alberta T6E 5T8 Phone (780) 437-4747 Fax (780) 436-4873 Calgary (403) 279-6121 Cold Lake Lloydminster (780) 875-6455 Fort McMurray Red Deer

(780) 826-6105 (780) 743-1536 (403) 347-1742 www.irisndt.com

Engineering, Calgary Engineering, Edmonton (780 Rope Access Services (780 Offices also located in USA and UK

(403) 217-9684 (780) 437-2022 (780) 437-2022



NONDESTRUCTIVE INSPECTION REPORT

CA1101-NDT-105

Page 4 of 6



1	IT	10	Ca	tin	n#5

IRISNDT #: LYN1800958

Client: HUSKY OIL OPERATIONS LIMITED

5311 - 86 Street NW, Edmonton, Alberta T6E 5T8 Phone (780) 437-4747 Fax (780) 436-4873

Calgary (403) 279-6121 Lloydminster (780) 875-6455 Barrhead (780) 674-3018 Nisku (780) 955-7616 Cold Lake Fort McMurray Red Deer

(780) 826-6105 (780) 743-1536 (403) 347-1742 www.irisndt.com

Date: 29-Jun-18

Engineering, Calgary Engineering, Edmonton

(Print)

(Sign)

Sheldon Trachuk

(403) 217-9684 (780) 437-2022 Rope Access Services (780 Offices also located in USA and UK (780) 437-2022