

Blackfoot/Lloyd

Tank Inspection Report

rank	inspection	Repo
_	19-Sent-19	


Location: 102/11-14-49-2W4M		Tank Type: Sal	es	Date: 18-Sept-19
Mfg: Universal	Year blt	. <u>2010</u> s	_{S/N:} 021080	-4 CAP: 1000 bbl
Floor Thk: 1/4"	Shell Thk: 1/4"	X 3/16"	Roof Th	k:_3/16"
Requisitioned by: Arnie Domes		Approver: Scott S	Stafford	Approver Code: 2Z-2020575
WO #: 81422566 PO#: 2	3401358779	CC:		SAP #: 66168164

ID	Item	Yes	Good	N/A	See Notes
	GENERAL				
T1	Other (Please Explain)			Х	
T2	Corrosion			Х	
T3	Leaks			Х	
T4	Vibration			Х	
T5	Dissimilar Flange Rating			Х	
T6	Ladder/Stairway	Х	Х		
T7	Platform	Х	Х		
T8	Electrical Ground	Х	Х		
T9	Cathodic Protection			Х	
T10	Painted Inactive Corrosion			Х	
T11	Coating/Painting	X	X		
T12	Level Gauge	Х	Х		
T13	Bottom	Х	X		
T14	Secondary Containment	Х	Х		
T15	Shell	Х	Х		
T16	Roof	Х	Х		
T17	Agitator/ Mixer			Х	1
	SUPPORTS			-	
T31	Other (Please Explain)			Х	
T32	Foundation	Х	Х		1
T33	Anchor Bolts			Х	
T34	Windgirders			Х	
	CONNECTIONS				
T41	Other (Please explain)				
T42	Small Branches			Х	
T43	Nozzles	Х	Х		
T44	Pipe Manifolds			Х	
T45	Swing Lines			Х	
T46	Manways/Hatches	Х	Х		
T47	Reinforcing Pads	Х	Х		
T48	Inadequate Thread Engagement			Х	
T49	Bolting	Х	Х		
T50	Flanges			Х	
T51	Leak Clamps			Х	
	INSULATION				
T61	Other (Please explain)			Х	
T62	Damage			Х	
T63	Penetrations	Х	Х		2
T64	Jacket			Х	
T65	Banding			X	
T66	Seals/Joints			Х	
	RELIEF DEVICE				
T7t	Other (Please explain)			Х	
T72	Corrosion			Х	
T73	Leaks			Х	
T74	Restricted InleUOutlet			Х	
T75	Manual Operation Lever			Х	

INTERNAL INSPECTION:

INTE	RNAL INSPECTION:			_		
ID	Item	Yes	Good	N/A	See Notes	
	GENERAL					
T1	Other (Please Explain)			Х		
T2	Corrosion			X		
T3	Erosion			Х		
T4	Distortion			X		
T5	Blisters			Х		
T6	Deposits	Х			3	
T7	Welds	Х	Х			
T8	Nozzles	Х			4	
T9	Shell	Х	X			
T10	Roof	X	Х			
T11	Floor	Х	X			
	GENERAL					
T21	Other - Firetube	Х	X			
T21	Other - Anodes			Х		
T22	Annular Ring			Х		
T23	Sump			Х		
T24	Roof Supports			Х		
T25	Thermowells	Х	Х			
	Metallic Linings			Х		
T27	Non Metallic Linings			Х		
T28	Internal Steam Coil / other Piping	Х	Х			
T29	Level Gauge	Х			5	
T30	Other Welded Attachements	Х	Х			
Bac	Backwelding Req'd X					

ID	Notes
1	On Planks Slight settlement
2	Penetrations are not Insulated
3	Scale from 20" Up
4	Replace Vault sting nozzle
5	Remove Guide wires





NONDESTRUCTIVE INSPECTION REPORT

CA1091-NDT-424

Page 1 of 1

Type of Inspection: UT/Vis

Test Technique: o-deg

N/A

Client: HUSKY OIL OPERATIONS

Date: 2019-Sep-22 WO #: 81422566 PO #: 8401358779

Equipment: DMS2 /Flashlight

Code/Standard: Client Information

IRISNDT #: LYN1901578 Location: 102/11-14-49-2W4M Item Inspected: Sales tank

Appr# 27-2020575

Inspection Results: Appr: Scott Stafford

Requisitioner: Arnie Domes

A Visual examination and UT thickness check was carried out on the following 1000Bbl tank for the purpose of determining tank condition and inspection interval. See attached pages for UT thickness readings and observations.



INSPECTION RESULTS:

Replace Vault sting nozzle

Remove Guide wires

Inspection Limitation(s):

Note Spot UT thickness readings give a General overall condition of the tank and are not a 100% Scan Method.

,							
Unit#:1039 In: In:	2000	s:	Consumables: min	Interpretation by: Tristan Sommerfeld (Print)	SNT-TC-1A:		
Personnel: Tristan Sommerfeld Steve White			1	(Sign) Client Representative: (Print) Tell agreement with report contents (Sign)	ry Neufeld		

5311 - 86 Street NW, Edmonton, Alberta T6E 5T8 Phone (780) 437-4747 Fax (780) 436-4873 Calgary (403) 279-6121

First course access only

(780) 875-6455 Lloydminster (780) 674-3018 Barrhead

(780) 955-7616

Cold Lake Fort McMurray Red Deer

(780) 826-6105 (780) 743-1536 (403) 347-1742 www.irisndt.com

Engineering, Calgary Engineering, Edmonton Rope Access Services

(403) 217-9684 (780) 437-2022 (780) 437-2022 Offices also located in USA and UK

Nisku