

Blackfoot/Lloyd

Tank Inspection Report

Location: 100/8-36-48-1W4M		Tank Type:_F	Production		Date: 9-Sept-19
Mfg: Universal	Year bl		S/N: 15282-2	21	CAP: 1000 bbl
Floor Thk: 1/4"	Shell Thk: 1/4	" X 3/16"	Roof Th	k: 3/16"	
Requisitioned by: Randy Chuirka		Approver: Scot	t Stafford	Арр	rover Code: 2Z-02020575
WO #: 81422568 PO#:	8401358779	cc:		SAP #: 661	

ID	Item	Yes	Good	N/A	See Notes
	GENERAL				
T1	Other (Please Explain)			Х	
T2	Corrosion			Х	
T3	Leaks			Х	
T4	Vibration			Х	
T5	Dissimilar Flange Rating			Х	
T6	Ladder/Stairway	Х	Х		
T7	Platform	Х	Х		
T8	Electrical Ground	Х	Х		
T9	Cathodic Protection			Х	
T10	Painted Inactive Corrosion			х	
T11	Coating/Painting	X	×		
T12	Level Gauge	X			1
T13	Bottom	X	X		
T14	Secondary Containment	X	X		_
T15	Shell	X	X		
T16	Roof	X	X		_
T17	Agitator/ Mixer	<u> </u>	^	X	
117	SUPPORTS			^	
T31	Other (Please Explain)			X	
T32	Foundation	X	Х	^	2
T33	Anchor Bolts	<u> </u>	_^	Х	2
T34	Windgirders	-		X	
134	CONNECTIONS			^	
T41					
T42	Other (Please explain) Small Branches	-			_
		-	-	Х	
T43	Nozzles	X	Х		
T44	Pipe Manifolds	-		Х	
T45	Swing Lines			Х	
T46	Manways/Hatches	Х	X		
T47	Reinforcing Pads	Х	Х		
T48	Inadequate Thread Engagement			Х	
T49	Bolting	Х	Х		
T50	Flanges			Х	
T51	Leak Clamps			Х	
	INSULATION				
T61	Other (Please explain)			X	
T62	Damage			Х	
T63	Penetrations	×	Х		
T64	Jacket			X	
T65	Banding			X	
T66	Seals/Joints			Х	
1000	RELIEF DEVICE			1000	
T7t	Other (Please explain)			Х	
T72	Corrosion			Х	
T73	Leaks	T		Х	
T74	Restricted InleUOutlet			Х	
T75	Manual Operation Lever		1	Х	

INTERNAL INSPECTION

ID	Item	Yes	Good	N/A	See Notes
	GENERAL				
T1	Other (Please Explain)			Х	
T2	Corrosion			Х	
T3	Erosion			Х	
T4	Distortion			Х	
T5	Blisters			Х	
T6	Deposits	X			3
T7	Welds	Х	X		
T8	Nozzles	X			4
T9	Shell	X	Х		
T10	Roof	X	X		
T11	Floor	X	Х		
	GENERAL				
T21	Other - Firetube	×	Х		5
T21	Other - Anodes			Х	
T22	Annular Ring			X	
T23	Sump			Х	
T24	Roof Supports			Х	
T25	Thermowells	Х	Х		
T26	Metallic Linings			Х	
T27	Non Metallic Linings			Х	
T28	Internal Steam Coil / other Piping	X			6
	Level Gauge	×	Х		
T30	Other Welded Attachements	X	X		
Bac	kwelding Req'd			Х	

ID	Notes
1	Gauge Board was assembled incorrectly- Straighten to allow movement of slide
2	On planks
3	Oilsand from 5' Up
4	Replace Vault sting nozzle
5	Blow out firetube and re-isnpect
6	Clean or replace Vault risers
_	
_	

Husky Energy Without MFE With MFE S/N: 15282-21 .170 - up 5 yr 140 - .150 5 yr 160 - .169 4 yr 130 - .139 4 yr Location: 100/8-36-48-1W4M .150 - .159 3 yr .120 - .129 3 yr .140 - .149 2 yr .110 - .119 2 yr .130 - .139 1 yr 100 - .109 1 yr Patch Patch Replace Replace under .130 under .100 Floor Floor Shell Shell 233 246 233 247 239 246 239 241 239 Comments: Repair Gauge board clean or replace vault risers Blow out firetube and re-inspect Replace Vault sting nozzle Inspected by: 103 for Date: 9-5,0+-19 Husky Inspector: Terry Neufeld 25/09/2019 Date:



Rev:

N/A

NONDESTRUCTIVE INSPECTION REPORT

CA1091-NDT-412

Page 1 of 1

Type of Inspection: UT/Vis
Test Technique: o-deg

Equipment: DMS2 /Flashlight
Code/Standard: Client Information


Client: HUSKY OIL OPERATIONS

IRISNDT #: LYN1901500 Location: 100/8-36-48-1W4M Item Inspected: Production tank Date: 2019-Sep-09 WO #: 81422568 PO #: 8401358779

Appr# 2Z-02020575

Inspection Results: Appr: Scott Stafford Requisitioner: Randy Chuirka

A Visual examination and UT thickness check was carried out on the following 1000Bbl tank for the purpose of determining tank condition and inspection interval. See attached pages for UT thickness readings and observations.



INSPECTION RESULTS:

Blow out and re-inspect fireube

Clean or replace vault risers

Repair Gauge Board

Replace vault sting nozzle

Note Spot UT thickness readings give a General overall condition of the tank and are not a 100% Scan Method.

Fort McMurray

Red Deer

First savings assess only

Unit#: 1039 In: Out: _ In: Out: _ Personnel:	Kilometers: 0 Hrs: Hrs:	Consumables: min	Interpretation by: Tristan Sommerfeld (Print) (Sign)	SNT-TC-1A: API-653 (Level) CERT #: 98310
Tristan Sommerfeld Steve WHite			Client Representative: I am in full agreement with report contents (Sign)	eufeld
	n, Alberta T6E 5T8 Phone (780 03) 279-6121	437-4747 Fax (780) 436-4873 Cold Lake	(780) 826-6105 Engineering,	Calgary (403) 217-968-

(780) 743-1536

(403) 347-1742

www.irisndt.com

(780) 875-6455

(780) 674-3018

(780) 955-7616

Lloydminster

Barrhead

Nisku

(780) 437-2022

(780) 437-2022

Engineering, Edmonton

Offices also located in USA and UK

Rope Access Services