


Without MFE		
.170 - up	5 yr	✓
.160 - .169	4 yr	
.150 - .159	3 yr	
.140 - .149	2 yr	
.130 - .139	1 yr	
under .130	Patch	
	Replace	
	Floor	
	Shell	

S/N: 29086-3 (Tanx2)

Location: 103/9-11-43-5 w4

With MFE		
.140 - .150	5 yr	
.130 - .139	4 yr	
.120 - .129	3 yr	
.110 - .119	2 yr	
.100 - .109	1 yr	
under .100	Patch	
	Replace	
	Floor	
	Shell	



Comments:

Tank in Good Overall Condition For a 5YR Turnaround. NO Repairs/Upgrades Required.

Inspected by:

Stephen Bryan

Date:

Date: May 28. 2019

Husky Inspector:



Date:

July 30, 2019

Terry Neufeld


Type of Inspection: VT **Rev:** 3.0
Test Technique: UT thickness(4.2)
Equipment: DMS2 / flashlight / grinder
Code/Standard: client information

Client: HUSKY OIL OPERATIONS
IRISNDT #: LYN1900860
Location: 103/ 9-11-47-5 W4M
Item Inspected: 1000 bbl tank 2 S/N# 29086-3

Date: 2019-May-28
WO #: 81391206
PO #: 8401358779

a UT and visual inspection was carried out as requested on 1000bbl tank, refer to attached pages for additional information.

1000bbl tank 2 S/N# 29086-3: The tank is in good overall condition for a 5yr turnaround, no additional repairs or upgrades required.



DMS 2 S/N# 31074 CAL DATE : JAN9 2019.

F2HE PROBE S/N# SCA2097

APPROVER: Jay Sinclair ZZ-8000441

Requested by Randy Chiuurka

Inspection Limitation(s): oil /shale deposits on the shell and piping.

Unit#: 767 Kilometers: 0
 In: _____ Out: _____ Hrs: _____
 In: _____ Out: _____ Hrs: _____
 Personnel:
 STEPHEN BRYAN / NIGEL GEARIN

Consumables:
 MIN

Interpretation by:

Stephen Bryan

SNT-TC-1A: _____

(Print)

C.G.S.B.: _____
 (Level)

(Sign)

C.G.S.B #: 12459

Client Representative:

(Print) Terry Neufeld

I am in full
 agreement with
 report contents

(Sign)