

AIR COOLED HEAT EXCHANGER INSPECTION REPORT

LSD: 06-25-046-03W4 **Date:** 2015-01-20 **SAP Equipment ID** 62045576

AIR COOLED HEAT EXCHANGER STATIC DATA

Plant:	Rivercourse	OP Unit:		System:	
Prov. Insp . #:		NB#:	2243	CRN:	M-5200-23
Equipment Description:	HEAT EXCHANGER				Serial #: 01543-2
Manufacturer:	AIR COOLED EXCHANGER INC.				Vessel Class: ACHE
Internal Access:	No	Description:		Year Built:	2001
MAWP:	1724	kpa	At Temp	112	C
Code:	N/S	Fluid Service:	Sweet:	Sour:	
Dimension		Length:	0	mm	(T/T): mm
				OAL:	mm
SHELL	Mat'l:	Unknown	SA 516-70	Thickness:	0.00 12.7 mm
Nozzle	Mat'l:			Thickness:	
Internal Coating:		Internal Clad:		Capacity:	m3
Nozzle Rating:	300	lb ANSI	Painted:	Yes	Insulated: No

PROCESS DATA

Operating Pressure	kpa	Operating Temp:	C	Status:	Shut-In
---------------------------	-----	------------------------	---	----------------	---------

PSV STATIC DATA

Tag #	Serial No.	Location	Size(mm)		Set Press (kPa)	Capacity Imperial (SCFM)	Manufacturer	Model	Last Service	Service Company
			Inlet	Outlet						
3415	7907-20	Piping	25.40	25.40	1379	761	Taylor Valve	T-8200-1	2010/06/01	GUEST

PSV DETAILS

	Type(Thread/Flange)	ANSI Rating	Size(In/mm)
PRD Inlet	Threaded	N/A	25.40
PRD Outlet	Threaded	N/A	25.40

NDE Equipment Records

Procedure #	Description	Manufacturer	Model#	Serial#	Due Date
**** See Associated NDE Report					

INSPECTION SUMMARY

VESSEL IS FIT FOR SERVICE. PIPING CML'S SHOW RDGS LOWER THAN NOM-MIL HOWEVER THE WALL LOSS IS MINOR AND ACCEPTABLE AT TIME OF INSPECTION.

RECOMMENDATIONS

RECOMMEND TO SERVICE PSV BEFORE PUTTING VESSEL BACK INTO SERVICE.

NONCONFORMANCES/INSPECTION DEFICIENCIES

PSV SERVICE IS PAST DUE.

Service PSV prior to re-commissioning the cooler.



AIR COOLED HEAT EXCHANGER INSPECTION REPORT

LSD: 06-25-046-03W4**Date:** 2015-01-20**SAP Equipment ID**


62045576

INSPECTION PLANNING

Inspection Strategy	_____	Availability	_____	Inspection Interval	<u>5 year</u>
Inspection Date	<u>2015/01/20</u>	Date of Last Inspect	_____	Date of Next Insp	<u>2020</u>

REPORT CERTIFICATION

The SignatureS below certify that inspections/tests have been completed in accordance with the identified inspection strategy and that the specified equipment is considered fit for service until the date of next inspection.

Inspected by	<u>Justin Orichowski</u>		Cert #	<u>758</u>	Date	<u>2015/01/20</u>
Reviewed and Approved by	_____	_____			Date	_____
Criticality Assessment Rerun	_____	Inspection Planning Rerun				
Assessed Next Inspection Date	<u>2020</u>	_____				

AIR COOLED HEAT EXCHANGER INSPECTION REPORT

LSD: 06-25-046-03W4

Date: 2015-01-20

SAP Equipment ID

62045576

DETAILED INSPECTION VISUAL EXTERNAL

ID	Description	Condition	Location	NCR	Comments
V1	General Other (Please Explain)	Accept		No	GOOD CONDITION.
V2	General Corrosion	Accept		No	NO CORROSION.
V3	General Leaks	N/A		No	NOT IN SERVICE.
V4	Vibration	N/A		No	NOT IN SERVICE.
V5	Dissimilar Flange Rating	Accept		No	
V6	Ladder/Stairway	N/A		No	
V7	Heads	N/A		No	
V9	Electrical Ground	N/A		No	
V10	Painted Inactive Corrosion	N/A		No	
V11	Coating/Painting	Accept		No	PAINT IN GOOD CONDITION.
V12	Expansion Joint or Bellows	N/A		No	
V13	Gauge/Site Glass	N/A		No	
V14	Shell	Accept		No	GOOD CONDITION.
V15	Jacket	N/A		No	
V21	Support Other (Please explain)	Accept		No	PIPING IS WELL SUPPORTED.
V22	Foundation	N/A		No	
V23	Anchor Bolts	N/A		No	
V24	Saddle/Skirt	N/A		No	
V25	Davit	N/A		No	
V26	Fireproofing	N/A		No	
V31	Connections Other (Please explain)	Accept		No	PIPING CONNECTIONS IN GOOD CONDITION.
V32	Small Branches	Accept		No	
V33	Nozzles	Accept		No	
V34	Manways	N/A		No	
V35	Reinforcing Pads	N/A		No	
V36	Inadequate Thread Engagement	Accept		No	ADEQUATE THREAD ENGAGEMENT OBSERVED.
V37	Bolting	Accept		No	
V38	Flanges	Accept		No	
V39	Leak Clamps	N/A		No	
V41	Insulation Other (Please explain)	N/A		No	
V42	Damage	N/A		No	
V43	Penetrations	N/A		No	
V44	Insulation Jacket	N/A		No	
V45	Banding	N/A		No	
V46	Seals/Joints	N/A		No	
V51	Relief Devices Other (Please explain)	Concern		No	SERVICED 06/2010 - PSV SERVICE IS PAST DUE.
V52	Corrosion	Accept		No	
V53	Leaks	N/A		No	NOT IN SERVICE.
V54	Restricted Inlet/Outlet	Accept		No	
V55	Manual Operation Lever	N/A		No	

AIR COOLED HEAT EXCHANGER INSPECTION REPORT

LSD: 06-25-046-03W4 **Date:** 2015-01-20 **SAP Equipment ID** 62045576

DETAILED INSPECTION OTHER TECHNIQUES

ID	Location	Observation/Measurement	Acceptance Criteria	NCR	Comments


DETAILED INSPECTION TUBE INSPECTION

Tube #	Flaw Type	Flaw Length	Location on Tube	Wall Loss	NCR	Comments

DETAILED INSPECTION UT THICKNESS




CML	Nom. Thickness (mm)	CURRENT READINGS (mm)	short term corr rate (mm/y)	long term corr rate (mm/y)	remaining life (year)	Survey Date	Comments
05 (SHELL) 12.7 mm	0.00	12.65	0.0000	0.0000	198.0	2015/01/20	NO COMMENTS within C/A
10 (SHELL) 12.7 mm	0.00	12.57	0.0000	0.0000	198.0	2015/01/20	NO COMMENTS within C/A

15 (90L 2 XS)	5.54	4.75	0.0556	0.0556	78.7	2015/01/20	LOW RDG IS BETWEEN NOM-CA AND Tmin
20 (90L 2 XS)	5.54	4.78	0.0538	0.0538	81.8	2015/01/20	LOW RDG IS BETWEEN NOM-CA AND Tmin

Inspected By	Signature	CGSB Level	CGSB No.	Survey Date	UT Equip	Due Date OF Calibration	NDE Procedure No.
Justin Orichowski		1	16325	01/20/2015	104_91638503_EPOCH4	06/17/2015	WQS UT-001

EXAMINATION ILLUSTRATION

DISTRICT:	AB- SOUTH	FACILITY:	RIVERCOURSE	LOCATION/LSD:	06-25-046-03W4
EQUIP NAME:	HEAT EXCHANGER			PROV REG No.:	
SERIAL No.:	01543-2	Equip No.:	62045576	National Board No.:	



NOTES:

PHOTOGRAPHS





EQUIP NAME:	HEAT EXCHANGER		PROV REG No.:	
SERIAL No.:	01543-2	Equip No.:	62045576	National Board No.:



NAMEPLATE



OVERALL



NOTES: