

PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD: 07-27-051-19W5M Date: JULY 09, 2014 SAP Equipment ID: 66126579

	VESSEL STATIC DATA											
Plant	Ansell Gas	Ansell Gas Plant				Syste	m					
Prov. Insp. #	A0563306		CRN U1205.21				Equip	Equip Tag # V-600				
Equipment Do	escription	Flare K	nockout	Drum	1			Serial	Serial # 07-2933-0001			0001
Manufacturer	•	Pyrami	d Corp.					Vesse	Vessel Class			
Internal Acce	ss: Yes	Descript	tion: 24	in ma	nway			Year	Built	2007		
MAWP 15		PSI		@ :	302	0	F	MDM	Γ	-48		°F
CODE:			RT: 1					PWH	Г: No			
I liamotor	3 in stimate	onata '	s/s) 228 estimate	in	0	AL in				Но	rizont	al
Shell Mat	'I		Thickn	ess		0.625	in	Corr A	llowand	ce 0.	125	in
Head Mat	'1		Thickn	ess		0.6875	in	Corr A	llowand	ce 0.	125	in
Nozzle Mat	'1		Thickn	ess			in	Corr A	llowand	се		mm
Internal Coati	ing: YES N	Ð	Internal Clad: YES NO			Capa	city			m3		
Manway:	yes		Inspection Port : no			Saddl	Saddle					
Nozzle Rating	150	lb ANSI	Painted: yes			Insula	Insulated yes					
	<u>.</u>			PRO	CESS D	ATA						
Product Desc		3	Sweet									
Operating Pre	essure		PSI Operating Temporating Temp			perature				F		
						– East P			_			2 1
Serial No.	Location	_	et sure	SCFM / I GPM	Dacity Lbs/Hr /	Manufac	cturer	Model /	туре		vice i	Date / any
				PS	V DETA							
Type (Thread/Fla			ange) ANSI Rating					Size	(in)			
PRD Inlet												
PRD Outlet			h · =		.*							
NDE Equipment records Procedure# Description Manufacturer Model# Serial# Due Date						-1-						
Procedure#	Description	wanut	acturer		Model	#		Serial#	Serial# Due Date		ate	

INSPECTION SUMMARY

A visual external inspection was conducted on vessel while in operation. Plant 2. Dataplate secure and legible. Vessel and piping are insulated and clad limiting visual inspection. Cladding and banding in good condition, coverplates present on all UT cut outs. Piping well supported. Paint in good condition on exposed surfaces. No ground cable connection found, skid welded to steel piles. Saddle supports securely bolted to skid. No PSV, atmospheric vessel. Ladder and platform securely attached, and in good condition. UT inspection performed 2014 by Streamline Inspection.

Vessel was found to be in good condition and fit for continued service.

RECOMMENDATIONS

Ensure vessel is properly grounded Review UT survey results. Double nut manway davit

NONCONFORMANCES / INSPECTION DEFICIENCIES

Manway davit only single nut. No ground cable connection found.



PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD: 07-27-051-19W5M Date: JULY 09, 2014 SAP Equipment ID: 66126579

INSPECTION PLANNING

Inspection Strategy		Availability		Inspection Interval	
Inspection Date	July 09, 2014	Date of Last Inspect	-	Date of Next Inspect	
		-		•	

REPORT CERTIFICATION

	REPURI CERTI	FICATION				
The signatures below certify that inspectio	ns/tests have been completed	l in accordance w	vith the identified i	nspection s	trategy and that	
the specified equipment is considered fit for	or service until the date of nex	t inspection.				
			_			
Inspected by	Ed Tymensen	<u> </u>		Date	July 09, 2014	
Company	Streamline Inspection	PESL #	000711	API#	27479	
Company	Streamme inspection	_ FESE#	000711	AFI#	21413	
Reviewed and Approved by				Date		
nononou and approvou by		_		Duit		
		PESL#		API#		
		_				
Criticality Assessment Rerun		Inspection Pla	nning Rerun			
		_	_			
Assessed Next Inspection Date						



PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD: 07-27-051-19W5M Date: JULY 09, 2014 SAP Equipment ID: 66126579

DETAILED INSPECTION VISUAL EXTERNAL

ID	Description	Condition	SPECTION VISUAL I Location	NCR	Comments
	-		Location	HOIL	
V1	General Other (Please Explain)	Good			Overall No correction noted
V2	General Corrosion	n/a			No corrosion noted
V3	General Leaks	n/a			No leaks noted
V4	Vibration	n/a			Circilos setiene
V5	Dissimilar Flange Rating	Good	Ladden/alattama		Similar ratings
V6	Ladder/Stairway	Good	Ladder / platform		Securely attached, bar present across platform opening
V7	Heads	n/a			Insulated – no visual
V8	Guy Wires	n/a			incarated no negar
V9	Electrical Ground	Poor			No ground cable connection found
V10	Painted Inactive Corrosion	n/a			The greater case comments.
V11	Coating/Painting	Good	Exposed surfaces		No significant damage or deterioration
V 1 1	Coating/r airting	0000	Exposod danados		noted
V12	Expansion Joint or Bellows	n/a			
V13	Gauge/Site Glass	n/a			
V14	Shell	n/a			Insulated – no visual
V15	Jacket	n/a			
V21	Support Other (Please explain)	Good	Piping		Well supported
V22	Foundation	Good			Vessel on steel skid, welded to steel piles
V23	Anchor Bolts	Good			Tight and secure both ends
V24	Saddle/Skirt	Good	Saddle		Bolted to skid, no visual access to support to shell connections
V25	Davit	n/a			
V26	Fireproofing	n/a			
V31	Connections Other (Please explain)	Good			All connections appear secure
V32	Small Branches	n/a			
V33	Nozzles	Good			No corrosion or damage noted
V34	Manways	Good			Davit is single nut only
V35	Reinforcing Pads	n/a			insulated
V36	Inadequate Thread Engagement	Good			Adequate engagement
V37	Bolting	Good			All bolting tight and secure, no corrosion of threads
V38	Flanges	Good			No leaks or corrosion
V39	Leak Clamps	n/a			
V41	Insulation Other (Please explain)	Good	Vessel / piping		Insulated and clad
V42	Damage	n/a			None noted
V43	Penetrations	Good	UT cut outs		Coverplates in place, sealed
V44	Insulation Jacket	Good	Vessel / piping		Tin cladding
V45	Banding	Good			
V46	Seals/Joints	good			
V51	Relief Devices Other (Please explain)	n/a			Atmospheric, no PSV required
V52	Corrosion	n/a			
V53	Leaks	n/a			
V54	Restricted Inlet/Outlet	n/a			
V55	Manual Operation Lever	n/a			



PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD: 07-27-051-19W5M Date: JULY 09, 2014 SAP Equipment ID: 66126579

DETAILED INSPECTION VISUAL INTERNAL

ID	Description	Condition	Location	NCR	Comments
V1	General Other (Please Explain)	n/a			
V2	Corrosion (depth, length, width)	n/a			
V3	Erosion	n/a			
V4	Distortion	n/a			
V5	Blisters	n/a			
V6	Deposits	n/a			
V7	Heads	n/a			
V8	Welds	n/a			
V9	Nozzles	n/a			
V10	Shell	n/a			
V11	Gasket Surfaces	n/a			
V21	Internals Other (Please explain)	n/a			
V22	Demister	n/a			
V23	Baffle/Wier	n/a			
V24	Sparger	n/a			
V25	Thermowells	n/a			
V26	Metallic Linings	n/a			
V27	Nonmetallic Linings	n/a			
V28	Trays	n/a	_		
V29	Tray Rings	n/a			
V30	Other Welded Attachments	n/a			

DETAILED INSPECTION OTHER TECHNIQUES

ID	Location	Observation/Measurement	Acceptance Criteria	NCR	Comments
1					
2					
3					
4					
5					
6					
7					
8					
9					
10					

DETAILED INSPECTION UT THICKNESS

CML	Nom. Thk	Current Reading	Short Term Corr Rate	Long Term Corr Rate	Remaining Life	Comments



PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD: 07-27-051-19W5M Date: JULY 09, 2014 SAP Equipment ID: 66126579

PHOTOS






LSD sign









DAVIT SINGLE NUT ONLY