Pressure Vessel Inspection Report

Equipment #: 62037651

Description: South Inlet Separator (North Building)

Serial# 2559

Location: 6-34-50-27 W3 (Cost Center # 72325)

Notification #:

Inspection Date: July 23, 2009 Inspected by: Les Deverill

INSPECTION SUMMARY:

Vessel remains in fair condition from an external visual review. Process Piping, as outlined below, needs to be evaluated . (Note: Vessel is online)

RECOMMENDATION:

- The foundation & building in which the vessel is located, really needs to be repaired, to maintain a suitable operating environment & to ensure no one steps through the floor.
- Conduct an engineering review to ensure adequate thickness of associated piping.

REPAIRS COMPLETED:

NONCOMPLIANCES:

EXTERNAL INSPECTION:

- Vessel in fair condition with no changes to previous inspection.
- The vessel building is deteriorating quickly, the wall where the door frame is contained is corroded away from the floor and the floor is extremely corroded. Floor perforations may be the next order of business.
- Inlet & Outlet Drain Elbows are exhibiting low measurements on the outside radius of the elbows (@ 0.177" & 0.161" respectively). Unless there is an engineering spec break, the design thickness for these elbows should be 0.436" (XXS). (Nozzles on drawing indicate XXS)

EXTERNAL NDE:

See Attached data sheet

INTERNAL INSPECTION:

No Access

INTERNAL NDE:

No Access

INSPECTION INTERVAL:

o 48 months

Les Deverill, Aug 5, 2009

APPROVED BY: //WY //WWWW

DATE: 2009-08-04

Ray Trachuk

C:\Documents and Settings\Les\Desktop\Les Deverill Info\CWIS (Vessels & Corrosion)\Husky Lloyd Field\Northminster\06-34-050-27 W3M WELLSITE\62037651 Inlet Sep South\INSP REPT - 2009.doc

Husky Energy Ltd.

Lloydminster Field

Pressure Vessel Inspection Report

#5 - Mid Shell	0.625"	0.637" (16.2 mm)	0.634" (16.1 mm)
#6 - Bottom Knuckle	0.625"	0.809" (20.5 mm)	0.841" (21.4 mm)
#7 - Bottom Head	0.625"	No Access	NA
#8 - Outlet Drain El	0.436"	0.177" (4.5 mm)	NA
#9 – Inlet El	0.436"	0.161" (4.1 mm)	NA

Data Assessment indicates no major changes in wall thickness measurements since 2004, however the outlet drain elbow (2") and inlet elbow (2") are thin. There could be a spec break at the valves, but the measurement is low even for Schd 40 -- 2" piping fittings.





PRO-27 (9/64)

BY____OF____ SUBJECT PROJECT_ 6-34.50.27 NONTA BLDS - SOUTH INCEL SER 533 # 27373. A# 29/6923 TMUS # TOP N KNUCKEE #1 769 TOP OUT NOZZ #2 462 FLOOR CURPURE 708 WEST KNUCK#3 751 FROM FLOOR IP PSV OUGLET NOZZ #4 480 PLACES UPPER SHELL HJ. 637 5888CIALLY NEAR BOTT KHUCK #6 809 BOTT HO # 7. NO ACCESS CARMS TO FAT BOH DRAW SL #8 177 18856 ONLINE INUST 20 49