Form: QR-19.7a Rev.: 2, Date: Jan 22<sup>nd</sup>, 2018

### PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD 07-27-51-1	LSD 07-27-51-19W5 Date June 19, 2018 SAP Equipment ID 66130683 Report #20180619Gb									
	VESSEL STATIC DATA									
Plant	Ansell Pla	nt 2		Op Unit			Syste	m		
Prov. Insp. #	A0571635	NB#		CRN	U0833.2		Equip	Tag #	V-800	
Equipment De	escription	PLANT 2	NGL BU	LLET			Serial	#	H070028	39
Manufacturer		Trinity	Industrie	s de Mexic	:0		Vesse	l Clas	S	
Internal Acce	ss <mark>YES</mark>	NO Des	cription				Year E	Built	2007	
MAWP 250	)	kPa / <mark>PS</mark>	<mark>81</mark> @	125	0	C / °F	MDMT	_	-20	°C / <mark>°F</mark>
CODE UM	U U2		RT 1 2	2 3 4			PWHT	NO		
Diameter 13	31.875" OD <b>L</b>	ength (T	Г/Т)	mm/in	<b>OAL</b> 1080	).875 in	Vertica	al	Horizon	<mark>tal</mark>
Shell Mat	'I SA-516-70	ON	Thicknes	ss	0.828	in	Corr A	llowan	се	mm / in
Head Mat	'I SA-516-70	N	Thicknes	ss	0.487	in	Corr A	llowan	се	mm / in
Nozzle Mat	'1		Thicknes	ss		mm / in	Corr A	llowan	се	mm / in
Internal Coati	ng: YES N	<mark>IO</mark>	Internal	Clad YE	is <mark>nc</mark>	)	Capac	ity		$m^3$
Manway	YES NO	)	Inspection	n Port Y	ES <mark>NO</mark>	<u>)</u>	Skirt	Legs	Saddle	
Nozzle Rating	150	lb ANSI	Painted	YE	S NO	1	Insula	ted	YES	NO
	•			PROCESS	DATA	_				
Product Desc		<u>SL</u>				Sweet		Sour		
Operating Pre	essure 70		kPa /	<mark>psi</mark> CTED BY P		ng Temp	erature	60		°C / <mark>°F</mark>
				RD STATIO		PSD				
	Location	Se		Capacity	Manufa	cturer	Model /	Type	Last Serv	ice Date
Serial No.		Press		CFM / Lbs/Hr / PM				71	& Com	pany
C06-38617	EAST SIDE ON TOP	227 PSI	I 4	4863 scfm	CROSI	3Y	26310-4	6/S1	JUNE 201	3
	PRD DETAILS									
	Type (	Thread/Fla	inge)		ANSI F	Rating			Size (mm	)
PRD Inlet										
PRD Outlet										
			IN	SPECTION .	SUMMARY	•				

	Vessel	is f	it for	further	service.
--	--------	------	--------	---------	----------

A visual internal inspection was completed on this bullet during the June 2018 outage. The bullet was cleaned prior to opening the manway. The returns to the truck were clean from the start. The bullet was then opened and a inspection was completed from the manway to determine the how clean it was. There were no signs of solids in the bullet. The vessel was then cleaned internal before inspection. During the internal inspection no corrosion or erosion was noted. The bullet is like brand new inside. No concerns.

A visual external inspection was completed on this bullet during the June 2018 outage. Dataplate secure and legible. A# stamped in vessel shell above d/p. Vessel and piping are in good condition, piping well supported. Paint in good condition, no significant deterioration noted. Ground cable securely attached directly to saddle support.

PAUT was completed in April of 2018 no indications were noted.

RECOMMENDATIONS							
NONCONFORMANCES / INSPECTION DEFICIENCIES							

**Form: QR-19.7a** Rev.: 2, Date: Jan 22<sup>nd</sup>, 2018

### PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD 07-27-51-19W5	Date June 19, 2018		SAP Equipment ID 66130683		Report #20180	0619GGb
Inspection Strategy		Availability		Inspection Ir	nterval	
Inspection Date	June 19, 2018	Date of Last Inspect	_	Date of Next	Inspect	June 2028
		_	-	•		

#### REPORT CERTIFICATION

	REPURIC	ERTIFICATION		
The signatures below certify that insp the specified equipment is considered			ied inspection	strategy and that
Inspected by	Greg Guenette		Date	June 21, 2018
Company	Husky Energy	IBPV # 334	API #	47818
Reviewed and Approved by	Greg Guenette		Date	June 21-2018
		IBPV # 334	API #	47818
Criticality Assessment Rerun		Inspection Planning Rerun		
Optional Rule Group Confirmed		Assessed Next Inspection Da	ate	

**Form: QR-19.7a** Rev.: 2, Date: Jan 22<sup>nd</sup>, 2018

### PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD 07-27-51-19W5 Date June 19, 2018 SAP Equipment ID 66130683 Report #20180619GGb

### **DETAILED INSPECTION VISUAL EXTERNAL**

ID	Description	Condition	Location VISU	NCR	Comments
V1	General Other (Please Explain)				
V2	General Corrosion	GOOD			
V3	General Leaks	GOOD			NONE NOTED
V4	Vibration				
V5	Dissimilar Flange Rating				
V6	Ladder/Stairway/Platforms				
V7	Heads	GOOD			
V8	Guy Wires				
V9	Electrical Ground	GOOD			
V10	Painted Inactive Corrosion	GOOD			
V11	Coating/Painting	GOOD			
V12	Expansion Joint or Bellows				
V13	Gauge/Site Glass	GOOD			
V14	Shell	GOOD			
V15	Jacket				
V21	Support Other (Please explain)				
V22	Foundation				
V23	Anchor Bolts	GOOD			
V24	Saddle/Skirt	GOOD			
V25	Davit				
V26	Fireproofing				
V31	Connections Other (Please				
	explain)				
V32	Small Branches				
V33	Nozzles	GOOD			
V34	Manways				
V35	Reinforcing Pads				
V36	Inadequate Thread Engagement	GOOD			NO SHORT BOLTING NOTED
V37	Bolting	GOOD			NO SHORT BOLTING NOTED
V38	Flanges	GOOD			
V39	Leak Clamps				
V41	Insulation Other (Please explain)				
V42	Damage				
V43	Penetrations				
V44	Insulation Jacket				
V45	Banding				
V46	Seals/Joints	1			
V51	Relief Devices Other (Please explain)	GOOD			PSV'S REMOVED AT TIME OF SERICING. SERVICE REPORTS WILL BE REVIEWED IN 2018
V52	Corrosion	GOOD			NONE NOTED
V53	Leaks	GOOD			NONE NOTED
V54	Restricted Inlet/Outlet				
V55	Manual Operation Lever				

**Form: QR-19.7a** Rev.: 2, Date: Jan 22<sup>nd</sup>, 2018

### PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD 07-27-51-19W5 Date June 19, 2018 SAP Equipment ID 66130683 Report #20180619GGb

**DETAILED INSPECTION VISUAL INTERNAL** 

ID	Description	Condition	Location	NCR	Comments
V1	General Other (Please Explain)				
V2	Corrosion (depth, length, width)	OK			NONE NOTED
V3	Erosion	OK			NONE NOTED
V4	Distortion	OK			NONE NOTED
V5	Blisters	OK			NONE NOTED
V6	Deposits	OK			NONE NOTED
V7	Heads	OK			ORGINAL CONSTRUCTION MARKINGS STILL PRESENT
V8	Welds	OK			
V9	Nozzles	OK			
V10	Shell	ОК			ORGINAL CONSTRUCTION MARKINGS STILL PRESENT
V11	Gasket Surfaces				
V21	Internals Other (Please explain)				
V22	Demister				
V23	Baffle/Weir				
V24	Sparger				
V25	Thermowells	OK			
V26	Metallic Linings				
V27	Nonmetallic Linings				
V28	Trays				
V29	Tray Rings				
V30	Other Welded Attachments				

Magnetic Particle Equipment records								
Procedure # Description								
Manufacturer	Model	Serial #	Current Type	Mag Part Type				
Lighting	Material + Grade	Thickness	Cal Block SN	Cal Due Date				

Liquid Penetrant Equipment records							
Procedure #		Description					
Penetrant	Solvent	Developer	Cleaner	Lighting	Material Grade + Thickness		

### **DETAILED INSPECTION OTHER TECHNIQUES**

ID	Location	Observation/Measurement	Acceptance Criteria	NCR	Comments
1					
2					
3					
4					
5					
6					
7					
8					
9					
10					

Ultrasonic Equipment records								
Procedure #		Description						
Test Unit	Instrument Mfr	Model #	Serial #	Cal Due Date				
Probe	Frequency	Probe SN	Probe Diameter	Couplant				
Cal Block	Cal Block Size	Cal Block SN	Cal Block Mtl					

Form: QR-19.7a Rev.: 2, Date: Jan 22<sup>nd</sup>, 2018

### PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD 07-27-51-19W5 Date June 19, 2018 SAP Equipment ID 66130683 Report #20180619G6b

#### **DETAILED INSPECTION UT THICKNESS**

CML	Nom. Thk	Current Reading	Short Term Corr Rate	Long Term Corr Rate	Remaining Life	Comments

Form: QR-19.7a Rev.: 2, Date: Jan 22<sup>nd</sup>, 2018

### PRESSURE VESSEL & COLUMN INSPECTION REPORT

LSD 07-27-51-19W5 Date June 19, 2018 SAP Equipment ID 66130683 Report #20180619GGb

#### **PHOTOS**

