



RBMI Entry Sept 22/17 sv

Form: QR-19.7d Rev: 0, Date: Jan 29th, 2016

BOILER INSPECTION REPORT

LSD 10-34-051-04-W4M Date: Aug 15, 2017 SAP Equipment ID 62066035 Report # 170815SDF005

LSD 10-34-051	-04-W4M	Date:	Aug 15, 2	017	SAP	Equipment ID	62066035	Repor	t # 170815SE)F005	
BOILER STATIC DATA											
					Op Unit Sys			m			
Prov. Insp. # NB#					CRN			Equip Tag #			
Equipment D	escription	Heating	Boiler		Ser			rial # 7119			
Manufacturer Saskatoon Boiler						Vessel Class					
Internal Access YES					Year Bu			Built	uilt 2011		
BOILER PROPER											
MAWP		psi	(@		°F	MDM	Т		°C /	
CODE	•			Glycol Sweet			PWH.	PWHT : N/A			
Operating Pr	essure 80)	psi Operating Tem			nperature	perature 125°F				
Diameter		Length (T/T)	mn	n/in C	DAL mm /	in		Horizon	tal	
Shell Mat	1	•	Thickn	ess		mm / i	n Corr A	llowan	се	mm / in	
Head Mat		Thickness				mm / i	n Corr A	llowan	се	mm / in	
Internal Coat	ing: NO		Interna	nternal Clad NO				city		m ³	
Manway Yes			Inspection Port YES				Legs	Legs			
Nozzle Rating	lozzle Rating 150 lb ANSI Painted			t	YES Insu			ated YES			
				EC	ONOMIZ	ZER					
MAWP		kPa / ps		@		°C / °F	MDM.			°C / °F	
CODE			Fluid Service			Sweet/Sour PWHT		Γ:			
Operating Pr	kPa / psi			Operating Temperature			°C / °F				
			-, -,			OAL mm / in Vertic			Horizon		
Shell Mat'l			Thickness mm/in				Corr Allowance mm / in Corr Allowance mm / in				
Head Mat'l			Thickness mm/in					ce	mm / in		
Internal Coating: YES NO			Internal Clad YES NO			-	Capacity m ³				
Manway YES NO		Inspection Port YE					Legs				
Nozzle Rating	9	lb ANSI	Painted		YES		Insul	ated	YES	NO	
	Landin	1 0			STATIC			T	Co.m.:!	Dete /	
Serial No.	Location	Se Press	sure	· · · · · · · · · · · · · · · · · · ·		Manufacturer			Company		
3933				7013 I	Titluonio			MOGABE Dec 15 / Guest			
PSV DETAILS											
Type (Thread/Flange) PRD Inlet 1.5" Male NPT				ANSI Rating				Size (mm)			
PRD Outlet 2.5" Female NPT											
PRD Outlet 2.5 Female NPT											

INSPECTION SUMMARY

-The Boiler was found fit for continued service with no outstanding concerns affecting the pressure boundary at time of inspection.

RECOMMENDATIONS

-Replace missing insulation around rear legs

NONCONFORMANCES / INSPECTION DEFICIENCIES

-None at the time of inspection.



Form: QR-19.7d

Rev: 0, Date: Jan 29th, 2016

BOILER INSPECTION REPORT

LSD 10-34-051-04-W4M Date: Aug 15, 2017 SAP Equipment ID 62066035 Report # 170815SDF005

Inspection Strategy Availability Inspection Interval 3 Years
Inspection Date Aug 2017 Date of Last Inspect Date of Next Inspect Aug 2020

REPORT CERTIFICATION The signatures below certify that inspections/tests have been completed in accordance with the identified inspection strategy and that the specified equipment is considered fit for service until the date of next inspection. Inspected by VE - Scott Fong Date Aug 15, 2017 Silvertip Inspection Services Company Ltd. IBPV# 78817(sk)/0187(ab) API# Reviewed and Approved by Date IBPV# API# **Criticality Assessment Rerun** Inspection Planning Rerun 2020 **Assessed Next Inspection Date**



Form: QR-19.7d Rev: 0, Date: Jan 29th, 2016

BOILER INSPECTION REPORT

LSD 10-34-051-04-W4M Date: Aug 15, 2017 SAP Equipment ID 62066035 Report # 170815SDF005

DETAILED INSPECTION VISUAL EXTERNAL

ID	Description	Condition	PECTION VISUAL EX	NCR	Comments
V1	General Other (Please Explain)	Good			No outstanding concerns, the equipment
V I	General Other (Flease Explain)	Good			was found in acceptable condition for
					continued service.
					The nameplate is intact and legible.
V2	General Corrosion	Good			No significant corrosion noted.
V3	General Leaks	Good			No leaks noted.
V4	Vibration	Good			No detrimental vibration noted.
V5	Dissimilar Flange Rating	Good			No outstanding concerns.
V6	Ladder/Stairway	N/A			
V7	Platforms	N/A			
V8	Guy Wires	N/A			
V9	Electrical Ground	Good			The boiler was bolted to the skid, and the
					skid was grounded.
V10	Painted Inactive Corrosion	N/A			
V11	Coating/Painting	Good			Boiler casing paint was in good condition.
V12	Expansion Joint or Bellows	N/A			
V13	Gauge/Site Glass	Good			Gauges and site glass appeared in good
1/4.4	Oball	NI/A			working condition.
V14	Shell	N/A			
V15	Jacket	N/A			
V21	Support Other (Please explain)	N/A			
V22	Foundation	Good			Boiler legs were bolted to the skid.
V23	Anchor Bolts	Good			No significant deterioration noted.
V24	Saddle/Skirt	N/A			
V25	Davit	Good			No concerns with the davits/hinges.
V26	Fireproofing	N/A			
V31	Connections Other (Please	Good			All piping connections to the boiler are
٧٥١	explain)	Good			secure.
V32	Small Branches	Good			There are no concerns with small branch
					connections.
V33	Nozzles	Good			All visible nozzles are straight with no mechanical deficiencies noted
V34	Manways	N/A			Thechanical deliciencies noted
V35	Reinforcing Pads	N/A			
V36	Inadequate Thread Engagement	Good			No short studs or bolting noted.
V37	Bolting	Good			No missing bolts or study noted.
V38	Flanges	Good			No significant misalignment noted.
V39	Leak Clamps	N/A			The digitilicant fineding information.
V41	Insulation Other (Please explain)	Fair			Some insulation missing near the rear legs.
V42	Damage	N/A			Come mediation meening floar the roal logo.
V42 V43	Penetrations	N/A			
V43	Insulation Jacket	Fair			Some cladding around the rear legs is
					loose.
V45	Banding	N/A			
V46	Seals/Joints	N/A			
V51	Relief Devices Other (Please explain)	Good			No concerns with the PSV.
V52	Corrosion	Good			No significant corrosion noted on the PSV
V53	Leaks	Good			No leaks noted
V54	Restricted Inlet/Outlet	Good			No restrictions noted on the PSV inlet or outlet.
V55	Manual Operation Lever	Good			Manual lever on PSV appeared in good
¥ 00	Manda Operation Level				condition.



Form: QR-19.7d Rev: 0, Date: Jan 29th, 2016

BOILER INSPECTION REPORT


LSD 10-34-051-04-W4M

Date: Aug 15, 2017

SAP Equipment ID 62066035

Report # 170815SDF005

PHOTOS





Nameplate



Overview









PSV tag

Missing Insulation and loose cladding