		GENERAL PR	FSSIIRE	VESSEL INFORMATION	T				
District: Wembly			ESSURE		N				
Facility: Goodfare	Field			Skid No. 6126					
		mber: 3 Phase Separa		Location (LSD) 06-21-7	2-11 W6M				
Orientation: Verti		mber: 5 Phase Separa	ator						
Status: operating		BDECGUDE		Regulatory Inspection					
"A" on "C" "C"	C. 1.) P.C.	PRESSURE	VESSEL	NAMEPLATE DATA					
"A" or "G" or "S" (Sask.) or BC Registration Number. A# 455071				CRN Number L-7115.2					
Vessel serial number	er: C9390.VS			Size (diameter x length-	estimate if necessar	ry): 20 in y '	7 ft 6 in		
Shell thickness: 26.2			Size (diameter x length- estimate if necessary): 20 in.x 7 ft 6 in. Shell material: SA 106 B						
Head thickness: 22.2				Head material: SA 516 70					
Tube wall thickness			Tube material:						
Tube diameter:			Tube length:						
Channel thickness:				Channel material:					
	Shell: 992	3 Кра		Chamier material.					
Design pressure	Tubes:			Operating pressure	Shell:				
	Shell: 54 C	1			Tubes:				
Design Temp.				Operating temperature	Shell:				
	Tubes:				Tubes:				
X-ray: RT 2				Heat treatment: NO					
Code parameters: A	SME VIII			Joint efficiency (if on nan	neplate):				
Manufacturer: RUSI				Year built: 2000	1				
Corrosion allowance	: 1.6 mm			Manway? No					
		PRESSURE SAF	ETY VAL	VE NAMEPLATE DATA	1				
Tag Number(s)	Set Pressure	CRN#		ufacturer /Model /Serial # Code Stamp	Capacity (Scfm)	Size	Set Date		
Shell Side G#600570	1100 Psi	None		Wellmark/W9501RS- 1600/40778/UV 2952 1"x1" N					
Tube Side G#									
		SERVICE CONDT	IONS-IND	DICATE ALL THAT APP	LY				
Sweet			Oil		Gas		Water		
Amine	LPG Con			lensate	Air		Glycol		
Other (Describe):									
nspection Interval Determined by MIC in con- eports reviewed and accep Mechanical Integrity	ted by:	PESL		# 77	ogram)	er Ma	axitra		
iccuanical integrity	Coordinatol	-			_Date	700 10	F 000		


External Inspection Items		F	P	N/A	Comments
Insulation Verify sealed around manways,	X				Poof real! 1
nozzles, no damage present, and there is no					Roof seal inplace
egress of moisture.					
External Condition Assess paint condition,	X				Paint in availlant at 122
areas peeling, record any corrosion, damage,	1				Paint in excellent condition, no peeling blistering or fading
etc (record location, size and depth of					
corrosion or damage)					
Leakage Record any leakage at flanges,	X				None
threaded joints, weep holes on repads, etc.					None
Skirt/ Saddle Assess condition of paint, fire	X				Attached to Clin I
protection, concrete. Look for corrosion,					Attached to Skid package via skirt
buckling, dents, etc. Look at vessel surface					Constant Control of the Control of t
area near supports. Verify no signs of leakage					Grounding cable firmly inplace to the skid package
at attachment to vessel and attachment welds					
are acceptable. Ground wire attached?					
Anchor Bolts Hammer tap to ensure secure.	X				Anchart to C. 1.3.1
Look for cracking in treads or signs of					Anchor bolts firmly inplace
deformation.					
Concrete foundation Check for cracks,				X	
spalling, etc.				^	
Ladder / Platform Describe general				X	
condition, ensure support is secure to vessel,				^	
describe any hazards.					
Nozzle Assess paint, look for leakage, and	X	-	-		D. C.
ensure stud threads are fully engaged. Record	^				Paint intact, no deflections, no short bolting
any damage, deflection, etc. Are nozzles					
gusseted?					
Gauges Ensure gauges are visible, working,	X				Clean and also wild in the
no leakage, and suitable for range of MAWP/	1				Clean and clear, within the operational range of the vessel
Temp.					
External Piping Ensure pipe is well	X				Wall supported point in the Unit
supported. All clamps, supports, shoes, etc. in					Well supported, paint in good condition,
place. Look for evidence of structural					
overload, deflection, etc. Paint condition,					
external corrosion?					
Valving Ensure no leaks are visible. Valves	X				No wooning on looking at 1
are properly supported and chained if	*				No weeping or leaking valves or fittings
necessary.					
PSV Ensure PSV is set at pressure at or below	X				Located on unner shall get at MANUP C
that of vessel. Discharge piping is same size as	**				Located on upper shell – set at MAWP of vessel.
inlet to valve and is properly supported and					
routed. Ensure no block valves between psv					
and vessel or if there are they are locked open.					
NDE methods Was UT/ MPI done on vessel	X		_		IIT correction gurway comission at the state of the state
(MI coordinator to review results)					UT corrosion survey carried out – No metal detected below nominal minus corrosion allowance.
Other			+		nominal fillius corrosion allowance.

Recommendations or corrective actions: Vessel is Fit for Service or describe corrective actions required) (MIC to review corrective actions with Operations, discuss with Chief Inspector where necessary, and get remedial action implemented)

Inspected By: ____Michael Parsons____

______Date: ____March 2 - 2005





Dverview Photo

Data Plate Photo

Inspected By:____Michael Parsons____

_Date:____March 2 2005