R&L Pampjack Services

Date 2020-01-08

Company **Implay**

Lease Area and WO Na

R&L Operator Trevor Letendre Serial # NYYT-91208-05JC

SF 16-1-43-8w5

DH Asset ID# 02/16-12-43-8w5

Unit Make Sentry **Unit Size** 912

Unit Structure C912D-365-192

Gearbox Make & Serial Sentry/NYYT-91208-01JO

Oil Level Good Oil Condition Good **Shaft Cover Seal Leaks** O.K. **Brake Conditions** O.K. **Brake Cable** O.K. **Brake Drum Size**

Brake Shoe Size 17" Jackshaft Sheave Size in out Na Jack Sheave Size

7c50" **Motor Frame** 404T

Motor Make and Serial # Westinghouse/ UCE71773E2011

17"

Motor HP 60

Motor Sheave Size 4c8" 2 7/8 shaft

Motor RPM 1180 Ratio 28-8 to1

Stroke Length 192" long stroke Stroke Position 3 of 3 long stroke

Jackshaft Make Size Na Jackshaft Belts Sizes Na **Motor Belts Sizes** 4c255

Belt Condition Medium Wear, O.K.

SPM Not running Comments Fair shape

Lube Type Grease

Left Seal Medium Wear,O.K.
Right Seal Medium Wear,O.K.

Left Bearing Heavy Wear, Medium Wear, Repair
Right Bearing Heavy Wear, Medium Wear, Repair

Left Pin Yes corrosion reset
Right Pin Yes Corrosion reset

Comments Found filings in bearings

Lube Type Grease

Left Seal Medium Wear,O.K.

Left Bearing Medium Wear,O.K.

Equalizer Shaft Medium Wear,O.K.

Right Seal Medium Wear,O.K.

Right Bearing Medium Wear,O.K.

Comments Fair condition

High Speed Gear

Secondary Gear

Low Speed Gear

High Speed Bearings

Medium Wear,O.K.

Medium Wear,O.K.

Medium Wear,O.K.

Medium Wear,O.K.

Medium Wear,O.K.

Medium Wear,O.K.

Aux Wiper System yes

Carrier Bar Size and Make Sentry horn style

Bridle Condition Ok
Bridle Length if Replacement Na

needed

Balance Not Running

Weight Size and Position
4- Sentry wts full out wts have no #'s
Level Alignment
Good head is off and next to the unit

Left Seal Medium Wear,Ok

Left Bearing Medium Wear,Ok to Run

Center Shaft Medium Wear,O.K.
Right Seal Medium Wear,O.K.
Right Bearing Medium Wear,O.K.

Comments Grease is burnt slight leaks

Information Cracks
Na
Tie Downs
Good
Bolts
Good
Rod Rotator
Na

Pitmans

Base sleeper Size and

Condition

Throat Bolt

Remarks

Good

8x32 double rail on piles

Head pin

Repair wps and reset pins tighten saddle bolts / tighten tailbolts

Pictures

