

## **Daily Service and Time Report**

Service Report Detail	Equipment Details			
Cust Name: TAQA NORTH LTD	Emp Name: Brandon Reyda	Work Order: 1596879	Make: Waukesha	SMU:  SMU Indicator: H  Job Complete?
Cust Unit #:	Work Date: 2017/03/20	MCO: 0060446869  Customer Work Order #	Model: W19L7042GL Location: 7-4-113-4W6	
Cust PO #:	Facility: GRANDE PRAIRIE POWER SYSTEMS			
ID: a18370000011ELm	Block Labour WO #:		Serial Number: C-13563/1	

Time Report					Repair Information	
Operation	Customer Charge Code	Start Time	Stop Time	Total Hours	Complaint: PERFORM ENGINE SERVICE	
ENGINE TROUBLESHOOT IN FIELD - 15	ST	3/20/2017 5:00 AM	3/20/2017 7:00 AM	2.00	Correction: went to PR branch to load parts, no parts on GWC shelf, could not find parts wait for PR warehouse staff to arrive, parts were on the shipping pallet in the corner behind undercarriage pallets, load parts, travel from peace river to hig level, top up fuel, travel to site, receive safe work permit, did JHA, went over booster unit, operator had unit shut down when I came in building, brought in tools and parts, removed ignition wiring, removed coils, removed spark plugs perform compression test, good, document numbers, all 220-230 psi, remove valve covers, removed old gaskets, perform valve set, torqued all adjustment nuts, gapped, installed and torqued new spark plugs, installed valve covers with new gaskets, installed coils and ignition wiring, replaced final filter assy, bump all fan bearings good, belts a bit loose, tighten belts for water pump drive, operator drained engine oil, refilled engine oil, replaced compressor differential filters and engine oil filters, replaced air filters, did not install prefilters, restart unit, noticed air leak on LH side at carb to manifold connection, shut unit down, removed fuel pressure regulator, removed air intake tube, removed mounting bolts and nuts, removed housing, made new	
ENGINE TRAVEL TO/FROM - 9951	ST	3/20/2017 7:00 AM	3/20/2017 11:30 AM	4.50		
ENGINE TROUBLESHOOT IN FIELD - 15	ST	3/20/2017 11:30 AM	3/20/2017 1:00 PM	1.50		
ENGINE TROUBLESHOOT IN FIELD - 15	тн	3/20/2017 1:00 PM	3/20/2017 7:30 PM	6.50		
ENGINE TRAVEL TO/FROM - 9951	ТН	3/20/2017 7:30 PM	3/20/2017 8:00 PM	0.50		
Total Hours: 15.0 gasket with gasket paper, reassembled unit, restart		gasket with gasket paper, reassembled unit, restart unit, no leaks, load unit, monitor unit, good, cleaned up tools and parts, load into truck, travel to camp, did time and report				
Warranty Information		<b>第二八百</b>			Complication:	
Possible Warranty: No			Failure Date:		Additional Information:	
Repair Comments:			Repair Date:			
Error Reason 1					Resultant Damage?	
Error Reason 2	-				Resultant Damage Description:	
Product Inoperable? No			Durability		Signatures  Employee Signature:	
Part No. Responsible:			PCF Serial Number:			
Group Part Number:			PCF Meters:			
SMCS Code:			PCF Code: H		Finning Supervisor Signature:	
ighway Truck Information			Travel Information			
ruck Model: W19L7042GL			Start Location:			
in:			Stop Location:		Customer Signature:	
ehicle Config:			Number of Trips:			
	0.00					