



Daily Service and Time Report

| Service Report Detail | | Equipment Details | | |
|----------------------------------|---|------------------------------|------------------------------------|----------------------------|
| Cust Name: TAQA NORTH LTD | Emp Name: Bob Wilson | Work Order: 1686978 | Make: | SMU: |
| Cust Unit #: | Work Date: 2018/03/01 | MCO: 0060512889 | Model: W19L7042GL | SMU Indicator: H |
| Cust PO #: | Facility: GRANDE PRAIRIE POWER SYSTEMS | Customer Work Order # | Location: EQYARD | Job Complete? No |
| ID: a1837000001QPJs | Block Labour WO #: | | Serial Number: C-13563/1 | |

| Time Report | | | | | Repair Information |
|---|-----------------------------|----------------------|-------------------|--------------------|--|
| Operation | Customer Charge Code | Start Time | Stop Time | Total Hours | Complaint: LSD: 07-04-113-04 W6 SITE: EAST SOUSA UNIT: BOOSTER UNIT 7042GL SN: C-13563/1 COST CENTER: 1600012 GL MAJOR/MINOR: 9200-802 APPROVER: SCOTT HUDSON TAQA WO: 1007074 PERFORM 3000HR SERVICE ON COMPRESSOR. |
| ENGINE TRAVEL TO/FROM - 9951 | ST | 3/1/2018 6:00 AM | 3/1/2018 12:30 PM | 6.50 | |
| 2000 SERVICE HOUR PERFORM AT CUSTOMERS SITE - 5 | ST | 3/1/2018 12:30 PM | 3/1/2018 2:00 PM | 1.50 | |
| 2000 SERVICE HOUR PERFORM AT CUSTOMERS SITE - 5 | TH | 3/1/2018 2:00 PM | 3/1/2018 8:30 PM | 6.50 | |
| ENGINE TRAVEL TO/FROM - 9951 | TH | 3/1/2018 8:30 PM | 3/1/2018 10:00 PM | 1.50 | |
| Total Hours: | | | | 16.0 | |
| Warranty Information | | | | | Cause: |
| Possible Warranty: No | | Failure Date: | | | Correction: -travel to and from location -site permit/jha -assist with 3000hr service -clean up tools/work area -do up paperwork |
| Repair Comments: | | Repair Date: | | | Complication: |
| Error Reason 1 | | | | | Additional Information: |
| Error Reason 2 | | | | | Resultant Damage? |
| Product Inoperable? No | | | | | Resultant Damage Description: |
| Part No. Responsible: | | | | | Signatures |
| Group Part Number: | | | | | Employee Signature: |
| SMCS Code: | | | | | Finning Supervisor Signature: |
| Highway Truck Information | | | | | Customer Signature: |
| Truck Model: W19L7042GL | | | | | |
| VIN: | | | | | |
| Vehicle Config: | | | | | |
| Cab Type: | | | | | |



Daily Service and Time Report

| Service Report Detail | | Equipment Details | | |
|----------------------------------|---|------------------------------|------------------------------------|----------------------------|
| Cust Name: TAQA NORTH LTD | Emp Name: Jason Troup | Work Order: 1686978 | Make: | SMU: |
| Cust Unit #: | Work Date: 2018/02/28 | MCO: 0060512889 | Model: W19L7042GL | SMU Indicator: H |
| Cust PO #: | Facility: GRANDE PRAIRIE POWER SYSTEMS | Customer Work Order # | Location: east sousa plant | Job Complete? No |
| ID: a1837000001QS71 | Block Labour WO #: | | Serial Number: C-13563/1 | |

| Time Report | | | | | Repair Information |
|---|-----------------------------|-----------------------|---------------------------------|--------------------|--|
| Operation | Customer Charge Code | Start Time | Stop Time | Total Hours | Complaint: LSD: 07-04-113-04 W6 SITE: EAST SOUSA UNIT: BOOSTER UNIT 7042GL SN: C-13563/1 COST CENTER: 1600012 GL MAJOR/MINOR: 9200-802 APPROVER: SCOTT HUDSON TAQA WO: 1007074 PERFORM 3000HR SERVICE ON COMPRESSOR. |
| 2000 SERVICE HOUR PERFORM AT CUSTOMERS SITE - 5 | ST | 2/28/2018 11:00 AM | 2/28/2018 12:30 PM | 1.50 | |
| Total Hours: | | | | 1.5 | |
| Warranty Information | | | | | Cause: |
| Possible Warranty: No | | | Failure Date: | | Correction: load parts, stock truck and verify special tooling for service truck |
| Repair Comments: | | | Repair Date: | | Complication: |
| Error Reason 1 | | | | | Additional Information: |
| Error Reason 2 | | | | | Resultant Damage? |
| Product Inoperable? No | | | Durability Indicator: No | | Resultant Damage Description: |
| Part No. Responsible: | | | PCF Serial Number: | | Signatures |
| Group Part Number: | | | PCF Meters: | | Employee Signature: |
| SMCS Code: | | | PCF Code: H | | |
| Highway Truck Information | | | Travel Information | | |
| Truck Model: W19L7042GL | | | Start Location: | | |
| VIN: | | | Stop Location: | | |
| Vehicle Config: | | | Number of Trips: | | |
| Cab Type: | | | Distance: | | |
| Delivery Date: | | | Total Hours: | | |
| | | | Reason for Accomodation? | | |
| | | | Field Truck Unit #: | | |
| | | | | | Finning Supervisor Signature: |
| | | | | | Customer Signature: |



Daily Service and Time Report

| Service Report Detail | | Equipment Details | | |
|----------------------------------|---|------------------------------|------------------------------------|----------------------------|
| Cust Name: TAQA NORTH LTD | Emp Name: Jason Troup | Work Order: 1686978 | Make: | SMU: |
| Cust Unit #: | Work Date: 2018/03/01 | MCO: 0060512889 | Model: W19L7042GL | SMU Indicator: H |
| Cust PO #: | Facility: GRANDE PRAIRIE POWER SYSTEMS | Customer Work Order # | Location: EQYARD | Job Complete? No |
| ID: a1837000001QS7B | Block Labour WO #: | | Serial Number: C-13563/1 | |

| Time Report | | | | | Repair Information |
|---|----------------------|---------------------------------|-------------------|-------------|--|
| Operation | Customer Charge Code | Start Time | Stop Time | Total Hours | Complaint: LSD: 07-04-113-04 W6 SITE: EAST SOUSA UNIT: BOOSTER UNIT 7042GL SN: C-13563/1 COST CENTER: 1600012 GL MAJOR/MINOR: 9200-802 APPROVER: SCOTT HUDSON TAQA WO: 1007074 PERFORM 3000HR SERVICE ON COMPRESSOR. Cause: Correction: travel to site fuel up in high level on way get safe work permit and do jha remove coils, extensions and spark plugs remove plug carriers and prechamber cups remove rocker assemblies and replace all pushtubes with tubes from on site stock as 80 percent of pushtube hydraulics were soft. reassemble all rockers and set all valves inspect front seal on gear box is leaking, along with majority of hoses. install prechamber cups and carriers compression test at 180psi across the board bob borescoped and there was no major scoring or issues with valves install valve covers, spark plugs, extensions, and coils reseal final filter housing and clean final filter clean up building fire up unit and warmup put unit on line and clean up tooling travel to town Complication: Additional Information: Resultant Damage? Resultant Damage Description: |
| ENGINE TRAVEL TO/FROM - 9951 | ST | 3/1/2018 6:00 AM | 3/1/2018 11:30 AM | 5.50 | |
| 2000 SERVICE HOUR PERFORM AT CUSTOMERS SITE - 5 | ST | 3/1/2018 11:30 AM | 3/1/2018 2:00 PM | 2.50 | |
| 2000 SERVICE HOUR PERFORM AT CUSTOMERS SITE - 5 | TH | 3/1/2018 2:00 PM | 3/1/2018 8:30 PM | 6.50 | |
| ENGINE TRAVEL TO/FROM - 9951 | TH | 3/1/2018 8:30 PM | 3/1/2018 10:00 PM | 1.50 | |
| Total Hours: | | | | 16.0 | |
| Warranty Information | | | | | |
| Possible Warranty: No | | Failure Date: | | | |
| Repair Comments: | | Repair Date: | | | |
| Error Reason 1 | | | | | |
| Error Reason 2 | | | | | |
| Product Inoperable? No | | Durability Indicator: No | | | |
| Part No. Responsible: | | PCF Serial Number: | | | |
| Group Part Number: | | PCF Meters: | | | |
| SMCS Code: | | PCF Code: H | | | |
| Highway Truck Information | | Travel Information | | | |
| Truck Model: W19L7042GL | | Start Location: | | | |
| VIN: | | Stop Location: | | | |
| Vehicle Config: | | Number of Trips: | | | |
| Cab Type: | | Distance: | | | |
| | | | | | Employee Signature: |
| | | | | | Finning Supervisor Signature: |