

Alberta Auto and Truck Repair Inc

11/16/2022 12:01:46 PM

4150B 14A St SE
Calgary, AB T2G3L3

Phone: 403-543-1000 Fax: 403-543-1005

Invoice #
44712

GST # 89833 8769 RT0001

1999 Coachman Sportcoach white

Odometer In: 75692 Odometer Out: 75692
License: 952389 VIN: 4UZ6XFBC8WC952389
Eng: Diesel
Unit #: Motorhome

Vehicle Time In: 2022-10-07 9:53:12AM

Description Of Services

Symptom: Check Brakes & Shock Absorber Condition

MOTORHOME CLASS A DIESEL FULL SERVICE - Perform Maintenance Inspection. Change Oil & Filter. Replace Fuel Filters & Lubricate Chassis.

Completed Full Service w/Checklist

Issue(s):

Right Front Marker Light Out
Water In The Head Lamp
Right Rear Drive Axle Inner Tire Off Bead
Serpentine Belt Loose
Hydraulic Tank Hose Leaking
Rear Weather Bags Cracked

Description	Quantity	Sale	Extended
Spin-on Oil Filter	1.00	\$58.00	\$58.00
Fuel/Water Separator	1.00	\$44.85	\$44.85
Fuel Fiter	1.00	\$62.65	\$62.65
15W40 CJ4 Diesel oil	19.00	\$7.99	\$151.81

Labor: \$489.95 Parts: \$317.31 Tire Fees: \$0.00 Sublet:\$0.00 Job Total: \$807.26

AIR CLEANER ELEMENT - R&I **Manufacturer Recommends Replacing When The Restriction Indicator Shows Restriction, Or Annually, Whichever Occurs First**

All Applicable Models - [Includes R&I of air cleaner element, inspecting sealing surface & ducting]

Customer Approves Replacement

Customer Declined Replacement. Owner/Customer Is Aware That Any Engine Damage From Air Cleaner Element Failure Is Not Warrantable.

Customer Initials

Description	Quantity	Sale	Extended
Air Filter	1.00	\$455.99	\$455.99

Labor: \$119.60 Parts: \$455.99 Tire Fees: \$0.00 Sublet:\$0.00 Job Total: \$575.59

RV DIFFERENTIAL SERVICE (does not incl.parts)

Drained Housing
Filled Differential With 10 lts Of New 75w90 Gear Oil
Checked For Leaks, Non Present

Description	Quantity	Sale	Extended
75W90 Synthetic Gear Oil	10.00	\$21.90	\$219.00

Labor: \$127.60 Parts: \$219.00 Tire Fees: \$0.00 Sublet:\$0.00 Job Total: \$346.60



Alberta Auto and Truck Repair Inc

4150B 14A St SE
Calgary, AB T2G3L3

Phone: 403-543-1000 Fax: 403-543-1005

11/16/2022 12:01:46 PM

Invoice #
44712

GST # 89833 8769 RT0001

1999 Coachman Sportcoach white

Odometer In: 75692 Odometer Out: 75692
License: 952389 VIN: 4UZ6XFBC8WC952389
Eng: Diesel
Unit #: Motorhome

Description Of Services

Continued From Previous Page

COOLING SYSTEM - Flush, Replace Coolant Filter If Required.

Diesel - [DOES NOT include R&I Thermostats.]

Perform RV Coolant Flush
Drained Radiator And Associated Hoses And Lines In Engine Area
Used Compressed Air To Blow Out Heater Lines Running To The Front Of The Coach
Filled Coolant System, Ran Unit With HVAC On High Heat
Topped Up System
Test Drive Needed

Description	Quantity	Sale	Extended
Antifreeze Extended Life (Red)	49.00	\$5.99	\$293.51

Labor: \$319.00 Parts: \$293.51 Tire Fees: \$0.00 Sublet:\$0.00 Job Total: \$612.51

Symptom: Steering & Fan System

(Steering System) HYDRAULIC SYSTEM - Flush

All Applicable Models

Remove Return Hose & Place Into Drain Pan.
Filled System Up & Ran Engine To push Old Fluid Out While Maintaining Level With New Fluid.
When Fluid Clean, Re-connected Hose To Reservoir, Adjust Fluid Level & Clean Off Residue.

Description	Quantity	Sale	Extended
Hydraulic Oil S1 M 32	19.00	\$9.99	\$189.81

Labor: \$466.70 Parts: \$189.81 Tire Fees: \$0.00 Sublet:\$0.00 Job Total: \$656.51

HYDRAULIC FILTER(S) - Replace

Unit not equipped with a hydraulic filter.

Symptom: Jack System

(Leveling Jacks) HYDRAULIC SYSTEM SERVICE - Replace Fluid1.6

Drained And Replaced Hydraulic Fluid In Leveling System
Operated System To Bleed Out Any Air
Topped Up Fluid Level In The Reservoir

Description	Quantity	Sale	Extended
Dexron 3/Mercon Transmission Fluid	6.00	\$12.88	\$77.28

Labor: \$179.50 Parts: \$77.28 Tire Fees: \$0.00 Sublet:\$0.00 Job Total: \$256.78

Symptom: Door Handle That Locks The Screen Door To The Main Door Needs To Be Remounted.

Parts Are Inside The Door.

INTERIOR DOOR HANDLE - Screen Door - Repair As Required

Installed Screen Locking Handle With Extra Washers To Properly Secure It.

Description	Quantity	Sale	Extended
Gr8 Flat Washer 7/16	2.00	\$0.96	\$1.92

Labor: \$89.75 Parts: \$1.92 Tire Fees: \$0.00 Sublet:\$0.00 Job Total: \$91.67

(Additional Oct20/22) AIR SPRING - R&I - Front (One)

Used Jack Stands On The Frame To Hang The Front End Suspension.
Removed Passenger Side Air Bag
Installed New Air Bag With New Hardware
Tested Operation, Good



Alberta Auto and Truck Repair Inc

11/16/2022 12:01:46 PM

4150B 14A St SE
Calgary, AB T2G3L3

Phone: 403-543-1000 Fax: 403-543-1005

Invoice #
44712

GST # 89833 8769 RT0001

1999 Coachman Sportcoach white

Odometer In: 75692 Odometer Out: 75692
 License: 952389 VIN: 4UZ6XFC8WC952389
 Eng: Diesel
 Unit #: Motorhome

Description Of Services

Continued From Previous Page

<u>Description</u>	<u>Quantity</u>	<u>Sale</u>	<u>Extended</u>
Front Air Spring	1.00	\$380.00	\$380.00
3/4 UNC GR8 Nylon Lock Nut	4.00	\$2.64	\$10.56
Gr8 Flat Washer 3/4	4.00	\$1.44	\$5.76

Labor: \$220.79	Parts: \$396.32	Tire Fees: \$0.00	Sublet: \$0.00	Job Total: \$617.11
------------------------	------------------------	--------------------------	-----------------------	----------------------------

(Additional Oct20/22) AIR SPRING - R&I - Both Rear

Used Jack Stands On The Frame To Hang The Rear End Suspension.
 Removed Both Air Bags
 Installed New Air Bags With New Hardware
 Tested Operation, Good

<u>Description</u>	<u>Quantity</u>	<u>Sale</u>	<u>Extended</u>
Rear Air Spring	2.00	\$565.00	\$1,130.00

Labor: \$718.00	Parts: \$1,130.00	Tire Fees: \$0.00	Sublet: \$0.00	Job Total: \$1,848.00
------------------------	--------------------------	--------------------------	-----------------------	------------------------------

Symptom: Right Front Marker Light Not Working

(Additional Oct20/22) EXTERIOR MARKER LIGHTS - Test Operation, Diagnose & Repair Or Advise

Removed Lens
 Tested For Power And Ground At The Marker Light. NO Voltage At Fixture
 Found Burnt Out Fuse Under Dash In Fuse Box
 Replaced Fuse, Power At Marker Light Returned
 Light Bulb Socket Had A Broken Clip
 Replaced Socket
 Tested Operation, Good

<u>Description</u>	<u>Quantity</u>	<u>Sale</u>	<u>Extended</u>
Twist In Light Socket	1.00	\$17.96	\$17.96
Non Insulated Butt Connector 22-16ga	2.00	\$0.88	\$1.76
3/16 Heat shrink	2.00	\$4.80	\$9.60
ATO Blade Fuse	1.00	\$1.75	\$1.75
Bulb	1.00	\$2.05	\$2.05

Labor: \$143.60	Parts: \$33.12	Tire Fees: \$0.00	Sublet: \$0.00	Job Total: \$176.72
------------------------	-----------------------	--------------------------	-----------------------	----------------------------

Symptom: Headlamp Has Water In It

(Additional Oct20/22) EXTERIOR HEADLIGHTS - Test Operation, Diagnose & Repair Or Advise

Drilled A Hole To Let The Water Drain Out Of the Headlamp Assembly

Labor: \$35.90	Parts: \$0.00	Tire Fees: \$0.00	Sublet: \$0.00	Job Total: \$35.90
-----------------------	----------------------	--------------------------	-----------------------	---------------------------

Symptom: Drive Belt Loose

(Additional Oct20/22) DRIVE BELT - Inspect For Abnormal Noise, Includes Pulleys & Tensioners

Inspected Drive Belt And Pulleys
 Found AC Compressor Was Loose
 Removed Hardware And Found One Of The Mounting Bolt Was Broken. Photo Sent To Mr. Singh.
 The Broken Bolt will need to be extracted and the A/c Mounting Plate Will Need To Be Re-secured

<u>Description</u>	<u>Quantity</u>	<u>Sale</u>	<u>Extended</u>
Belt - A/C	1.00	\$50.96	\$50.96

Labor: \$143.60	Parts: \$50.96	Tire Fees: \$0.00	Sublet: \$0.00	Job Total: \$194.56
------------------------	-----------------------	--------------------------	-----------------------	----------------------------



Alberta Auto and Truck Repair Inc

11/16/2022 12:01:46 PM

4150B 14A St SE
Calgary, AB T2G3L3

Phone: 403-543-1000 Fax: 403-543-1005

Invoice #
44712

GST # 89833 8769 RT0001

1999 Coachman Sportcoach white

Odometer In: 75692	Odometer Out: 75692	
License: 952389	VIN: 4UZ6XFBC8WC952389	
	Eng: Diesel	
Unit #: Motorhome		

Description Of Services

Continued From Previous Page

(Additional Oct 31/22) BROKEN BOLTS IN A/C MOUNTING HARDWARE - 1 - Drill, Extract & Re Thread. Does Not Include Removal Of Part Or Component.

Disconnected batteries & welded a nut onto broken bolt. Removed broken bolt & cleaned all threads with a tap.

Labor: \$359.00	Parts: \$0.00	Tire Fees: \$0.00	Sublet: \$0.00	Job Total: \$359.00
------------------------	----------------------	--------------------------	-----------------------	----------------------------

(Additional Oct 31/22) REMOUNT A/C COMPRESSOR TO ENGINE BLOCK - Replace Hardware

Install adapter to engine & re-install AC mounting bracket.
Re-install AC compressor.
Had to remove engine cooling fan to replace AC drive belt.
Re-install fan & tighten belt tension.

<u>Description</u>	<u>Quantity</u>	<u>Sale</u>	<u>Extended</u>
M10x 30 Socket Head Capscrew GR 12.9	3.00	\$5.95	\$17.85

Labor: \$179.50	Parts: \$17.85	Tire Fees: \$0.00	Sublet: \$0.00	Job Total: \$197.35
------------------------	-----------------------	--------------------------	-----------------------	----------------------------

Symptom: Right Rear Inner Tire Off Bead

(Additional Oct20/22) TIRE LEAK REPAIR - HD - Mark Tire Position, Dismount Tire From Rim, Inspect Tire Condition & Patch.

[Does Not Include Balancing]

Placed Rear Axle On Jack Stands
Removed Right Side Drive Tires
Found Both Tires Were Leaking
Inner Tire Has Severe Cracks On The Side Wall (Photos Sent)
Recommend Replacing Both tires As A Set.

(Additional Oct 31/22) TIRE - HD - Replace & Balance, Two Wheels.

Placed rear axle on jack stands
Removed wheels, marked and dismount 2 tires
Cleaned both rims with wire brush, replaced valve stems
Mounted and balanced both tires, installed wheels, torqued to 330ft/lbs, installed chrome covers
Adjusted tire pressures.

<u>Description</u>	<u>Quantity</u>	<u>Sale</u>	<u>Extended</u>
Tires Size: 245/75R22.5	2.00	\$914.80	\$1,829.60
Tire Fee 2	2.00	\$14.00	\$28.00
Frieght	1.00	\$310.00	\$310.00
Truck Stem 3.75" 0.625 Dia.	2.00	\$7.80	\$15.60
LT2 6oz Truck Wheel Weight	1.00	\$5.80	\$5.80
LT2 5oz Truck Wheel Weight	1.00	\$4.10	\$4.10
LT2 3oz Truck Wheel Weight	2.00	\$2.30	\$4.60

Labor: \$220.00	Parts: \$2,169.70	Tire Fees: \$28.00	Sublet: \$0.00	Job Total: \$2,417.70
------------------------	--------------------------	---------------------------	-----------------------	------------------------------



Alberta Auto and Truck Repair Inc

4150B 14A St SE
Calgary, AB T2G3L3
Phone: 403-543-1000 Fax: 403-543-1005

11/16/2022 12:01:46 PM

Invoice #
44712

GST # 89833 8769 RT0001

1999 Coachman Sportcoach white

Odometer In: 75692 Odometer Out: 75692
License: 952389 VIN: 4UZ6XFC8WC952389
Eng: Diesel
Unit #: Motorhome

Description Of Services

Continued From Previous Page

Service Advisor: D'Aversa, Gino

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.

I hereby authorize the above repair work to be done along with the necessary materials and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere for the purpose to testing and/or inspection at my risk. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Company assumes no vehicle responsibility for loss due to theft/damage while the unit is here for repairs/storage. ENSURE WHEEL NUTS FOR CORRECT TORQUE WITHIN 100 KM

RV'S - NO WARRANTY OR GUARANTEE ON YOUR GLASS INSTALLATION OR GASKET
RV'S - NO WARRANTY OR GUARANTEE ON POP OUT ISSUES OF COACH WINDSHIELDS OR STRESS CRACKS

Labor Total:	\$3,812.49
Parts Total:	\$5,352.77
Shop Sup.:	\$199.99
HazMat:	\$95.00
Tire Fees:	\$28.00

Sub Total:	\$9,488.25
Tax Total:	\$474.41
Grand Total:	\$9,962.66
Balance Due:	\$9,962.66



SIGNATURE.....

Date.....

