

SENT

Please submit to: 9410 – 20th Avenue Edmonton, AB T6N 0A4 Tel (780) 437-9100 Fax (780) 437-7787

nent safety authority (02048714 & (02048715 & (02019424) A

BOILER AND PRESSURE VESSEL STATUS REPORT

NOTE: This form may be used to provide notification of changes in ownership, location, operating status or scrapped boilers and pressure vessels.

Please review the responsibilities of the vendor and the new owner under Section 36 of the Pressure Equipment Safety Regulation (regulation can be found on our website www.absa.ca)

Safety Regula	ation. (regulation can be found of	n our website www.absa.ca)		
Re: Vessel (A)	1) 2988254 2	2988260 3)	3010079	
Serial No.	944411.3	944411.4	LS-4255	
CRN	X27(do. Z	X27(do.Z	K1579.2	
Vessel(s) sold	d or purchased. Please transfer ew Owner:	the registration of the vesse	l(s) to:	
	ocation of	(Street Address or L	CD	
Conto	-t Damas	Tel:		
Conta	ct Person: E-Mail:		161.	
Dat	te of Sale:		PO No.:	
Vessel(s) rem	oved from service on:			
	responsible for ensuring the ves	sel is inspected by ABSA pri	or to it being returned to service in	
The above ves	ssel(s) returned to service on:			
Inspected on	:	(Date).	Inspection Report attached	
Vessel(s) relo	cated to:			
	(Street Address or LSD) We own but do not know the location of this vessel. (ABSA records will record the location as unknown, and			
the applicable	annual fee(s) will remain in force	to your account. Responsib	record the location as unknown, and illity for safe operation in Alberta you are required to notify ABSA.	
			ain your company name as the ompany until new ownership details	
	rating outside of the Province	of Alberta since	(Date), Please	
remove from annual registration. You are required to notify ABSA if the vessel returns to service in Alberta.				
Vessel Scrappe	ed - All three conditions I	pelow must be satisfie	d	
Vessel has been removed from service and there is no intention to return it to pressure service.				
☐ The nameplate	has been removed and all other	identification has been remo	ved.	
	a condition that it cannot be presor a head has been cut off.	ssurized, i.e. A hole has bee	n cut in the vessel, or a nozzle has	
Company Name	Husty Energ	C		
	Data Admin		Tel: 300-825-1143	
(Please print name)	Amy Scaddon	E mail:	Scaddan@huskyenergy.com	
Signature:	18 W	Date:		
\sim) andown	7017 1	3 05	