

Date: June 6, 2012 Equipment ID: 62048715

Report #: IR120606SHAb Bar Code #: N/S

Facility: Sask – Tangleflags Field

-	sk-Tangleflag		•	-18-051-25W		Sys					
Asset # N/S		Equi	pment ID	62048715			et Type	Exchang			
Description	Cooler			Prov. Ins		9882		Serial #	9444		
Manufacturer	Air-X-Cha			CRN	K2766.2			Year Built	1994		
MAWP 45		KPag	9	@ 149	@ 149 °C		MD		-29		°С
Code AS	SME VIII	Fluid	Service	Gas		Sweet F		PWHT	No		
Internal Acces	s No	Insul	ated No					Internal Coating		No	
Operating Pre	ssure 1	N/S		KPag		Ope	rating Temp	np N/S			٥С
				PSV E	DATA						
PSV ID #	Location	Si	ize	Set	Capacit	у	Manufacture	er Mo	del	La	ast
		Inlet	Outlet	Pressure	SCFM / Lbs/Hr / G	PM					rvice
457980-6-KE	Inlet Piping	38.1mm	63.5mm	1586 kPa	2468 SCF	М	Farris	27GA-4	6-M20	29-S 10	Sept-
			1	NSPECTION	SUMMARY	Y					
0.511		**************************************									
	oes not have a ' d condition.	"3" for Saskato	chewan.								
	- NB# 24491. M. Lafontaine, 2013-04-01: - all measured thicknesses were greater than the minimum required thickness										
							-	e minimum re	equired th	icknes	S
				stated on the i			ia report vith manufactu	rer Confirma	tion in ea	uinmei	nt file
				in HDMS.	ii Citiv commi	iiica v	vitii iiiaiiaiaeta	irer. commina	tion in eq	шрпісі	TC THC
				RECOMME	<u>NDATIONS</u>						
- Verify	CRN to ensure t	he vessel can	be used in Sa	askatchewan.							
		NO	NCONFORM	IANCES / IN	SPECTION	DEF	ICIENCIES				
- None											
				NSPECTION	PLANNING	3					
Inspection Strat	_		Availability				Inspection I		5 ye	ars	
Inspection Date			Date of Last	Inspect			Date of Nex	t Inspect	201	7-06	
				REPORT CER	RTIFICATION	,					
The signatures							with the ident	ified inspecti	on strate	gy and	that
the specified eq	uipment is con	isiaerea tit to	Scott Abbot		iext inspection	on. ≁	4	Date	. Jui	ne 6, 20	012
' '					20 N						
Reviewed and A	,							Date			
Criticality Asses	ssment Rerun	•			Inspect	ion P	lanning Rerun	<del></del>			
Assessed Next	Inspection Date	е									



Date: June 6, 2012 Equipment ID: 62048715

Report #: IR120606SHAb Bar Code #: N/S

Facility: Sask – Tangleflags Field

# DETAILED INSPECTION VISUAL EXTERNAL

ID	Description	Condition	Location	NCR	Comments
V1	General Other (Please Explain)	N/A			
V2	General Corrosion	No			
V3	General Leaks	No			
V4	Vibration	Minor			
V5	Dissimilar Flange Rating	No			
V6	Ladder/Stairway	N/A			
V7	Heads	Good			
V9	Electrical Ground	Yes			Skid is grounded.
V10	Painted Inactive Corrosion	N/A			
V11	Coating/Painting	Good			
V12	Expansion Joint or Bellows	N/A			
V13	Gauge/Site Glass	N/A			
V14	Shell	Good			
V15	Jacket	N/A			
V21	Support Other (Please explain)	N/A			
V22	Foundation	Skid			
V23	Anchor Bolts	Good			
V24	Saddle/Skirt	Good			
V25	Davit	N/A			
V26	Fireproofing	N/A			
V31	Connections Other (Please	N/A			
	explain)				
V32	Small Branches	N/A			
V33	Nozzles	Good			
V34	Manways	No			
V35	Reinforcing Pads	No			
V36	Inadequate Thread Engagement	No			
V37	Bolting	Good			
V38	Flanges	Good			
V39	Leak Clamps	N/A			
V41	Insulation Other (Please explain)	N/A			
V42	Damage	N/A			
V43	Penetrations	N/A			
V44	Insulation Jacket	N/A			
V45	Banding	N/A			
V46	Seals/Joints	N/A			
V51	Relief Devices Other (Please	Good			
	explain)				
V52	Corrosion	No			
V53	Leaks	No			
V54	Restricted Inlet/Outlet	No			
V55	Manual Operation Lever	No			



Date: June 6, 2012 Equipment ID: 62048715

Report #: IR120606SHAb Bar Code #: N/S

Facility: Sask – Tangleflags Field

# DETAILED INSPECTION VISUAL INTERNAL

ID	Description	Condition	Location	NCR	Comments
V1	General Other (Please Explain)	N/A			
V2	Corrosion (depth, length, width)	N/A			
V3	Erosion	N/A			
V4	Distortion	N/A			
V5	Blisters	N/A			
V6	Deposits	N/A			
V7	Heads	N/A			
V8	Welds	N/A			
V9	Nozzles	N/A			
V10	Shell	N/A			
V11	Gasket Surfaces	N/A			
V21	Internals Other (Please explain)	N/A			
V22	Demister	N/A			
V23	Baffle/Wier	N/A			
V24	Sparger	N/A			
V25	Thermowells	N/A			
V26	Metallic Linings	N/A			
V27	Nonmetallic Linings	N/A			
V30	Other Welded Attachments	N/A			
V31	Tubes	N/A			
V32	Tube sheet	N/A			

# DETAILED INSPECTION OTHER TECHNIQUES

ID	Location	Observation/Measurement	Acceptance Criteria	NCR	Comments
1	N/A				
2	N/A				
3	N/A				
4	N/A				
5	N/A				
6	N/A				
7	N/A				
8	N/A				
9	N/A				
10	N/A				

# DETAILED INSPECTION TUBE INSPECTION

Tube #	Flaw Type	Flaw Length	Location on Tube	Wall Loss	NCR	Comments
N/A						
N/A						
N/A						
N/A						
N/A						
N/A						
N/A						
N/A						
N/A						
N/A						



Date: June 6, 2012 Equipment ID: 62048715

Report #: IR120606SHAb Bar Code #: N/S

Facility: Sask - Tangleflags Field

# DETAILED INSPECTION UT THICKNESS

CML	Nom. Thk	Current Reading	Short Term Corr Rate	Long Term Corr Rate	Remaining Life	Comments
						See Attached UT Report.

#### **PHOTOS**






Date: June 6, 2012 Equipment ID: 62048715
Report #: IR120606SHAb Bar Code #: N/S
Facility: Sask – Tangleflags Field









P.E. No.: 62048715 PARA: N/S SASK. (S) N/S B.C.: N/S C. Stamp: U Yr. Blt.: \_\_\_\_1994 Serial No.: 944411.4 P.R.N. (A) \_\_2988254 Manway: \_\_\_NO C.R.N.: K-2766.2 Manufacturer: \_\_AIR-X-CHANGERS CLIENT HUSKY ENERGY **FACILITY** SASK - TANGLEFLAGS FIELD LSD 04-18-051-25W3M

COOLER

DATE: 2012/05

DWG.#: 003

ITEM

BY: S.H.A.

\_\_\_ Code/Div.: ASME VIII DIV.1 Size: 8" X 6" X 31" Radiography: N/S Service: SWEET Insulated: NO PWHT: NO \_\_\_\_\_ N.B. No.: 24491

# Design & Materials Data

HEAD: Material: N/S Nom.: N/S C.A.: N/S Material: \_\_\_\_\_ Nom.: \_\_\_\_ C.A.: \_\_\_\_ SHELL Material:  $\frac{N}{S}$  Nom.:  $\frac{N}{S}$  C.A.:  $\frac{N}{S}$ Material: \_\_\_\_\_ Nom.: \_\_\_\_ C.A.: \_\_\_\_ Head Mat'l.: \_\_\_\_\_ Nom.: \_\_\_\_ C.A.:\_ Shell Mat'l.: \_\_\_\_\_ Nom.: \_\_\_\_ C.A.:\_\_ CHANNEL \_\_\_\_\_ Nom: \_\_\_\_ Material: \_ MAWP Shell Side: 655 PSI @ Temp.: 300°F/-20°F MAWP Tube Side: \_\_\_\_\_\_ @ Temp.:\_\_\_\_ Comments: \_\_\_



**Husky Energy** Unit: T-064

FACILITY: MANUFACTURER: AIR X-CHANGERS TANGLEFLAGS FIELD LSD: 04-18-051-25W3 DESIGN PRESSURE: 4516 kPa / 655 psi ITEM DESC .: **COOLER** DESIGN TEMP.: 149 C 300 F

EOUIP / OIP#: 62048715

PROV. REG. #: A2988254 VESSEL CORROSION ALLOWANCE:

SERIAL #: 944411.4

CRN.: TOTAL CAUTION / ACTION TML: K-2766.2 1

### Item # 003

5.01

Pts.

0.00

Nom.

TML No.: 5 W COOLER T-B

AVERAGE THICKNESS MEASURED: **DATE BUILT: 01/1994** 16.63 mm. MINIMUM THICKNESS MEASURED: MATERIAL: 16.63 mm. Pts. Nom. CA +Nom. B/L Prev. Last Short Long Rem Future UT Action/Caution Thick. Steel -CA Survey Survey Survey Term Term Half Reading Thick. Mfg.Tol. -Toll. Required Item Thick. Thick. CR CR Life mm-yyyy mm. mm. mm. mm. mm/yr mm. mm. mm/yr mm. yr 06/2012

0.0000

Short

0.0000

Long

N/A

Rem.

Future UT

NO

16.63

Last

E COOLER T-B **TML No.: 10** 

0.00

CA +

0.00

Nom.

N/A

B/L

DATE BUILT: 01/1994 AVERAGE THICKNESS MEASURED: 17.00 mm. MATERIAL: MINIMUM THICKNESS MEASURED: 17.00 mm.

Prev.

N/A

	Thick. mm.	Steel Mfg.Tol. mm.	-CA -Toll. mm.	Survey Thick. mm.	Survey Thick. mm.	Survey Thick. mm.	Term CR mm/yr	Term CR mm/yr	Half Life yr	Reading mm-yyyy mm.	Action/Caution Required Item	
						06/2012						
10.01	0.00	0.00	0.00	N/A	N/A	17.00	0.0000	0.0000	N/A		NO	

#### **TML No.: 15** 4" CIRC 300# NOZ

**DATE BUILT: 01/1994** AVERAGE THICKNESS MEASURED: 8.58 mm. MATERIAL: MINIMUM THICKNESS MEASURED: 8.58 mm.

Pts.	Nom. Thick. mm.	CA + Steel Mfg.Tol. mm.	Nom. -CA -Toll. mm.	B/L Survey Thick. mm. 01/1994	Prev. Survey Thick. mm.	Last Survey Thick. mm. 06/2012	Short Term CR mm/yr	Long Term CR mm/yr	Rem. Half Life yr	Future UT Reading mm-yyyy mm.	Action/Caution Required Item
15.01	8.56	0.00	8.56	8.56	N/A	8.58	0.0000	0.0000	3.34		CAUTION *

If Baseline (B/L) Survey Thickness Measurement was not taken at the time of Manufacture, then Nominal Thickness is used as Baseline Thickness. Minimum Thickness is calculated

Design Minimum Thickness = Nom. Thick. - CA - Manufacturing Steel Tolerance.

Manufacturing Tolerance of pipe and forged fittings is + or -12.5% (May or may not apply dependent upon the Client's Owner-User Integrity Management System).

Manufacturing Tolerance of plate is + or - 0.25mm (0.010") (May or may not apply dependent upon the Client's Owner-User Integrity Management System).

<sup>(\*)</sup> and GREEN Represent 25% of the last thickness readings, which have the shortest remaining half life.



Husky Energy
Unit: T-064

FACILITY: TANGLEFLAGS FIELD MANUFACTURER: AIR X-CHANGERS
LSD: 04-18-051-25W3 DESIGN PRESSURE: 4516 kPa / 655 psi
ITEM DESC.: COOLER DESIGN TEMP.: 149 C / 300 F

EQUIP / OIP#: 62048715

PROV. REG. #: A2988254 VESSEL CORROSION ALLOWANCE:

SERIAL #: 944411.4

CRN.: K-2766.2 TOTAL CAUTION / ACTION TML: 1

#### Item # 003

TML No.: 20 4"CIRC 300# NOZ

DATE BUILT: 01/1994 AVERAGE THICKNESS MEASURED: 8.86 mm. MATERIAL: MINIMUM THICKNESS MEASURED: 8.86 mm.

Rem. Pts. Nom. CA +Nom. B/L Prev. Last Short Long Future UT Action/Caution Thick. Steel -CA Survey Survey Survey Term Term Half Reading Mfg.Tol. -Toll. Thick. Thick. Thick. Required Item CR CR Life mm-yyyy mm. mm. mm. mm/yr mm. mm. mm. mm. mm/yr yr 01/1994 06/2012 20.01 8.56 0.00 8.56 8.56 N/A 8.86 0.0000 0.0000 50.00 NO

TML No.: 25 4"CIRC 300# NOZ

DATE BUILT: 01/1994 AVERAGE THICKNESS MEASURED: 8.73 mm.
MATERIAL: MINIMUM THICKNESS MEASURED: 8.73 mm.

Pts.	Nom.	CA +	Nom.	B/L	Prev.	Last	Short	Long	Rem.	Future UT	
	Thick.	Steel	-CA	Survey	Survey	Survey	Term	Term	Half	Reading	Action/Caution
	mm.	Mfg.Tol.	-Toll.	Thick.	Thick.	Thick.	CR	CR	Life	mm-yyyy	Required Item
		mm.	mm.	mm.	mm.	mm.	mm/yr	mm/yr	yr	mm.	
				01/1994		06/2012					
25.01	8.56	0.00	8.56	8.56	N/A	8.73	0.0000	0.0000	28.34		NO

If Baseline (B/L) Survey Thickness Measurement was not taken at the time of Manufacture, then Nominal Thickness is used as Baseline Thickness. Minimum Thickness is calculated

Design Minimum Thickness = Nom. Thick. - CA - Manufacturing Steel Tolerance.

Manufacturing Tolerance of pipe and forged fittings is + or -12.5% (May or may not apply dependent upon the Client's Owner-User Integrity Management System).

Manufacturing Tolerance of plate is + or - 0.25mm (0.010") (May or may not apply dependent upon the Client's Owner-User Integrity Management System).

(\*) and GREEN Represent 25% of the last thickness readings, which have the shortest remaining half life.

BLUE (Caution TML Point) - if Corrosion Rate exceed a 0.250mm / 0.009 in. per yr. or Half Life is less than 15 years.

RED (Action TML Point) - If Remaining Half Life is 0 and Last Survey Thickness is below Nominal-CA-Tolerance Thickness.

CA - Corrosion Allowance, CR - Corrosion Rate (Brown if CR >= 0.500mm or 0.019in/yr.).



ULTRASONI	C EXAMINA	REPORT No.: UT - 1723-C - 00								
							Page:	1	of	1
Client:	Husky Energy					ITS Job No.:	1723-C			
District:	Saskatchewan			LSD: Various		Date:	June 6, 2012			
Facility:	Tangleflags Field					Time:	13:00			
Item(s) Examined:	Corrosion Surveys	(as per client requ	uest) Indica	ted Through Job Shee	t.	W.O. No.:	N/S			
						P.O. No.:	N/S			
Acceptance Criteria:	For Clients Review			Rev. / Date: N/A		Cost Code:	Various			
Procedure No.:	UT-02			Rev. / Date: Rev. 1,	Oct 2011	AFE:	N/S			
Technique No.:	02			Rev. / Date: Rev. 1,	Oct 2011	Other:	N/S			
Equipment Data:						•	<u>'</u>			
PRN: (A)	N/S Se	rial No.:	N/S	N/S	CRN:		N/S			
Material:	N/S		Thicknes	ss: N/S		Other:	N/S	3		
Surface Condition:			_							
■ Base Metal □	Machined   Sho	t Blasted	ire Wheeled	☐ As Ground ☐	As Welded	Painted Co	ated Other:			
☐ < 0°C (32°F)	· · · · · · · · · · · · · · · · · · ·	(32°F) to 54°C (130		■ 55°C (131°F			☐ > 100°C	(212°F	)	
Ultrasonic Equipment		(02 17 (0 0 1 0 (100	, , ,	- 00 0 (1011	7.0 100 0 (2121	,				
Instrument:	Olympus	Model:	LTC	Serial No.:	100182	403 Ca	I. Due Date:	23	-Feb-1	3
Cal. Block:		Wedge 2.5mm to 12		Serial No.:	2476		uplant:		UTX	
Cal. Block:		N/A		Serial No.:	N/A		-			
Transducer Cable(s)	); Type:	Lemo to I	Micro	Length:	6'					
Transducer:										
Δr	ngle Frequency	Size 7	Гуре	Primary Reference	Scanning Ser	nsitivity Tr	ansfer Value		Range	6
Serial No.	(°): (MHz):	3	Dual	(db) (%FSH):	(db):	ionivity	(db):		(mm)	
	0 5	6.35		58db 80% FSH	>6db. Maintain	80%FSH	N/A		50.8	,
735560	0 5	9.53		64db 80% FSH	>6db. Maintain	80%FSH	N/A		50.8	
Examination Details:										
SCOPE:	To perform ultrason	ic corrosion survey	on various e	quipment in the Saskato	hewan area for h	Husky Energy loo	oking for wall lo	SS.		
RESULTS:	Ultrasonic thickness	readings taken on	vessels and	piping attached to the v	essels.					
CONCLUSION:	Thickness readings	provided for clients	review							
	g-									
Client Representativ	e:			Sign:			Date:			
Technician(s):										
Sign:	W 95					7				
Print:	Scott Abbott	elaire	Repor	rt Review:	Initial	2				
	1 <sup>st</sup> Technician CGSB	SNT ACCP/ASNT		2 <sup>nd</sup> Technician / CGSB		P/ASNT		ii iiuaje		
Le Certification I			Cer	Level: rtification No.:						
Soons of Sanicar										

a connection of appendix positive figure (as a first positive figure (as a first position of a popular contract provided for in writing and the preparation of reports or similar documents reflecting the inspection data obtained or the opinion formulated on the basis of such contract positive for in writing and the preparation of reports or similar documents reflecting the inspection data obtained or the opinion formulated on the basis of such contract positive for the entire your device of the contract positive for in writing and descriptions, comments and expressions of a good positive for the owner/operator, and the owner/operator retains complete responsibility for the engineering, repet and disconce as a result of the respection data or other internation provided by (3). In or over that first positive for the engineering, repet and disconce as a result of the respection data or other internation provided by (3). In or over that first positive for the engineering, repet and disconce as a result of the engineering or the