

62048715

Technical  
Safety Authority  
of Saskatchewan

Boiler and Pressure Vessel  
Safety Unit  
2202 2nd Avenue  
REGINA SK S4R 1K3

Report Number: 234462  
Previous Inspector:  
Licence Number: 29511 - (Acceptance Pending)  
Serial - Unit Number: 944411.4 - *113056*  
Plant: 0 (pieces)

Equipment:

Bld/Oilfield: Tangleflags North  
Address: 04-18-51-25W3M  
City/Town: Turtleford  
LLD: 04-18-51-25W3M  
Community: Turtleford  
District: 5

Owned By:

Husky Energy - Lloyd (2) (306) 825 - 1234 (Phone)  
c/o Ray Trachuk (780) 205 - 2092 (Cell)  
4335-44th Street  
Lloydminster (Sask), Saskatchewan  
S9V 0Z8  
Canada

Item Type: 05 - Heat Exchanger (Provincial)

Inspector Description:

Owner Description: *Two Stage Discharge Cooler*

CRN: K2766.2.3

Mobility: Stationary

NB: *24491*

Shell WP: 4516

Manufacturer: Air-X-Changers

Tube WP:

Manufactured Date: 1994-01-01

Diameter (m): 0.2

Last Internal Insp.:

Length (m): 0.8

Inspection Method: Acceptance

Next Inspection Date: *2018.12.10* (yyyy-mm-dd)

Install Permit No.: 24141

Assigned to Inspector: 0445 - Larry Holuk

Previous Conditions:

Inspection Conditions: A - Acceptable R - Repairs or Corrective Action Required N - Not Applicable  
C - Comments or Recommendations I - Incomplete/Object Not Exposed/Not Operating

|                                    |  |                         |
|------------------------------------|--|-------------------------|
| 1. Safety Valve: <i>A</i>          | 7. Inspection Openings: <i>N</i>       | 13. Nameplate: <i>N</i> |
| 2. Level Gauge: <i>N</i>           | 8. Associated Piping: <i>A</i>         | 14. Other: <i>N</i>     |
| 3. Pressure / Temp Gauge: <i>N</i> | 9. Shell: <i>A</i>                     |                         |
| 4. Tubesheet: <i>A</i>             | 10. Heads: <i>A</i>                    |                         |
| 5. Tubes: <i>A</i>                 | 11. Data Report: <i>A</i>              |                         |
| 6. Insulation: <i>N</i>            | 12. Sask Design Registration: <i>A</i> |                         |

Comments/Repairs or Corrective Action Required:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Unable to do inspection on: \_\_\_\_\_ (yyyy-mm-dd)

Reason inspection was not done: \_\_\_\_\_

Items Classified with an "R" must be repaired or corrected by : \_\_\_\_\_ (yyyy-mm-dd)

and the Boiler and Pressure Vessel Safety Unit must be notified in writing by fax or mail.

Please include the Licence No. and the Serial Number on all correspondence.

(306) 787-1443 Phone/1-866-530-8599 (Phone - Toll free in SK)

(306) 787-9273 Fax/1-866-760-9255 (Fax - Toll free in SK)

Holuk, Larry  
952, 122 3rd Avenue North  
SASKATOON Saskatchewan S7K 2H6  
(306) 933 - 5073 (Work)  
(306) 220 - 3195 (Cell)  
Larry.Holuk@tsask.ca (Email)

☐ This report was discussed with the owner or his representative.

☒ A copy of this report was mailed to the owner/representative by regular mail on: \_\_\_\_\_ (yyyy-mm-dd)

Signature of Person receiving report

*2018.12.10*  
Inspection Date (yyyy-mm-dd)

*[Signature]*  
Signature of Inspector

*0445*  
Inspector Number

CLIENT