PETROCUMAN Oil and Gas

WESTERN CANADA UPSTREAM INSPECTION PROCEDURES FOR OIP

Oil and Gas	
PROCEDURE NO.	SUBJECT
IP-320	FIRED EQUIPMENT

50-1406-H-101 750 FL 406 14.06 Weilsite Heder

CHECKLIST #1 - EXTERNAL INSPECTION

1.	Ladders, stairways, platforms and walkways	L
2.	Foundations and supports	
3.	Nozzles	3
4.	Grounding connections	
5.	Protective coatings and insulation	9
5 .	External metal surfaces	4
7.	Pressure relief devices	
3.	Name plate	F
9.	Ultrasonic thickness survey	□ MA Willed to
10.	Inspection report completed	□ MA
11.	Nonconformance report completed	MA


APPROVAL
CHIEF INSPECTOR MAY, 1999

APPROVAL
CHIEF INSPECTOR MAY, 1999

APPROVAL
TO BE REVISION


50-1406 AUGUST 2003

H-101



50-1406 AUGUST 2003

4-101



50-1406 AUGUST 2003

H-101

