300002746



MAGNETIC PARTICLE INSPECTION REPORT

SB382-MT-132 Page 1 of 1

Procedure: 5.0 Technique: MT-2V	Client: IRISNDT	HUSKY OPERATIONS #: 176871	Date: 15-Sep-14 WO #: 50006293
Code: API 650 - Sect 8.2.4		: 102/ 14-10-51-1 W4M,AB	PO #: 8400860277
Other:	Item Insp		61995-09
Surface Condition: Painted Sandblas	sted 🛛 Machined 🔲	As Cast	eldment 🛛 Other 🖂
Material: P1		Thickness: N/A	Heat Treatment: N/A
Magnetizing Equipment: Yoke ⊠ Coil □	Permanent IRISND	Γ#: 40097 Mfg: CONTOUR	Calibration Date: 26-Jul-14
Method of Magnetization: AC ⊠ DC □	Continuous 🛛		
Blacklight: Y ☐ N/A ☒ IRISNDT #: Verification per AS	SME V Art 7 T.777.2	3	RISNDT #: alibration Date:
Whitelight: Y ⊠ N/A □ Verification per AS	SME V Art 7 T.777.1		
Magnetic Particles: Dry ☐ Wet ⊠	Red [scent [
Batch #: 1331-4			7C
Background: ⊠ Batch #: 1343	Mfg:	ARDROX Type:	8901W
REQ: DEREK HOSKINS APP:GEORGE GREENING 2Z-2020571			
Inspection Limitation(s):			
Unit#: 767 Kilometers: N/C	Consumables:	Interpretation by: STEPHEN BRYAN	SNT-TC-1A: 2
In: 1700 Out: 1900 Hrs: 2.0	IAIIIA	(Print)	C.G.S.B.: 2
In: Out: Hrs:		41	(Level)
		Signature	C.G.S.B.# 12459
Personnel: STEPHEN BRYAN / BRANDEN FOWLOW		Cont Representative:	
		l am in full	
		agreement with report contents	
2		(Sign)	
E244 98 Stock Edmonton Alberto TSE 5T8 Phone: (780) 433	7.2022 fav: (780) 436-4873		

Fort McMurray Red Deer

(780) 826-6105 (780) 743-1536 (403) 347-1742 www.irisndt.com

Engineering, Calgary Engineering, Edmonton Rope Access Services Offices also located in USA and UK

(403) 217-9684 (780) 437-2022 (780) 437-2022